



# Road & Bridge FY 2017 Annual Road Report


COUNTY OF: HENDERSON

§  
§  
§

PRECINCT NUMBER: 4

1. Condition of each road, culvert, and bridge in the precinct and the primary cause of any road, culvert or bridge degradation: Precinct 4 contains 242.275 miles of County Maintained Roads (as reported in the Biennial TXDOT Report, submitted 5/2/16). Precinct 4 assists in the maintenance of 29.51 miles of City Roads (Berryville, Coffee City & Poynor) under an Inter-Local Agreement. Precinct 4 maintains two (2) Bridges on CR 4614 and CR 4628, which are both in "Good" condition as reported by TXDOT. The Precinct roads are on average in "Good" condition, which is improved from FY 2016. The Road Rating Report is attached.
2. Amount of money necessary for maintenance of the precinct roads during the next fiscal year (2018): \$1,306,643, Note: This amount is based on the cost estimates for Road & Bridge Material, Equipment, Equipment maintenance, Fuel and Employee Wages, but does not include the cost of employee benefits or administrative costs.
3. Number of traffic control devices in the precinct defaced or torn down: 18  
However, it should be explained that this is total signage work performed during the 2017 Fiscal year. This includes the sign upgrade program to bring Precinct 4 signage in compliance with the 2011 TMUTCD and is still at 95% completed. In addition to the normal upgrade activity, Precinct 4 started deploying the Blue & Yellow County Road Number signs and should complete by the end of FY 2018
4. Any new road that should be opened in the precinct: None
5. Any bridges, culverts, or other improvements necessary to place the precinct roads in good condition, and the probable cost of the improvements: During FY 2017 Precinct 4 continued to upgrade the water crossings throughout the Precinct. The amount upgraded and or replaced during this fiscal year totaled 757 feet.


Submitted by the undersigned on this 15<sup>th</sup> day of May, 2018.

  
\_\_\_\_\_, Commissioner, Precinct 4  
**Ken Geeslin**

Subscribed and sworn to, before me, the undersigned authority, this 15<sup>th</sup> day of May 2018

Notary Public: 

My commission expires:



[File in minutes and submit to grand jury with a copy of any road work contracts for past year during ninth month of county fiscal year – Section 251.005, Transportation Code]

Item 1 has been revised to include the primary cause of any road, culvert or bridge degradation (likely overweight oil & gas truck traffic) as required by S.B. 1747



**Road & Bridge  
Annual Road Report**

**FY - 2017**

**PRECINCT 4**

**ROAD CONDITION LIST**



## County Roads

Type: All

Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
0 OFF						
1 Bad Weather						
2 Multi Locations						
155 Panarama Dr. E (Brierwood Bay)	Asphalt / Seal Coat	0.211	20	40		4 (Good)
155 Autumn Trail (Brierwood Bay)	Asphalt / Seal Coat	0.588	20	40		3 (Fair)
155 Brierwood Dr (Brierwood Bay)	Asphalt / Seal Coat	1.411	20	40		3 (Fair)
155 Carol Way (Brierwood Bay)	Oil Sand	0.300	20	40		3 (Fair)
155 Coral Dr. (Brierwood Bay)	Oil Sand	0.300				3 (Fair)
155 Cutter Dr (Brierwood Bay)	Asphalt / Seal Coat	0.310	20	40		3 (Fair)
155 Driftwood (Brierwood Bay)	Asphalt / Seal Coat	0.123	20	40		3 (Fair)
155 Forest Hill Dr. EW (Brierwood Bay)	Asphalt / Seal Coat	0.250	18	40		3 (Fair)
155 Forest Hill Dr. NS ( Brierwood Bay )	Asphalt / Seal Coat	0.200	20	40		3 (Fair)
155 High Point Dr. (Brierwood Bay)	Asphalt	0.140	18	40		5 (Excellent)
155 Holley Hills (Brierwood Bay)	Asphalt / Seal Coat	0.150	20			3 (Fair)
155 Judy Ln. (Brierwood Bay)	Oil Sand	0.282				3 (Fair)
155 Lindy Ln (Brierwood Bay)	Oil Sand	0.300				3 (Fair)
155 Panarama Dr. (Brierwood Bay)	Asphalt / Seal Coat	0.166	20	40		4 (Good)
155 Phillip Pl (Brierwood Bay)	Oil Sand	0.300	20	40		3 (Fair)
155 Shadybrook Dr. (Brierwood Bay)	Oil Sand	0.160				3 (Fair)
155 Tanglewood Dr. (brierwood Bay)	Oil Sand	0.460				3 (Fair)
155 Valleyview Dr (Brierwood Bay)	Asphalt / Seal Coat	1.941	20	40		3 (Fair)
155A Diamond Head Bay Rd.	Road Oil / Seal Coat	0.278	18	50		4 (Good)
315 Creekside St. (Parkside)	Asphalt	0.342	18	50		4 (Good)
315 Hickory St. (Parkside)	Oil Sand	0.235	18	50		4 (Good)
315 Parkside St. (Parkside)	Asphalt	0.520	18	50		4 (Good)
315 Poolside Dr. (Parkside)	Asphalt	0.153	18	50		4 (Good)
CR 4023 IMPALA SOUTH #2	Road Oil / Seal Coat	0.300	20	50		4 (Good)
CR 4100 HENDERSON (ext 4117)	Oil Sand	0.760	16	40		4 (Good)
CR 41000 BRENTWOOD DR. (Oak Manor) {Minor Collector}	Asphalt	0.876	16	50		4 (Good)
CR 41001 BRENTWOOD CIRCLE (Oak Manor)	Asphalt	0.327	16	40		4 (Good)
CR 41002 RANCH ROAD (Oak Manor)	Asphalt / Seal Coat	0.594	16	50		4 (Good)

## County Roads

Type: All  
Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 41003 LINDEN LN (Oak Manor)	Road Oil / Seal Coat	0.057	16	40		4 (Good)
CR 4101 PERRY (ext 4117)	Road Oil / Seal Coat	0.432	16	40		4 (Good)
CR 4102 BUD JONES (ext 4117)	Oil Sand	0.200	16	40		4 (Good)
CR 4103 (ext 4102)	Iron Ore	0.092	16	40		4 (Good)
CR 4104 ATWOOD-A (Off 155)	Road Oil / Seal Coat	0.261	16	40		4 (Good)
CR 41100 WAGONTREE TRAIL {Minor Collector}	Road Oil / Seal Coat	0.666	16	40		4 (Good)
CR 41101 BROKENSPOKE (Wagontree)	Road Oil / Seal Coat	0.256	16	40		3 (Fair)
CR 41102 SINGLETREE (Wagontree)	Road Oil / Seal Coat	0.593	16	40		3 (Fair)
CR 41103 SETTLERS LOOP (Wagontree)	Road Oil / Seal Coat	0.436	16	40		3 (Fair)
CR 41104 BUGGYHUB (Wagontree)	Road Oil / Seal Coat	0.998	16	40		3 (Fair)
CR 41105 LAND GRANT (Wagontree) {Minor Collector}	Road Oil / Seal Coat	1.183	16	40		3 (Fair)
CR 41106 DOUBLETREE (Wagontree)	Road Oil / Seal Coat	0.146	16	40		3 (Fair)
CR 41107 MILL RUN RD (35 MPH)	Road Oil / Seal Coat	3.500	20	50		4 (Good)
CR 41107A LAKE ESTATES DR.	Asphalt	0.387	18	50		4 (Good)
CR 4112 Bacon Bacon	Road Oil / Seal Coat	0.190	14	30		5 (Excellent)
CR 41126 LABELLO	Road Oil / Seal Coat	0.583	16	40		4 (Good)
CR 4117 B. VILLE {Minor Collector*}	Road Oil / Seal Coat	0.463	20	50		4 (Good)
	Road Oil / Seal Coat	4.207	20	50		4 (Good)
CR 4117A KIETH LN (ext 4117)	Oil Sand	0.235	16	40		5 (Excellent)
CR 4117B KEVIN CIRCLE (ext 4117)	Road Oil / Seal Coat	0.320	16	40		5 (Excellent)
CR 4120 ATWOOD-B (Off 155)	Dirt	0.546	16	40		3 (Fair)
CR 41200 DOGWOOD TRAIL	Road Oil / Seal Coat	0.774	18	50		5 (Excellent)
CR 41201 OAKTREE Dr. (Dogwood)	Asphalt	0.380	18	50		4 (Good)
CR 41511 (Larry Anding)	Road Oil / Seal Coat	0.923	18	50		3 (Fair)
CR 41511E CR 41511E	Road Oil / Seal Coat	0.208	16	40		3 (Fair)
CR 41512 RYAN	Road Oil / Seal Coat	0.641	16	50		3 (Fair)
CR 41513	Road Oil / Seal Coat	0.741	16	50		4 (Good)
CR 41514	Road Oil / Seal Coat	1.456	16	50		4 (Good)
CR 41515 McGEE NURSEY	Road Oil / Seal Coat	0.176	16	40		3 (Fair)
CR 41516 DOUGLAS DRIVE	Road Oil / Seal Coat	0.430	16	40		4 (Good)
CR 41518 (EXT. Douglas)	Asphalt	0.120	18	50		3 (Fair)

## County Roads

Type: All

Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4200 (Road Closed)	Road Oil / Seal Coat	0.300	18	50		3 (Fair)
CR 4201 SUNRISE (off 315) {Minor Collector}	Road Oil / Seal Coat	0.952	16	40		3 (Fair)
CR 4201A CHEROKEE Dr. (Cherokee)	Road Oil / Seal Coat	0.581	16	40		3 (Fair)
CR 4201B Sunbird Dr. (Cherokee)	Road Oil / Seal Coat	0.576	18	50		3 (Fair)
CR 4201C Tomahawk Dr. (Cherokee)	Road Oil / Seal Coat	0.316	18	50		3 (Fair)
CR 4201D Arrowhead Dr. (Cherokee)	Road Oil / Seal Coat	0.070	18	50		3 (Fair)
CR 4201E Ridge Rd. (Woodridge)	Road Oil / Seal Coat	0.186	18	40		3 (Fair)
CR 4201F Quil Cutoff (Woodridge)	Road Oil / Seal Coat	0.146	18	40		3 (Fair)
CR 4201G Hillcrest (Woodridge)	Road Oil / Seal Coat	0.168	18	40		4 (Good)
CR 4201H Pineview (Woodridge)	Road Oil / Seal Coat	0.213	18	40		4 (Good)
CR 4202 CAPE (off FM 3506)	Road Oil / Seal Coat	1.670	18	50		4 (Good)
CR 4213 TWIN OAKS (off FM 315)	Asphalt	0.296	16	40		3 (Fair)
CR 4213A Post Oak (Twin Oaks)	Asphalt	0.184	18	40		5 (Excellent)
CR 4213B PINE Dr. (Twin Oaks)	Oil Sand	0.330	16	40		3 (Fair)
CR 4213C Red Oak Dr. (Twin Oaks)	Oil Sand	0.090	18	40		4 (Good)
CR 4215 WELDER (ext 4224)	Iron Ore	0.456	16	40		3 (Fair)
CR 4216 Old Caney Rd (ext. off old 4200)	Asphalt	0.250	16	40		4 (Good)
CR 4217 MANOY (Pleasant Ridge)	Asphalt / Seal Coat	0.710	18	40		3 (Fair)
	Asphalt / Seal Coat	3.590	18	40		3 (Fair)
CR 4221 PINE SPRINGS (ext off 4222)	Road Oil / Seal Coat	0.955	16	40		3 (Fair)
	Road Oil / Seal Coat	0.650	16	40		3 (Fair)
CR 4222 KENNEDY CORNER (45 MPH)	Asphalt / Seal Coat	1.896	18	50		3 (Fair)
CR 4224 STELLA WALKER (45 MPH)	Asphalt / Seal Coat	6.084	18	50		4 (Good)
CR 4225 RED FLAT (45 MPH)	Road Oil / Seal Coat	2.426	18	50		3 (Fair)
CR 4226 ROUND TOP CHURCH	Road Oil / Seal Coat	0.940	16	40		4 (Good)
CR 4228 BRUNO	Road Oil / Seal Coat	0.186	16	40		3 (Fair)
CR 4229 RYLIE (Off 4226)	Dirt	0.336	16	40		3 (Fair)
CR 4231 BETHEL CEMETARY	Road Oil / Seal Coat	1.071	16	40		4 (Good)
CR 4233 NEWMAN (ext 4235)	Road Oil / Seal Coat	1.439	16	40		4 (Good)
CR 4234	Iron Ore	0.517	16	30		2 (Poor)
CR 4235 JOHN'S (35 MPH)	Road Oil / Seal Coat	2.273	16	40		3 (Fair)

## County Roads

Type: All  
 Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4236 DANSBY (ext 4235)	Road Oil / Seal Coat	1.073	16	50		4 (Good)
CR 4237 UNDERWOOD (ext ACR 300-303)	Oil Sand	0.386	16	40		3 (Fair)
CR 4238 (off FM 315)	Iron Ore	0.348	16	40		3 (Fair)
CR 4239 BOLES	Road Oil / Seal Coat	0.393	16	40		3 (Fair)
CR 4300 BELL (off FM 314)	Road Oil / Seal Coat	0.839	16	40		3 (Fair)
CR 4301 BELL CEMETARY (off 4300)	Dirt	0.296	16	30		3 (Fair)
CR 4302 ALLEN (off 4300)	Dirt	0.076	16	40		3 (Fair)
CR 4303 GENE LINSEY (off 314)	Oil Sand	0.164	18	40		3 (Fair)
	Oil Sand	0.036	18	40		3 (Fair)
CR 4304 LONE STAR (off FM 314)	Asphalt / Seal Coat	0.816	18	50		3 (Fair)
	Asphalt / Seal Coat	1.384	18	50		3 (Fair)
CR 4305N C. HARMON (ext 4304)	Road Oil / Seal Coat	1.140	16	40		3 (Fair)
	Road Oil / Seal Coat	0.454	16	40		3 (Fair)
CR 4305S HIGHTOWER (ext 4304)	Road Oil / Seal Coat	0.533	16	40		4 (Good)
CR 4307 GUSSIE LEE (35 MPH) {Minor Collector}	Asphalt / Seal Coat	0.370	16	50		4 (Good)
	Asphalt / Seal Coat	2.683	16	50		4 (Good)
CR 4308 STEVE (off 4305 N)	Road Oil / Seal Coat	0.288	16	40		3 (Fair)
CR 4309 LIVE COVE (off 4307)	Road Oil / Seal Coat	0.270	16	40		5 (Excellent)
CR 4310 FGS Pinewood Trail	Oil Sand	0.543	20	50		4 (Good)
CR 4311 FGS Pineview Trail	Road Oil / Seal Coat	0.766	18	40		4 (Good)
CR 4311A FGS Pinebluff Rd.	Oil Sand	0.126	16	40		3 (Fair)
CR 4312 FGS Pinewilde Rd.	Road Oil / Seal Coat	0.156	16	40		4 (Good)
CR 4313 (ext 4307) PINECREST	Road Oil	0.173	16	40		2 (Poor)
CR 4314 (ext 4307)	Road Oil / Seal Coat	0.190	16	40		4 (Good)
CR 4316 EULESS WARREN (ext 4307)	Road Oil / Seal Coat	0.577	16	40		3 (Fair)
CR 4317A MOORE STA. LOOP	Road Oil / Seal Coat	0.370	16	40		4 (Good)
CR 4317B HOE HANDLE	Dirt	1.194	16	40		3 (Fair)
CR 4318 (off 4319)	Road Oil / Seal Coat	0.150	18	40		4 (Good)
CR 4319 FED'S {Minor Collector}	Road Oil / Seal Coat	1.874	16	40		4 (Good)
	Road Oil / Seal Coat	0.626	16	40		4 (Good)
CR 4320 CUMBY	Road Oil / Seal Coat	0.266	16	40		4 (Good)

## County Roads

Type: All

Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4321 PRESSWOOD	Iron Ore	0.356	16	40		4 (Good)
CR 4322 TIP TOP	Asphalt	0.344	14	30		4 (Good)
CR 4323 STREETS (off FM 315)	Road Oil	0.120	14	30		4 (Good)
	Road Oil	0.030	14	30		
CR 4324 OILFIELD (off 4325)	Iron Ore	0.083	14	30		3 (Fair)
CR 4325 N.Y.- MOORE STATION {Minor Collector}	Asphalt / Seal Coat	7.644	18	50		4 (Good)
CR 4326 SORRELLS Oil Field (Gated)	Dirt	0.126	16	40		4 (Good)
CR 4328 TROY CROSSLEY (35 MPH)	Asphalt	2.839	16	40		4 (Good)
CR 4329 (off 4325)	Dirt	0.306	14	30		3 (Fair)
CR 4330 DINGLER	Asphalt	4.575	18	40		4 (Good)
CR 4331 TERRELL-HOWETH	Asphalt	2.866	18	40		3 (Fair)
CR 4332 TINDEL-A (off FM 607)	Dirt	0.460	14	30		3 (Fair)
CR 4334 N.Y. CHURCH	Road Oil / Seal Coat	2.450	18	50		5 (Excellent)
CR 4335 ARCHIE DENNIS-A (ext 4334)	Iron Ore	0.304	16	40		3 (Fair)
CR 4336 MYRTLE SPRINGS (45 MPH)	Asphalt / Seal Coat	7.113	18	50		3 (Fair)
CR 4338 KUGLE (ext 4328)	Iron Ore	0.600	16	40		2 (Poor)
CR 4340 ROY SMITH (ext 4336)	Seal Coat	1.018	16	40		3 (Fair)
CR 4341 Taylor Farms Rd (ext 4336)	Iron Ore	1.016	14	30		3 (Fair)
CR 4343 JOE YOUNG	Road Oil / Seal Coat	5.735	16	50		3 (Fair)
	Road Oil / Seal Coat	0.765	16	50		3 (Fair)
CR 4344 BOB WALKER	Road Oil	1.413	16	40		4 (Good)
CR 4345 CHURCH OF CHRIST	Road Oil / Seal Coat	0.570	16	40		2 (Poor)
CR 4346 SMITH	Oil Sand	1.823	16	40		3 (Fair)
CR 4348 SHOLAR'S	Road Oil / Seal Coat	0.673	16	40		5 (Excellent)
CR 4349 WYLIE	Oil Sand	0.366	16	40		3 (Fair)
	Iron Ore	0.661	16	40		3 (Fair)
CR 4350 LARUE CEMETARY	Road Oil / Seal Coat	0.459	16	30		4 (Good)
CR 4351 LARUE	Road Oil / Seal Coat	0.203	16	40		4 (Good)
CR 4353 LARUE	Road Oil / Seal Coat	0.258	16	40		4 (Good)
CR 4355 LARUE FIRE DEPT	Road Oil / Seal Coat	0.256	16	40		4 (Good)
CR 4356 BERRYHILL / LARUE	Iron Ore	0.020	16	40		4 (Good)

## County Roads

Type: All  
Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4357 CHURCH CAMP	Oil Sand	0.159	14	30		3 (Fair)
	Iron Ore	0.360	14	30		3 (Fair)
CR 4359 CHAMPS (off FM 314)	Road Oil / Seal Coat	0.150	14	30		4 (Good)
CR 4360 BROWN-B (off FM 314)	Road Oil / Seal Coat	0.110	14	30		4 (Good)
CR 4400 ROCKHILL (35 MPH)	Asphalt / Seal Coat	5.283	18	50		3 (Fair)
CR 4401 DOUGLAS LOOP	Road Oil / Seal Coat	0.766	16	40		3 (Fair)
CR 4402 ROSENBERG (off FM 2588) (35 MPH)	Road Oil / Seal Coat	4.130	16	40		3 (Fair)
CR 4403 SISSY'S	Road Oil / Seal Coat	1.810	16	40		4 (Good)
CR 4404 ARCHIE DENNIS-A (off US 175)	Road Oil / Seal Coat	0.400	16	50		3 (Fair)
CR 4405 ARCHIE DENNIS-B (off 4404)	Oil Sand	0.298	18	30		3 (Fair)
CR 4494 TUFFY ROBERTS	Oil Sand	0.108	16	40	2	2 (Poor)
CR 4500	Road Oil / Seal Coat	0.150	16	40		3 (Fair)
CR 4501 COUNTRY LN	Road Oil / Seal Coat	0.380	16	40		4 (Good)
CR 4502 CREEKSIDE (off US 175)	Road Oil / Seal Coat	0.130	16	40		4 (Good)
CR 4503 ENOCK (off US 175)	Road Oil / Seal Coat	0.771	16	40		3 (Fair)
CR 4504 Rakestraw	Road Oil / Seal Coat	0.320	16	40		4 (Good)
CR 4506 HUGGINS (ext 4507)	Road Oil / Seal Coat	0.500	10	20		2 (Poor)
CR 4507 MOONSHINE (off US 175)	Road Oil / Seal Coat	0.926	16	50		5 (Excellent)
CR 4508 MOONSHINE (ext 4507)	Road Oil / Seal Coat	0.623	16	40		3 (Fair)
CR 4509 HARRY MILLS	Road Oil / Seal Coat	0.311	16	40		3 (Fair)
	Oil Sand	0.169	16	40		2 (Poor)
CR 4510 TU	Road Oil / Seal Coat	1.753	16	40		5 (Excellent)
CR 4511 BAXTER/PINEGROVE (45 MPH) {Minor Collector*}	Road Oil / Seal Coat	3.217	18	50		3 (Fair)
CR 4511A CHAMPION RANCH DR. (Champion Ranch)	Asphalt	0.840	18	50		5 (Excellent)
CR 4511B CHAMPION STABELS DR. (Champion Ranch)	Asphalt	0.348	18	50		5 (Excellent)
CR 4511C HORSESHOE DR. (Champion Ranch)	Asphalt	0.846	18	50		5 (Excellent)
CR 4511D STALLION LAKES CRT. (Champion Ranch)	Asphalt	0.145	18	50		5 (Excellent)
CR 4513 D. McGEE	Road Oil / Seal Coat	0.510	16	40		4 (Good)
CR 4514 DAVIS CEM.	Oil Sand	0.090	14	40		4 (Good)



## County Roads

Type: All  
 Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4515 RICHARDSON (45 MPH)	Asphalt / Seal Coat Asphalt / Seal Coat Asphalt / Seal Coat	4.887	18	50		4 (Good)
CR 4516 HAIRGROVE	Road Oil / Seal Coat	1.970	16	40		3 (Fair)
CR 4517 CUMMINGS	Road Oil / Seal Coat Iron Ore	0.356 0.074	14 14	40 40		3 (Fair) 3 (Fair)
CR 4518 BURNETT / SUPER COP (35MPH)	Road Oil / Seal Coat	1.117	16	40		4 (Good)
CR 4520E RAINBOW-E ( Rainbo Gate to 4402	Millings RAP	2.676	18	40		3 (Fair)
CR 4520W RAINBOW-W (1615 to Rainbo Gate)	Road Oil / Seal Coat	2.700	18	40		3 (Fair)
CR 4521 LOOKABOUTH	Road Oil / Seal Coat	0.410	16	40		4 (Good)
CR 4522 GROSS	Road Oil / Seal Coat	0.423	16	40		3 (Fair)
CR 4523 HALBERT	Road Oil / Seal Coat	0.227	16	40		4 (Good)
CR 4524 BUBBA BURNETT	Road Oil / Seal Coat	0.240	14	40		5 (Excellent)
CR 4528 COUNTY LINE (35 MPH)	Road Oil / Seal Coat	5.087	18	40		3 (Fair)
CR 4529 MRS. MCGEE	Iron Ore	0.580	16	40		2 (Poor)
CR 4530 SHEPTRINE (35 MPH)	Road Oil / Seal Coat	1.251	14	40		4 (Good)
CR 4533	Millings RAP	0.130				4 (Good)
CR 4534 (GATED NO ACCESS)	Iron Ore	0.040	16	50	2	4 (Good)
CR 4535 PALMER	Other	0.103	14	30		4 (Good)
CR 4537 E. COLLEGE	Asphalt / Seal Coat	0.540	18	50		4 (Good)
CR 4538 COLONIAL CIRCLE	Road Oil / Seal Coat	0.631	20	50		3 (Fair)
CR 4600 CARROLL SPRINGS (35 MPH)	Road Oil / Seal Coat	2.439	16	40		5 (Excellent)
CR 4601 (to county line)	Road Oil / Seal Coat	0.250	14	40		2 (Poor)
CR 4603 MUD ALLEY	Road Oil / Seal Coat	0.190	14	40		3 (Fair)
CR 4604 Terry Davis	Road Oil / Seal Coat	0.490	16	40		5 (Excellent)
CR 4607 DIAMOND C	Road Oil / Seal Coat	0.683	18	40		5 (Excellent)
CR 4608 D WARREN	Oil Sand	0.247	14	40		4 (Good)
CR 4610 GARY RD	Road Oil / Seal Coat	2.093	18	50		3 (Fair)
CR 4610A BROWN-A	Road Oil / Seal Coat	0.681	16	40		3 (Fair)
CR 4610B LASITER	Road Oil / Seal Coat	0.340	16	40		3 (Fair)
CR 4610C BONHAM	Road Oil / Seal Coat	0.249	16	40		3 (Fair)

## County Roads

Type: All  
 Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4611 BUTLER	Road Oil / Seal Coat	0.330	18	40	2	5 (Excellent)
CR 4612 MAYS CAFÉ	Road Oil / Seal Coat	0.453	14	30		2 (Poor)
CR 4613 OLD 19 (35 MPH)	Asphalt / Seal Coat	2.978	16	50		5 (Excellent)
CR 4614 HOLDER (35 MPH)	Road Oil / Seal Coat	1.648	16	40		3 (Fair)
CR 4615 LITTLE ACRES	Asphalt / Seal Coat	0.183	16	40		5 (Excellent)
CR 4616 GIN	Oil Sand	0.393	16	40		3 (Fair)
CR 4617 CARROL DR / VIRGINIA PINES-A	Road Oil / Seal Coat	0.240	16	40		4 (Good)
CR 4618 VIRGINIA PINES-B	Road Oil / Seal Coat	0.186	16	40		4 (Good)
CR 4619 VIRGINIA PINES-C	Road Oil / Seal Coat	0.190	16	40		4 (Good)
CR 4622 OWEN CEMETARY	Oil Sand	0.983	18	40		5 (Excellent)
CR 4625 South Park Circle	Asphalt	0.187	20	50	2	4 (Good)
CR 4626 WAVERLY WAY 30 MPH	Road Oil / Seal Coat	0.331	24	50		4 (Good)
CR 4627 GIBSON {Minor Collector*}	Road Oil / Seal Coat	0.493	18	50		3 (Fair)
CR 4628 ROBBINS RD (35 MPH) {Minor Collector*}	Asphalt / Seal Coat	1.355	18	40		4 (Good)
CR 4700 WARD (35 MPH) {Minor Collector}	Asphalt	1.976	18	50		5 (Excellent)
CR 4700A WOODCREST (ext 4700)	Road Oil / Seal Coat	0.141	18	40		4 (Good)
CR 4700B RUTH (ext 4700)	Road Oil / Seal Coat	0.090	18	40		4 (Good)
CR 4702 NEW SUBDIVISION (between 4704 & 4705)	Other	0.444				4 (Good)
CR 4703 HOPEWELL CHURCH	Road Oil / Seal Coat	0.051	14	30		4 (Good)
CR 4704 RAY ROAD	Road Oil / Seal Coat	1.833	14	40		2 (Poor)
CR 4705 THOMAS FRANK	Road Oil / Seal Coat	1.166	16	40		3 (Fair)
CR 4706 POWDER RIVER	Iron Ore	2.183	16	40		3 (Fair)
CR 4708 SMITH LUMBER	Dirt	0.850	16	40		3 (Fair)
CR 4710 COOK-A	Millings RAP	1.310	16	40		3 (Fair)
CR 4712 COOK-B	Road Oil / Seal Coat	2.601	16	40		3 (Fair)
CR 4713 KITCHENS	Dirt	0.316	14	40		4 (Good)
CR 4714 Tiner (off 4712)	Road Oil / Seal Coat	0.173	14	40		5 (Excellent)
CR 4715 ALLIGATOR	Road Oil / Seal Coat	1.583	14	30		2 (Poor)
CR 4716 Tiger	Road Oil / Seal Coat	0.086				3 (Fair)
CR 4717 HOSKINS	Road Oil / Seal Coat	0.112	14	30		3 (Fair)
CR 4718 HALLMARK	Road Oil / Seal Coat	0.461	14	30		3 (Fair)

## County Roads

Type: All

Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4719 COUNTY BARN	Road Oil / Seal Coat	0.335	16	40		2 (Poor)
CR 4720 LAMBRIGHT	Road Oil / Seal Coat	0.343	14	40		3 (Fair)
CR 4800 BAXTER RD (45 MPH) {Minor Collector*}	Road Oil / Seal Coat	1.821	18	50		3 (Fair)
CR 4801 DAM	Road Oil / Seal Coat	1.162	16	40		4 (Good)
CR 4802 PERKINS {Minor Collector*}	Road Oil / Seal Coat	0.546	20	40		5 (Excellent)
CR 4803 OAKWOOD	Road Oil / Seal Coat	1.549	18	50		4 (Good)
CR 4804 UPPER ROOM {Minor Collector*}	Road Oil / Seal Coat	1.170	16	40		4 (Good)
CR 4805 PLANTATION POINT (30 MPH)	Road Oil / Seal Coat	1.150	16	40		4 (Good)
CR 4805A PLANTATION Point Dr E	Asphalt / Seal Coat	0.211	18	40		3 (Fair)
CR 4806 (off 4804)	Road Oil / Seal Coat	0.410	16	40		3 (Fair)
CR 4807 Grassy Lane	Road Oil	0.116	12	15	1	3 (Fair)
CR 4807 VFW	Oil Sand	0.211				4 (Good)
CR 4808 Impala South (30 MPH)	Asphalt	1.020				4 (Good)
CR 4810 VIEWPOINT (off Bear Creek)	Road Oil / Seal Coat	0.310	14	40		3 (Fair)
CR 4810A DREW Ln. (off Viewpoint)	Asphalt					
	Road Oil	0.090	18	40		4 (Good)
CR 4811 PEEWEE	Road Oil / Seal Coat	1.616	16	40		4 (Good)
CR 4812 Peninsula Point {Minor Collector*} (35 MPH) 40,000 lb	Asphalt / Seal Coat	0.609	18	50		4 (Good)
CR 4812A Peninsula Circle	Asphalt	0.700	18	40		4 (Good)
CR 4812B West Circle	Asphalt	0.053	18	40		4 (Good)
CR 4812C East Circle	Asphalt	0.037	18	40		4 (Good)
CR 4812D Dorsey Ln.	Asphalt	0.308				4 (Good)
CR 4812E Dorsey Circle	Asphalt	0.046	18	40		4 (Good)
CR 4812F Dorsey Drive	Asphalt	0.356	18	40		4 (Good)
CR 4812G Crestview Rd (Timberlake Estates)	Asphalt	0.571	18	40		4 (Good)
CR 4812H Sherwood Rd. (Timberlake Estates)	Asphalt	0.310	18	40		4 (Good)
CR 4812J Kim Ln (Timberlake Estates)	Asphalt	0.108	18	40		4 (Good)
CR 4812K TANGLEWOOD (Timberlake Estates)	Asphalt	0.313				4 (Good)
CR 4814 E. Ridge Rd (off 2495)	Asphalt	0.101				4 (Good)
CR 4814A Lewis Ct.	Asphalt	0.108				5 (Excellent)
CR 4815 SUNCRESTDr. (off 2495)	Asphalt	0.341	18	50		5 (Excellent)

## County Roads

Type: All  
Rating: All

Henderson County

### Precinct 4: County Roads

Road Number and/or Road Name	Surface Type	Length (Miles)	Width (Feet)		Traffic Lanes	Rating (Condition)
			Surface	R.O.W.		
CR 4815A Sunrise Ct.	Asphalt	0.123				5 (Excellent)
CR 4815B Sunset Ct.	Asphalt	0.060	18	50		5 (Excellent)
CR 4817 PHANTOM (30 MPH)	Road Oil / Seal Coat	1.046	18	50		4 (Good)
CR 4819 GRUBBS	Road Oil / Seal Coat	0.134	16	40		4 (Good)
CR 4825 BEARCREEK {Minor Collector*}	Road Oil / Seal Coat	1.506	16	50		3 (Fair)
CR 4825A BEARCREEK CIRCLE	Road Oil / Seal Coat	0.273	16	40		3 (Fair)
CR 4826 HOPSON	Road Oil / Seal Coat	1.765	16	40		4 (Good)
CR 4826A Two Mile Cir. (off Hopson)	Road Oil / Seal Coat	0.491	16	40		3 (Fair)
CR 4827 BLUEBIRD	Road Oil / Seal Coat	0.551	14	40		4 (Good)
CR 4828 ROUNSAVALL	Asphalt	1.234	16	40		5 (Excellent)
CR 4829 TINDEL-B	Oil Sand	0.835	18	40		5 (Excellent)
CR 4830 COY TERREL	Oil Sand	0.578	18	40		5 (Excellent)
CR 4831 Melvin Pool	Oil Sand	0.416	16	40		4 (Good)
CR 4832 LEDBETTER	Oil Sand	0.666	14	40		4 (Good)
CR 4833 JOHN MARK	Oil Sand	1.520	16	40		4 (Good)
CR 4834 PeeWee Dirt RD	Iron Ore	0.750				3 (Fair)
CR 4835 COLEMAN	Road Oil / Seal Coat	0.605	16	40		3 (Fair)
	Dirt	1.327	14	40		3 (Fair)
CR 4836 DUCKER	Road Oil / Seal Coat	0.134	14	40		4 (Good)
CR 4837 FORESTER DR.	Road Oil / Seal Coat	1.055	16	50		4 (Good)
CR 4838 GARNER	Asphalt	0.480	16	40		4 (Good)
CR 4908 JOE BROWNING	Asphalt	0.724	16	40		5 (Excellent)
CR 4910 ROBY	Road Oil / Seal Coat	0.511	18	40		5 (Excellent)
CR 4911 DEER RUN	Road Oil / Seal Coat	0.610	16	40		3 (Fair)
CR 4912 CRYSTAL	Road Oil / Seal Coat	0.230	18	50		3 (Fair)
CR 4913 DUSTY RD.	Oil Sand	0.540	16	40		4 (Good)
CR 4914 Lakefront Shores Rd.	Asphalt	0.351	16	50		3 (Fair)

Mileage Recorded for Precinct 4    244.015



**Road & Bridge  
Annual Road Report**

**FY - 2017**

**PRECINCT 4**

**ROAD MAINTENANCE  
REPORT**



## Daily Work Expense Summary (Annual Report)

1/1/2017 - 12/31/2017

All Assignments	Henderson County			
Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
2 Multi Locations	837.20	674.80		1,512.00
155 Autumn Trail (Brierwood Bay)				
155 Brierwood Dr (Brierwood Bay)	2,843.59	12,231.65	2,639.32	17,714.56
155 Carol Way (Brierwood Bay)				
155 Coral Dr. (Brierwood Bay)	38.27	42.25	34.52	115.04
155 Cutter Dr (Brierwood Bay)	38.27	42.25	34.52	115.04
155 Driftwood (Brierwood Bay)				
155 Forest Hill Dr. NS ( Brierwood Bay )	2,230.60	6,384.00	2,279.80	10,894.40
155 High Point Dr. (Brierwood Bay)	633.74	2,048.50	9,078.33	11,760.57
155 Holley Hills (Brierwood Bay)	304.24	586.00		890.24
155 Judy Ln. (Brierwood Bay)				
155 Lindy Ln (Brierwood Bay)				
155 Phillip Pl (Brierwood Bay)	38.27	42.25	34.52	115.04
155 Shadybrook Dr. (Brierwood Bay)	803.50	3,093.00	6,496.49	10,392.99
155 Valleyview Dr (Brierwood Bay)	123.11	81.15	34.52	238.78
315 Parkside St. (Parkside)	929.84	2,517.25	2,495.29	5,942.38
CR 4020 Pine ST (FAT DOG)				
CR 4100 HENDERSON (ext 4117)	584.72	2,019.50	3,754.76	6,358.98
CR 41000 BRENTWOOD DR. (Oak Manor) {Minor Collector}				
CR 41001 BRENTWOOD CIRCLE (Oak Manor)				
CR 41002 RANCH ROAD (Oak Manor)	63.85	126.75	92.33	282.93
CR 4101 PERRY (ext 4117)				
CR 4102 BUD JONES (ext 4117)	141.52	848.00		989.52
CR 4103 (ext 4102)				
CR 4104 ATWOOD-A (Off 155)				
CR 41100 WAGONTREE TRAIL {Minor Collector}				
CR 41101 BROKENSPOKE (Wagontree)				
CR 41102 SINGLETREE (Wagontree)	19.75	42.25	63.13	125.13
CR 41103 SETTLERS LOOP (Wagontree)	77.66	235.12	64.79	377.57

Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 41105 LAND GRANT (Wagontree) {Minor Collector}	213.90	621.00	388.13	1,223.03
CR 41106 DOUBLETREE (Wagontree)				
CR 41107 MILL RUN RD (35 MPH)	7,488.22	30,332.48	88,713.77	126,534.47
CR 4112 Bacon Bacon			23.48	23.48
CR 41126 LABELLO	162.00	380.00		542.00
CR 4117 B. VILLE {Minor Collector*}	4,485.06	12,424.85	145.49	17,055.40
CR 4117A KIETH LN (ext 4117)				
CR 4117B KEVIN CIRCLE (ext 4117)				
CR 4119 COFFEE CITY LANDING	2,068.24	7,699.00		9,767.24
CR 4120 ATWOOD-B (Off 155)	99.52	390.50	450.00	940.02
CR 41201 OAKTREE Dr. (Dogwood)	97.40	169.00	396.00	662.40
CR 41511 (Larry Anding)	634.34	1,918.25	534.82	3,087.41
CR 41512 RYAN	48.70	84.50	238.36	371.56
CR 41513	39.50	84.50	91.74	215.74
CR 41514	196.11	197.25	98.53	491.89
CR 41515 McGEE NURSEY	939.98	2,682.15	234.82	3,856.95
CR 41516 DOUGLAS DRIVE	24.35	42.25	59.00	125.60
CR 41518 (EXT. Douglas)	24.35	42.25	66.23	132.83
CR 4200 (Road Closed)				
CR 4201 SUNRISE (off 315) {Minor Collector}	1,351.47	4,278.25	73.34	5,703.06
CR 4201A CHEROKEE Dr. (Cherokee)	24.35	42.25	73.34	139.94
CR 4201B Sunbird Dr. (Cherokee)	12.17	21.12	73.34	106.63
CR 4201C Tomahawk Dr. (Cherokee)	12.17	21.12	73.34	106.63
CR 4201D Arrowhead Dr. (Cherokee)				
CR 4201E Ridge Rd. (Woodridge)	19.75	42.25	59.00	121.00
CR 4201F Quil Cutoff (Woodridge)	19.75	42.25	59.00	121.00
CR 4201G Hillcrest (Woodridge)	19.75	42.25	29.50	91.50
CR 4201H Pineview (Woodridge)	19.75	42.25	29.50	91.50
CR 4202 CAPE (off FM 3506)	187.92	316.87	137.06	641.85
CR 4213 TWIN OAKS (off FM 315)	123.28	211.25	162.25	496.78
CR 4213A Post Oak (Twin Oaks)	567.20	2,182.00	3,771.28	6,520.48
CR 4215 WELDER (ext 4224)	454.96	1,518.25		1,973.21

Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 4216 Old Caney Rd (ext. off old 4200)				
CR 4217 MANOY (Pleasant Ridge)	7,403.84	20,373.50	38,488.60	66,265.94
CR 4218 STEVENSON (Off 4217)	2,015.76	6,856.50	325.00	9,197.26
CR 4220 DIXON (ext off 4221)	24.35	42.25	59.00	125.60
CR 4221 PINE SPRINGS (ext off 4222)	136.23	165.65	127.47	429.35
CR 4222 KENNEDY CORNER (45 MPH)	109.57	144.52	127.47	381.56
CR 4223 MAYOR RD (ext 4217)				
CR 4224 STELLA WALKER (45 MPH)	5,049.58	16,115.40	29,783.80	50,948.78
CR 4225 RED FLAT (45 MPH)	350.06	1,164.50	346.32	1,860.88
CR 4226 ROUND TOP CHURCH	1,265.62	3,801.00	6,735.05	11,801.67
CR 4228 BRUNO	24.35	42.25	92.07	158.67
CR 4229 RYLIE (Off 4226)	582.80	2,147.00	1,890.11	4,619.91
CR 4231 BETHEL CEMETARY	529.34	2,755.25	171.69	3,456.28
CR 4233 NEWMAN (ext 4235)	1,463.80	5,830.85	269.49	7,564.14
CR 4234	18.04	19.45		37.49
CR 4235 JOHN'S (35 MPH)	1,973.75	5,628.70	371.41	7,973.86
CR 4236 DANSBY (ext 4235)	512.63	2,146.75	237.77	2,897.15
CR 4237 UNDERWOOD (ext ACR 300-303)	431.50	1,311.00	982.86	2,725.36
CR 4238 (off FM 315)				
CR 4239 BOLES	118.50	253.50	217.71	589.71
CR 4300 BELL (off FM 314)	84.56	169.00	93.22	346.78
CR 4303 GENE LINSEY (off 314)	25.00	84.50	59.00	168.50
CR 4304 LONE STAR (off FM 314)	861.48	949.75	139.24	1,950.47
CR 4305N C. HARMON (ext 4304)	25.00	84.50	91.04	200.54
CR 4305S HIGHTOWER (ext 4304)	25.00	84.50	50.74	160.24
CR 4307 GUSSIE LEE (35 MPH) {Minor Collector}	1,385.46	4,839.95	6,010.45	12,235.86
CR 4308 STEVE (off 4305 N)	152.12	353.25	125.00	630.37
CR 4309 LIVE COVE (off 4307)				
CR 4310 FGS Pinewood Trail	42.28	84.50	99.30	226.08
CR 4311 FGS Pineview Trail				
CR 4312 FGS Pinewilde Rd.	162.00	169.00	122.13	453.13
CR 4313 (ext 4307) PINECREST	38.83	42.25	44.99	126.07



Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 4314 (ext 4307)				
CR 4316 EULESS WARREN (ext 4307)			40.30	40.30
CR 4317A MOORE STA. LOOP	666.28	1,964.50	59.00	2,689.78
CR 4317B HOE HANDLE				
CR 4318 (off 4319)				
CR 4319 FED'S {Minor Collector}	1,198.40	6,370.00	99.30	7,667.70
CR 4320 CUMBY				
CR 4321 PRESSWOOD				
CR 4322 TIP TOP	191.80	402.00	148.68	742.48
CR 4323 STREETS (off FM 315)				
CR 4325 N.Y.- MOORE STATION {Minor Collector}	1,632.68	8,580.00	500.64	10,713.32
CR 4328 TROY CROSSLEY (35 MPH)	343.55	549.25	461.83	1,354.63
CR 4329 (off 4325)	205.56	706.50		912.06
CR 4330 DINGLER	785.98	3,135.50	682.87	4,604.35
CR 4331 TERRELL-HOWETH	112.55	211.25	212.75	536.55
CR 4332 TINDEL-A (off FM 607)	498.08	2,168.00		2,666.08
CR 4334 N.Y. CHURCH	154.77	263.22	295.61	713.60
CR 4336 MYRTLE SPRINGS (45 MPH)	1,537.43	7,325.97	774.83	9,638.23
CR 4340 ROY SMITH (ext 4336)	1,406.07	5,006.25	1,621.50	8,033.82
CR 4341 Taylor Farms Rd (ext 4336)	1,600.42	6,018.00		7,618.42
CR 4343 JOE YOUNG	1,964.59	6,656.75	13,085.32	21,706.66
CR 4344 BOB WALKER	37.50	126.75	94.10	258.35
CR 4345 CHURCH OF CHRIST				
CR 4346 SMITH	886.52	3,510.00	1,350.00	5,746.52
CR 4347 FLOYD'S (Poynor)				
CR 4348 SHOLAR'S	3,868.80	12,542.75	42,388.12	58,799.67
CR 4349 WYLIE	35.38	212.00		247.38
CR 4350 LARUE CEMETARY	2,465.00	6,189.35	2,341.69	10,996.04
CR 4351 LARUE				
CR 4353 LARUE				
CR 4400 ROCKHILL (35 MPH)	2,875.44	10,229.00	1,017.42	14,121.86
CR 4401 DOUGLAS LOOP	184.72	531.90		716.62

Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 4402 ROSENBERG (off FM 2588) (35 MPH)	958.48	2,201.50	809.55	3,969.53
CR 4403 SISSY'S	1,918.36	5,390.90	21,045.94	28,355.20
CR 4404 ARCHIE DENNIS-A (off US 175)	261.50	1,165.00	1,998.92	3,425.42
CR 4494 TUFFY ROBERTS				
CR 4500	1,065.36	2,650.75	963.20	4,679.31
CR 4501 COUNTRY LN	171.76	155.00	89.68	416.44
CR 4502 CREEKSIDE (off US 175)				
CR 4503 ENOCK (off US 175)				
CR 4504 Rakestraw	241.54	19.45	416.76	677.75
CR 4506 HUGGINS (ext 4507)				
CR 4507 MOONSHINE (off US 175)				
CR 4508 MOONSHINE (ext 4507)	97.40	169.00	312.00	578.40
CR 4509 HARRY MILLS	73.05	126.75	251.25	451.05
CR 4510 TU	326.01	572.37	17.25	915.63
CR 4511 BAXTER/PINEGROVE (45 MPH) {Minor Collector*}	409.62	925.25	507.23	1,842.10
CR 4513 D. McGEE	70.10	126.75	113.28	310.13
CR 4514 DAVIS CEM.	45.75	84.50	66.67	196.92
CR 4515 RICHARDSON (45 MPH)	683.46	1,496.45	927.48	3,107.39
CR 4516 HAIRGROVE	807.96	2,635.40	415.06	3,858.42
CR 4518 BURNETT / SUPER COP (35MPH)	167.44	272.95	455.03	895.42
CR 4520E RAINBOW-E ( Rainbo Gate to 4402	997.29	3,227.00	1,617.45	5,841.74
CR 4520W RAINBOW-W (1615 to Rainbo Gate)	1,249.03	4,876.75	430.92	6,556.70
CR 4521 LOOKABOUGH				
CR 4522 GROSS				
CR 4523 HALBERT				
CR 4524 BUBBA BURNETT	1,247.08	3,475.25	11,907.60	16,629.93
CR 4528 COUNTY LINE (35 MPH)	6,377.71	19,511.30	105,740.14	131,629.15
CR 4529 MRS. MCGEE				
CR 4530 SHEPTRINE (35 MPH)				
CR 4533				
CR 4535 PALMER	6.25			6.25
CR 4537 E. COLLEGE	39.50	84.50	65.25	189.25

Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 4538 COLONIAL CIRCLE	39.50	84.50	75.00	199.00
CR 4600 CARROLL SPRINGS (35 MPH)	1,380.60	3,937.00	11,930.61	17,248.21
CR 4601 (to county line)	73.05	126.75	145.14	344.94
CR 4604 Terry Davis	153.72	324.00	18.29	496.01
CR 4607 DIAMOND C				
CR 4608 D WARREN				
CR 4609 ANDING				
CR 4610 GARY RD	592.91	1,302.00	1,896.15	3,791.06
CR 4610A BROWN-A				
CR 4610B LASITER				
CR 4610C BONHAM				
CR 4611 BUTLER	1,249.73	3,446.50	15,628.62	20,324.85
CR 4612 MAYS CAFÉ	168.67	890.25	75.00	1,133.92
CR 4613 OLD 19 (35 MPH)	15,531.22	51,505.50	133,241.72	200,278.44
CR 4614 HOLDER (35 MPH)	822.94	1,316.70	1,570.00	3,709.64
CR 4615 LITTLE ACRES	17.87	9.72	20.61	48.20
CR 4616 GIN	168.67	890.25	118.00	1,176.92
CR 4617 CARROL DR / VIRGINIA PINES-A	158.91	159.05	59.00	376.96
CR 4618 VIRGINIA PINES-B	24.35	42.25	44.43	111.03
CR 4619 VIRGINIA PINES-C	24.35	42.25	44.43	111.03
CR 4622 OWEN CEMETARY	698.75	3,354.50	670.37	4,723.62
CR 4625 South Park Circle	617.46	1,419.00		2,036.46
CR 4626 WAVERLY WAY 30 MPH	158.91	159.05	44.43	362.39
CR 4627 GIBSON {Minor Collector*}	158.60	253.50	461.95	874.05
CR 4628 ROBBINS RD (35 MPH) {Minor Collector*}	170.45	204.55	257.71	632.71
CR 4700 WARD (35 MPH) {Minor Collector}	5,745.67	20,279.35	87,215.15	113,240.17
CR 4700A WOODCREST (ext 4700)				
CR 4700B RUTH (ext 4700)				
CR 4702 NEW SUBDIVISION (between 4704 & 4705)	275.10	605.50		880.60
CR 4703 HOPEWELL CHURCH	15.79	21.12	31.27	68.18
CR 4704 RAY ROAD	184.31	232.38	493.00	909.69
CR 4705 THOMAS FRANK	49.35	42.25	17.25	108.85

Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 4706 POWDER RIVER	193.50	295.75	390.79	880.04
CR 4708 SMITH LUMBER	19.75	42.25		62.00
CR 4710 COOK-A	48.70	84.50	186.00	319.20
CR 4712 COOK-B	3,139.63	13,767.87	747.35	17,654.85
CR 4713 KITCHENS	17.87	9.72	20.61	48.20
CR 4714 Tiner (off 4712)				
CR 4715 ALLIGATOR	1,236.41	5,888.37	894.19	8,018.97
CR 4716 Tiger	212.28	1,272.00		1,484.28
CR 4718 HALLMARK	6.25			6.25
CR 4719 COUNTY BARN	155.30	169.00	118.00	442.30
CR 4720 LAMBRIGHT	19.75	42.25	59.00	121.00
CR 4800 BAXTER RD (45 MPH) {Minor Collector*}	182.77	372.75	317.88	873.40
CR 4801 DAM			106.88	106.88
CR 4802 PERKINS {Minor Collector*}	19.75	42.25	34.50	96.50
CR 4803 OAKWOOD	35.73	19.45	197.88	253.06
CR 4804 UPPER ROOM {Minor Collector*}			90.38	90.38
CR 4805 PLANTATION POINT (30 MPH)				
CR 4806 (off 4804)				
CR 4807 VFW	36.85	42.25	61.95	141.05
CR 4808 Impala South (30 MPH)				
CR 4810 VIEWPOINT (off Bear Creek)	189.20	338.00	570.51	1,097.71
CR 4811 PEEWEE	611.41	2,160.75	376.24	3,148.40
CR 4812 Peninsula Point {Minor Collector*} (35 MPH) 40,000 lb	340.64	1,822.75	108.96	2,272.35
CR 4812A Peninsula Circle			16.50	16.50
CR 4812B West Circle				
CR 4812C East Circle				
CR 4812D Dorsey Ln.			16.50	16.50
CR 4812E Dorsey Circle				
CR 4812F Dorsey Drive	441.28	1,214.75	3,234.03	4,890.06
CR 4812G Crestview Rd (Timberlake Estates)				
CR 4812H Sherwood Rd. (Timberlake Estates)	638.75	2,031.50	1,612.53	4,282.78
CR 4812J Kim Ln (Timberlake Estates)				

Road Number and/or Name	Labor (\$)	Equipment (\$)	Material (\$)	Total (\$)
CR 4812K TANGLEWOOD (Timberlake Estates)	165.46	161.50		326.96
CR 4817 PHANTOM (30 MPH)	98.70	169.00	190.03	457.73
CR 4819 GRUBBS	12.17	21.12	37.50	70.79
CR 4825 BEARCREEK {Minor Collector* }	355.54	948.25	1,531.01	2,834.80
CR 4825A BEARCREEK CIRCLE	12.50			12.50
CR 4826 HOPSON	376.37	1,734.75	150.72	2,261.84
CR 4826A Two Mile Cir. (off Hopson)	12.50		16.50	29.00
CR 4827 BLUEBIRD	31.60	42.25	91.50	165.35
CR 4828 ROUNSAVALL	214.12	714.00		928.12
CR 4829 TINDEL-B	48.70	84.50	206.50	339.70
CR 4830 COY TERREL	6.09	10.56	14.75	31.40
CR 4831 Melvin Pool				
CR 4832 LEDBETTER	39.50	84.50	66.08	190.08
CR 4833 JOHN MARK	621.13	1,597.00	2,350.67	4,568.80
CR 4834 PeeWee Dirt RD	33.64	42.25	47.55	123.44
CR 4835 COLEMAN	121.84	211.25	257.15	590.24
CR 4836 DUCKER	39.50	84.50	43.81	167.81
CR 4837 FORESTER DR.	546.86	972.50	43.81	1,563.17
CR 4838 GARNER	46.14	84.50	73.16	203.80
CR 4908 JOE BROWNING	2,236.27	5,367.30	30,403.41	38,006.98
CR 4910 ROBY	25.00			25.00
CR 4911 DEER RUN	61.85	126.75	101.48	290.08
CR 4912 CRYSTAL	12.50	42.25	17.46	72.21
CR 4913 DUSTY RD.	1,821.60	4,264.25	2,654.42	8,740.27
Cemetary Road				
Elm Street	898.48	1,287.15	833.52	3,019.15
Elwood				
Hunt Oil Road				
Shady Lane	162.00	253.50	142.19	557.69
Total for all roads (\$):	137,746.70	442,935.55	725,961.22	1,306,643.47



**Road & Bridge  
Annual Road Report**

**FY - 2017**

**PRECINCT 4**

**ROAD MAINTENANCE  
REPORT DETAIL**



## Annual Expense Details for Roads

1/1/2017 - 12/31/2017

All Assignments

Henderson County

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>155 Autumn Trail (Brierwood Bay)</u>								
19468	Patched - road surface	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>155 Brierwood Dr (Brierwood Bay)</u>								
18778	Patched - road surface	\$42.25	2.00	\$38.27	\$34.52	1/3/2017	1/3/2017	\$115.04
18914	Inquiry about road status	\$38.90	4.00	\$84.84		2/6/2017	2/6/2017	\$123.74
19350	Cut Brush/ Brush Cutter	\$424.00	4.00	\$70.76		6/29/2017	6/29/2017	\$494.76
19376	Mow Right-of-Way	\$1,456.00	16.00	\$310.64		7/3/2017	7/3/2017	\$1,766.64
19375	Cut Brush/ Brush Cutter	\$1,456.00	16.00	\$310.64		7/5/2017	7/5/2017	\$1,766.64
19374	Mow Right-of-Way	\$1,456.00	16.00	\$310.64		7/6/2017	7/6/2017	\$1,766.64
19373	Cut Brush/ Brush Cutter	\$1,456.00	16.00	\$310.64		7/7/2017	7/7/2017	\$1,766.64
19580	Chip Brush w/ Wood Chipper	\$1,608.00	32.00	\$357.52		8/7/2017	8/7/2017	\$1,965.52
19588	Trimmed brush or trees	\$1,206.00	24.00	\$270.24		8/8/2017	8/8/2017	\$1,476.24
19871	Road culvert - replaced	\$2,362.50	32.00	\$565.28	\$1,954.80	10/5/2017	10/5/2017	\$4,882.58
19915	Road base material - added	\$726.00	12.00	\$214.12	\$650.00	10/6/2017	10/6/2017	\$1,590.12
		<u>\$12,231.65</u>	<u>174.00</u>	<u>\$2,843.59</u>	<u>\$2,639.32</u>			<u>\$17,714.56</u>
<u>155 Carol Way (Brierwood Bay)</u>								
19455	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>155 Coral Dr. (Brierwood Bay)</u>								
18776	Patched - road surface	\$42.25	2.00	\$38.27	\$34.52	1/3/2017	1/3/2017	\$115.04
19456	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$38.27</u>	<u>\$34.52</u>			<u>\$115.04</u>
<u>155 Cutter Dr (Brierwood Bay)</u>								
18777	Patched - road surface	\$42.25	2.00	\$38.27	\$34.52	1/3/2017	1/3/2017	\$115.04
19457	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$38.27</u>	<u>\$34.52</u>			<u>\$115.04</u>
<u>155 Driftwood (Brierwood Bay)</u>								
19464	Patched - road surface	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>155 Forest Hill Dr. NS ( Brierwood Bay )</u>								
19467	Patched - road surface	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
19836	Moved equipment to work site	\$262.00	8.00	\$152.12		10/3/2017	10/3/2017	\$414.12
19872	waterline damaged reschedule	\$1,928.00	32.00	\$565.28		10/6/2017	10/6/2017	\$2,493.28
19920	Road culvert - replaced	\$1,652.00	40.00	\$665.28	\$1,954.80	10/17/2017	10/17/2017	\$4,272.08
19926	Road base material - added (lift road over culvert)	\$1,816.00	32.00	\$565.28	\$0.00	10/18/2017	10/18/2017	\$2,381.28
19941	Road base material - added	\$726.00	16.00	\$282.64	\$325.00	10/19/2017	10/19/2017	\$1,333.64
		<u>\$6,384.00</u>	<u>128.00</u>	<u>\$2,230.60</u>	<u>\$2,279.80</u>			<u>\$10,894.40</u>
<u>155 High Point Dr. (Brierwood Bay)</u>								
19465	Patched - road surface	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
19761	Asphalt overlay	\$2,048.50	40.00	\$633.74	\$9,078.33	8/31/2017	8/31/2017	\$11,760.57
		<u>\$2,048.50</u>	<u>40.00</u>	<u>\$633.74</u>	<u>\$9,078.33</u>			<u>\$11,760.57</u>
<u>155 Holley Hills (Brierwood Bay)</u>								
19466	Patched - road surface	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
19701	Moved equipment to work site	\$586.00	16.00	\$304.24		8/24/2017	8/24/2017	\$890.24
		<u>\$586.00</u>	<u>16.00</u>	<u>\$304.24</u>				<u>\$890.24</u>
<u>155 Judy Ln. (Brierwood Bay)</u>								
19458	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>155 Lindy Ln (Brierwood Bay)</u>								
19454	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>155 Phillip Pl (Brierwood Bay)</u>								
18775	Patched - road surface	\$42.25	2.00	\$38.27	\$34.52	1/3/2017	1/3/2017	\$115.04
19460	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$38.27</u>	<u>\$34.52</u>			<u>\$115.04</u>
<u>155 Shadybrook Dr. (Brierwood Bay)</u>								
19509	Cut Brush/ Brush Cutter	\$636.00	6.00	\$106.14		7/19/2017	7/19/2017	\$742.14
19742	Driveway culvert - reset	\$896.00	12.00	\$220.64		8/28/2017	8/28/2017	\$1,116.64
19762	Oil Sand Overlay	\$1,561.00	32.00	\$476.72	\$6,496.49	8/31/2017	8/31/2017	\$8,534.21
		<u>\$3,093.00</u>	<u>50.00</u>	<u>\$803.50</u>	<u>\$6,496.49</u>			<u>\$10,392.99</u>
<u>155 Valleyview Dr (Brierwood Bay)</u>								
18774	Patched - road surface	\$42.25	2.00	\$38.27	\$34.52	1/3/2017	1/3/2017	\$115.04



ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>155 Valleyview Dr (Brierwood Bay)</u>								
18915	Inquiry about road status	\$38.90	4.00	\$84.84		2/6/2017	2/6/2017	\$123.74
19459	Patched - road surface	\$0.00	0.00	\$0.00		7/13/2017	7/13/2017	\$0.00
		\$81.15	6.00	\$123.11	\$34.52			\$238.78
<u>2 Multi Locations</u>								
19744	Put up County Road Number sign 'NS'	\$155.60	8.00	\$144.32		8/25/2017	8/25/2017	\$299.92
19743	Put up County Road Number sign 'NS'	\$155.60	8.00	\$144.32		8/28/2017	8/28/2017	\$299.92
20005	Put up County Road Number sign 'NS'	\$155.60	16.00	\$244.32		11/20/2017	11/20/2017	\$399.92
20055	Storm preparation (East End)	\$208.00	16.00	\$304.24		12/19/2017	12/19/2017	\$512.24
		\$674.80	48.00	\$837.20				\$1,512.00
<u>315 Parkside St. (Parkside)</u>								
19158	Patched - road surface	\$169.00	12.00	\$126.40	\$183.75	5/12/2017	5/12/2017	\$479.15
19207	Road culvert - replaced	\$1,622.25	32.00	\$582.80	\$1,460.08	5/25/2017	5/25/2017	\$3,665.13
19798	Road surface repair	\$726.00	12.00	\$220.64	\$851.46	9/6/2017	9/6/2017	\$1,798.10
		\$2,517.25	56.00	\$929.84	\$2,495.29			\$5,942.38
<u>Cemetary Road</u>								
19565	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
19602	Mow Right-of-Way					8/7/2017	8/7/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4020 Pine ST (FAT DOG) 1.5 mi.</u>								
19424	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4100 HENDERSON (ext 4117) 0.3 mi.</u>								
19046	Oil Sand Overlay	\$1,171.50	24.00	\$443.20	\$3,754.76	3/27/2017	3/27/2017	\$5,369.46
19804	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		9/7/2017	9/7/2017	\$989.52
		\$2,019.50	32.00	\$584.72	\$3,754.76			\$6,358.98
<u>CR 41000 BRENTWOOD DR. (Oak Manor) {Minor Collector} 0.9 mi.</u>								
18853	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00
19258	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/8/2017	6/8/2017	\$0.00
19625	Patched - road surface	\$0.00	0.00	\$0.00		8/11/2017	8/11/2017	\$0.00
19781	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 41001 BRENTWOOD CIRCLE (Oak Manor) 0.3 mi.</u>								
19259	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/8/2017	6/8/2017	\$0.00
19780	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 41002 RANCH ROAD (Oak Manor) 0.6 mi.</u>								
18878	Patched - road surface	\$42.25	2.00	\$24.35	\$61.95	1/30/2017	1/30/2017	\$128.55
19248	Mow Right-of-Way					6/2/2017	6/2/2017	\$0.00
19782	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00
20041	Patched - road surface	\$84.50	4.00	\$39.50	\$30.38	12/4/2017	12/4/2017	\$154.38
		<u>\$126.75</u>	<u>6.00</u>	<u>\$63.85</u>	<u>\$92.33</u>			<u>\$282.93</u>
<u>CR 4101 PERRY (ext 4117) 0.4 mi.</u>								
19533	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4102 BUD JONES (ext 4117) 0.4 mi.</u>								
19796	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		9/5/2017	9/5/2017	\$989.52
		<u>\$848.00</u>	<u>8.00</u>	<u>\$141.52</u>				<u>\$989.52</u>
<u>CR 4103 (ext 4102) 0.1 mi.</u>								
19534	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4104 ATWOOD-A (Off 155) 0.3 mi.</u>								
19427	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 41100 WAGONTREE TRAIL {Minor Collector} 0.6 mi.</u>								
18847	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00
19624	Patched - road surface	\$0.00	0.00	\$0.00		8/11/2017	8/11/2017	\$0.00
19783	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/31/2017	8/31/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 41101 BROKENSPOKE (Wagontree) 0.2 mi.</u>								
18848	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 41102 SINGLETREE (Wagontree) 0.6 mi.</u>								
18849	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 41102 SINGLETREE (Wagontree) 0.6 mi.</u>								
19286	Patched - road surface	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
19357	Patch- FALL IN	\$0.00	0.00	\$0.00	\$0.00	7/3/2017	7/3/2017	\$0.00
19558	Patched - road surface	\$42.25	2.00	\$19.75	\$63.13	7/31/2017	7/31/2017	\$125.13
		<u>\$42.25</u>	<u>2.00</u>	<u>\$19.75</u>	<u>\$63.13</u>			<u>\$125.13</u>
<u>CR 41103 SETTLERS LOOP (Wagontree) 0.4 mi.</u>								
18850	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00
18858	Repaired washout	\$235.12	4.00	\$77.66	\$64.79	1/25/2017	1/25/2017	\$377.57
		<u>\$235.12</u>	<u>4.00</u>	<u>\$77.66</u>	<u>\$64.79</u>			<u>\$377.57</u>
<u>CR 41105 LAND GRANT (Wagontree) {Minor Collector} 1.1 mi.</u>								
18851	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00
19076	Driveway culvert - installed/set	\$578.75	10.00	\$194.15	\$325.00	4/7/2017	4/7/2017	\$1,097.90
19557	Patched - road surface	\$42.25	2.00	\$19.75	\$63.13	7/31/2017	7/31/2017	\$125.13
		<u>\$621.00</u>	<u>12.00</u>	<u>\$213.90</u>	<u>\$388.13</u>			<u>\$1,223.03</u>
<u>CR 41106 DOUBLETREE (Wagontree) 0.1 mi.</u>								
18852	Patched - road surface	\$0.00	0.00	\$0.00		1/25/2017	1/25/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 41107 MILL RUN RD (35 MPH) 3.7 mi.</u>								
18910	Patch- FALL IN	\$42.25	2.00	\$24.35	\$14.75	2/8/2017	2/8/2017	\$81.35
19048	Patch- FALL IN	\$84.50	4.00	\$48.70	\$118.00	3/27/2017	3/27/2017	\$251.20
19056	Cleared debris or fallen tree	\$462.48	7.50	\$137.89		3/29/2017	3/29/2017	\$600.37
19073	Patched - road surface	\$84.50	4.00	\$48.70	\$118.00	4/3/2017	4/3/2017	\$251.20
19253	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/6/2017	6/6/2017	\$0.00
19270	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/7/2017	6/7/2017	\$992.32
19271	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/8/2017	6/8/2017	\$992.32
19272	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/9/2017	6/9/2017	\$992.32
19273	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/12/2017	6/12/2017	\$992.32
19274	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/13/2017	6/13/2017	\$992.32
19309	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/14/2017	6/14/2017	\$992.32
19310	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/15/2017	6/15/2017	\$992.32
19326	Stabilized ditch erosion	\$2,964.00	40.00	\$706.80	\$0.00	6/19/2017	6/19/2017	\$3,670.80
19399	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/19/2017	6/19/2017	\$992.32
19327	Stabilized ditch erosion	\$2,340.00	32.00	\$569.76		6/20/2017	6/20/2017	\$2,909.76
19400	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/20/2017	6/20/2017	\$992.32
19328	Asphalt overlay	\$2,101.00	40.00	\$706.80	\$3,216.78	6/21/2017	6/21/2017	\$6,024.58

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 41107 MILL RUN RD (35 MPH) 3.7 mi.</u>								
19401	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/21/2017	6/21/2017	\$992.32
19402	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/22/2017	6/22/2017	\$992.32
19403	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/23/2017	6/23/2017	\$992.32
19331	Asphalt overlay	\$5,820.00	96.00	\$1,567.36	\$41,862.30	6/27/2017	6/27/2017	\$49,249.66
19332	Asphalt overlay	\$5,820.00	104.00	\$1,704.40	\$43,258.86	6/28/2017	6/28/2017	\$50,783.26
19556	Patched - road surface	\$84.50	4.00	\$39.50	\$63.13	7/31/2017	7/31/2017	\$187.13
19699	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19897	Cleared debris or fallen tree	\$353.25	12.00	\$202.12		10/11/2017	10/11/2017	\$555.37
19956	Patched - road surface	\$0.00	0.00	\$0.00	\$61.95	10/23/2017	10/23/2017	\$61.95
		<u>\$30,332.48</u>	<u>441.50</u>	<u>\$7,488.22</u>	<u>\$88,713.77</u>			<u>\$126,534.47</u>
<u>CR 4112 Bacon Bacon 0.4 mi.</u>								
19496	Patched - road surface	\$0.00	0.00	\$0.00	\$23.48	7/20/2017	7/20/2017	\$23.48
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>	<u>\$23.48</u>			<u>\$23.48</u>
<u>CR 41126 LABELLO 0.6 mi.</u>								
20077	Chip Brush w/ Wood Chipper	\$380.00	12.00	\$162.00		12/29/2017	12/29/2017	\$542.00
		<u>\$380.00</u>	<u>12.00</u>	<u>\$162.00</u>				<u>\$542.00</u>
<u>CR 4117 B. VILLE {Minor Collector*} 4.3 mi.</u>								
19107	Cleared debris or fallen tree	\$924.00	16.00	\$285.84		4/27/2017	4/27/2017	\$1,209.84
19240	Patched - road surface	\$42.25	2.00	\$33.64	\$47.55	6/12/2017	6/12/2017	\$123.44
19479	Cut Low Hanging Limbs	\$1,208.00	40.00	\$706.80		7/17/2017	7/17/2017	\$1,914.80
19504	Trimmed brush or trees	\$1,220.00	40.00	\$706.80		7/20/2017	7/20/2017	\$1,926.80
19530	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
19637	Trimmed brush or trees	\$514.50	30.00	\$532.80		8/18/2017	8/18/2017	\$1,047.30
19644	Patch- FALL IN	\$0.00	0.00	\$0.00		8/18/2017	8/18/2017	\$0.00
19681	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		8/21/2017	8/21/2017	\$989.52
19682	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		8/22/2017	8/22/2017	\$989.52
19745	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		8/23/2017	8/23/2017	\$989.52
19746	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		8/25/2017	8/25/2017	\$989.52
19747	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		8/28/2017	8/28/2017	\$989.52
19765	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		9/1/2017	9/1/2017	\$989.52
19874	Patched - road surface	\$84.50	4.00	\$39.50	\$97.94	10/4/2017	10/4/2017	\$221.94
19939	Cleaned ditches	\$1,880.00	40.00	\$665.28		10/24/2017	10/24/2017	\$2,545.28
19940	Cleaned ditches	\$1,463.60	40.00	\$665.28		10/25/2017	10/25/2017	\$2,128.88
		<u>\$12,424.85</u>	<u>260.00</u>	<u>\$4,485.06</u>	<u>\$145.49</u>			<u>\$17,055.40</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4117A KIETH LN (ext 4117)</u>								
19531	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4117B KEVIN CIRCLE (ext 4117) 0.6 mi.</u>								
19532	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4119 COFFEE CITY LANDING 0.8 mi.</u>								
19425	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19797	Road surface repair	\$311.00	6.00	\$110.32		9/6/2017	9/6/2017	\$421.32
19815	Asphalt overlay	\$3,694.00	56.00	\$978.96		9/14/2017	9/14/2017	\$4,672.96
19814	Asphalt overlay	\$3,694.00	56.00	\$978.96		9/15/2017	9/15/2017	\$4,672.96
		\$7,699.00	118.00	\$2,068.24				\$9,767.24
<u>CR 4120 ATWOOD-B (Off 155) 0.5 mi.</u>								
19428	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19764	Bladed - road surface	\$390.50	6.00	\$99.52	\$450.00	9/1/2017	9/1/2017	\$940.02
		\$390.50	6.00	\$99.52	\$450.00			\$940.02
<u>CR 41201 OAKTREE Dr. (Dogwood)</u>								
18807	Patched - around mailboxes	\$169.00	8.00	\$97.40	\$396.00	1/12/2017	1/12/2017	\$662.40
		\$169.00	8.00	\$97.40	\$396.00			\$662.40
<u>CR 41511 (Larry Anding) 1.2 mi.</u>								
18919	Inquiry about road status	\$79.25	3.00	\$59.55		2/9/2017	2/9/2017	\$138.80
19000	Cleaned outfall ditch	\$408.75	6.00	\$114.09		3/2/2017	3/2/2017	\$522.84
19002	Driveway culvert - reset	\$413.25	12.00	\$228.18	\$232.94	3/3/2017	3/3/2017	\$874.37
19025	Patched - road surface	\$84.50	4.00	\$48.70	\$271.50	3/17/2017	3/17/2017	\$404.70
19257	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/8/2017	6/8/2017	\$0.00
19408	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/30/2017	6/30/2017	\$992.32
19779	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00
20039	Patched - road surface	\$84.50	4.00	\$39.50	\$30.38	12/4/2017	12/4/2017	\$154.38
		\$1,918.25	37.00	\$634.34	\$534.82			\$3,087.41
<u>CR 41512 RYAN 0.7 mi.</u>								
18945	Patched - road surface	\$84.50	4.00	\$48.70	\$177.00	2/15/2017	2/15/2017	\$310.20
19255	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/7/2017	6/7/2017	\$0.00
19359	Patched - road surface	\$0.00	0.00	\$0.00	\$61.36	7/3/2017	7/3/2017	\$61.36
19778	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		\$84.50	4.00	\$48.70	\$238.36			\$371.56

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 41513 0.7 mi.</u>								
19254	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/7/2017	6/7/2017	\$0.00
19360	Patched - road surface	\$0.00	0.00	\$0.00	\$61.36	7/3/2017	7/3/2017	\$61.36
19741	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
20040	Patched - road surface	\$84.50	4.00	\$39.50	\$30.38	12/4/2017	12/4/2017	\$154.38
		<u>\$84.50</u>	<u>4.00</u>	<u>\$39.50</u>	<u>\$91.74</u>			<u>\$215.74</u>
<u>CR 41514 1.5 mi.</u>								
18946	Patched - road surface	\$42.25	2.00	\$24.35	\$37.17	2/15/2017	2/15/2017	\$103.77
19256	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/7/2017	6/7/2017	\$0.00
19355	Cleared debris or fallen tree	\$155.00	6.00	\$171.76		7/1/2017	7/1/2017	\$326.76
19361	Patched - road surface	\$0.00	0.00	\$0.00	\$61.36	7/3/2017	7/3/2017	\$61.36
19777	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		<u>\$197.25</u>	<u>8.00</u>	<u>\$196.11</u>	<u>\$98.53</u>			<u>\$491.89</u>
<u>CR 41515 McGEE NURSEY 0.2 mi.</u>								
18818	Clean Culvert/Beaver Dam	\$259.40	4.00	\$77.66		1/17/2017	1/17/2017	\$337.06
18857	Repaired washout	\$290.25	4.00	\$77.66	\$64.79	1/25/2017	1/25/2017	\$432.70
18999	Clean Culvert/Beaver Dam	\$272.50	4.00	\$76.06		3/2/2017	3/2/2017	\$348.56
19261	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/8/2017	6/8/2017	\$0.00
19606	Road culvert - replaced	\$958.00	24.00	\$441.28	\$139.65	8/14/2017	8/14/2017	\$1,538.93
19784	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/31/2017	8/31/2017	\$0.00
19925	Clean Culvert/Beaver Dam (needs more work)	\$545.00	8.00	\$120.76		10/18/2017	10/18/2017	\$665.76
19936	Clean Culvert/Beaver Dam	\$272.50	6.00	\$107.06		10/23/2017	10/23/2017	\$379.56
20038	Patched - road surface	\$84.50	4.00	\$39.50	\$30.38	12/4/2017	12/4/2017	\$154.38
		<u>\$2,682.15</u>	<u>54.00</u>	<u>\$939.98</u>	<u>\$234.82</u>			<u>\$3,856.95</u>
<u>CR 41516 DOUGLAS DRIVE 0.7 mi.</u>								
18947	Patched - road surface	\$42.25	2.00	\$24.35	\$59.00	2/15/2017	2/15/2017	\$125.60
19260	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/8/2017	6/8/2017	\$0.00
19786	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/31/2017	8/31/2017	\$0.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$24.35</u>	<u>\$59.00</u>			<u>\$125.60</u>
<u>CR 41518 (EXT. Douglas)</u>								
18953	Patched - road surface	\$42.25	2.00	\$24.35	\$66.23	2/17/2017	2/17/2017	\$132.83
19785	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/31/2017	8/31/2017	\$0.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$24.35</u>	<u>\$66.23</u>			<u>\$132.83</u>
<u>CR 4200 (Road Closed)</u>								
19523	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4200 (Road Closed)</u>								
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4201 SUNRISE (off 315) {Minor Collector} 1 mi.</u>								
18827	Chip Brush w/ Wood Chipper	\$1,608.00	24.00	\$336.32		1/18/2017	1/18/2017	\$1,944.32
18828	Chip Brush w/ Wood Chipper	\$1,608.00	24.00	\$454.96		1/20/2017	1/20/2017	\$2,062.96
18838	Patched - road surface	\$42.25	2.00	\$24.35	\$73.34	1/23/2017	1/23/2017	\$139.94
19219	Cleaned outfall ditch	\$618.00	24.00	\$445.76		5/24/2017	5/24/2017	\$1,063.76
19436	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19587	Trimmed brush or trees	\$402.00	8.00	\$90.08		8/8/2017	8/8/2017	\$492.08
		\$4,278.25	82.00	\$1,351.47	\$73.34			\$5,703.06
<u>CR 4201A CHEROKEE Dr. (Cherokee) 1.4 mi.</u>								
18839	Patched - road surface	\$42.25	2.00	\$24.35	\$73.34	1/23/2017	1/23/2017	\$139.94
19113	Patched - road surface	\$0.00	0.00	\$0.00		4/28/2017	4/28/2017	\$0.00
19437	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19618	Patched - road surface	\$0.00	0.00	\$0.00		8/10/2017	8/10/2017	\$0.00
		\$42.25	2.00	\$24.35	\$73.34			\$139.94
<u>CR 4201B Sunbird Dr. (Cherokee)</u>								
18840	Patched - road surface	\$21.12	1.00	\$12.17	\$73.34	1/23/2017	1/23/2017	\$106.63
19112	Patched - road surface	\$0.00	0.00	\$0.00		4/28/2017	4/28/2017	\$0.00
19438	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19619	Patched - road surface	\$0.00	0.00	\$0.00		8/10/2017	8/10/2017	\$0.00
		\$21.12	1.00	\$12.17	\$73.34			\$106.63
<u>CR 4201C Tomahawk Dr. (Cherokee)</u>								
18841	Patched - road surface	\$21.12	1.00	\$12.17	\$73.34	1/23/2017	1/23/2017	\$106.63
19439	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19620	Patched - road surface	\$0.00	0.00	\$0.00		8/10/2017	8/10/2017	\$0.00
		\$21.12	1.00	\$12.17	\$73.34			\$106.63
<u>CR 4201D Arrowhead Dr. (Cherokee)</u>								
19440	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19621	Patched - road surface	\$0.00	0.00	\$0.00		8/10/2017	8/10/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4201E Ridge Rd. (Woodridge)</u>								
19441	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19997	Patched - road surface	\$42.25	2.00	\$19.75	\$59.00	11/9/2017	11/9/2017	\$121.00
		\$42.25	2.00	\$19.75	\$59.00			\$121.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4201F Quil Cutoff (Woodridge)</b>								
19442	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19998	Patched - road surface	\$42.25	2.00	\$19.75	\$59.00	11/9/2017	11/9/2017	\$121.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$19.75</u>	<u>\$59.00</u>			<u>\$121.00</u>
<b>CR 4201G Hillcrest (Woodridge)</b>								
19443	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19999	Patched - road surface	\$42.25	2.00	\$19.75	\$29.50	11/9/2017	11/9/2017	\$91.50
		<u>\$42.25</u>	<u>2.00</u>	<u>\$19.75</u>	<u>\$29.50</u>			<u>\$91.50</u>
<b>CR 4201H Pineview (Woodridge)</b>								
19444	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
20000	Patched - road surface	\$42.25	2.00	\$19.75	\$29.50	11/9/2017	11/9/2017	\$91.50
		<u>\$42.25</u>	<u>2.00</u>	<u>\$19.75</u>	<u>\$29.50</u>			<u>\$91.50</u>
<b>CR 4202 CAPE (off FM 3506) 1.5 mi.</b>								
18823	Trash/garbage picked-up	\$211.25	10.00	\$121.75		1/17/2017	1/17/2017	\$333.00
18842	Patched - road surface	\$21.12	1.00	\$12.17	\$73.34	1/23/2017	1/23/2017	\$106.63
19111	Patched - road surface	\$0.00	0.00	\$0.00		4/28/2017	4/28/2017	\$0.00
19422	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
20037	Patched - road surface	\$84.50	6.00	\$54.00	\$63.72	12/1/2017	12/1/2017	\$202.22
		<u>\$316.87</u>	<u>17.00</u>	<u>\$187.92</u>	<u>\$137.06</u>			<u>\$641.85</u>
<b>CR 4213 TWIN OAKS (off FM 315) 1 mi.</b>								
19214	Patched - road surface	\$84.50	2.00	\$42.28	\$44.25	5/24/2017	5/24/2017	\$171.03
20036	Patched - road surface	\$126.75	9.00	\$81.00	\$118.00	12/1/2017	12/1/2017	\$325.75
		<u>\$211.25</u>	<u>11.00</u>	<u>\$123.28</u>	<u>\$162.25</u>			<u>\$496.78</u>
<b>CR 4213A Post Oak (Twin Oaks)</b>								
19811	Oil Sand Overlay	\$2,182.00	32.00	\$567.20	\$3,771.28	9/11/2017	9/11/2017	\$6,520.48
		<u>\$2,182.00</u>	<u>32.00</u>	<u>\$567.20</u>	<u>\$3,771.28</u>			<u>\$6,520.48</u>
<b>CR 4215 WELDER (ext 4224) 0.4 mi.</b>								
18796	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/9/2017	1/9/2017	\$992.32
18806	/ Repair Sink Hole	\$670.25	16.00	\$310.64		1/12/2017	1/12/2017	\$980.89
		<u>\$1,518.25</u>	<u>24.00</u>	<u>\$454.96</u>				<u>\$1,973.21</u>
<b>CR 4216 Old Caney Rd (ext. off old 4200) 0.2 mi.</b>								
19423	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19529	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/21/2017	7/21/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>



ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4217 MANOY (Pleasant Ridge) 4.3 mi.</b>								
19043	Blade- Patch road surface / from 4200 to 4232	\$2,342.00	40.00	\$751.92	\$7,014.54	3/23/2017	3/23/2017	\$10,108.46
19044	Asphalt overlay / Culvert @ Highsaw Inlet	\$1,756.50	30.00	\$563.94	\$5,285.40	3/24/2017	3/24/2017	\$7,605.84
19160	Asphalt overlay	\$885.00	16.00	\$291.40	\$1,466.25	5/15/2017	5/15/2017	\$2,642.65
19245	Road culvert - replaced	\$1,032.00	32.00	\$582.80	\$489.25	6/8/2017	6/8/2017	\$2,104.05
19246	Road culvert - replaced	\$1,350.00	50.00	\$1,033.86	\$5,950.00	6/9/2017	6/9/2017	\$8,333.86
19247	Road culvert - replaced	\$1,124.00	24.00	\$445.76	\$491.91	6/12/2017	6/12/2017	\$2,061.67
19306	Stabilized ditch erosion	\$1,868.00	24.00	\$445.76		6/14/2017	6/14/2017	\$2,313.76
19307	Stabilized ditch erosion	\$1,868.00	24.00	\$445.76		6/15/2017	6/15/2017	\$2,313.76
19308	Asphalt overlay	\$1,199.00	24.00	\$445.76		6/16/2017	6/16/2017	\$1,644.76
19315	Asphalt overlay	\$1,559.75	24.00	\$445.76	\$4,422.90	6/16/2017	6/16/2017	\$6,428.41
19469	Patched - road surface	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00
19521	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19511	Moved equipment to work site	\$1,570.00	24.00	\$441.28		7/24/2017	7/24/2017	\$2,011.28
19512	Road culvert - replaced	\$1,080.00	24.00	\$441.28	\$10,460.00	7/25/2017	7/25/2017	\$11,981.28
19513	Road culvert - replaced	\$1,080.00	24.00	\$441.28		7/26/2017	7/26/2017	\$1,521.28
19763	Asphalt overlay	\$781.00	12.00	\$199.04	\$2,908.35	9/1/2017	9/1/2017	\$3,888.39
19902	Patched - road surface	\$0.00	0.00	\$0.00		10/10/2017	10/10/2017	\$0.00
19918	Remove Dead Tree	\$878.25	24.00	\$428.24		10/16/2017	10/16/2017	\$1,306.49
		<u>\$20,373.50</u>	<u>396.00</u>	<u>\$7,403.84</u>	<u>\$38,488.60</u>			<u>\$66,265.94</u>
<b>CR 4218 STEVENSON (Off 4217) 1.2 mi.</b>								
19522	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19888	Driveway culvert - installed/set	\$790.00	24.00	\$398.08	\$325.00	9/18/2017	9/18/2017	\$1,513.08
19812	Asphalt overlay	\$3,694.00	56.00	\$986.24		9/19/2017	9/19/2017	\$4,680.24
19813	Asphalt overlay	\$2,372.50	36.00	\$631.44		9/20/2017	9/20/2017	\$3,003.94
		<u>\$6,856.50</u>	<u>116.00</u>	<u>\$2,015.76</u>	<u>\$325.00</u>			<u>\$9,197.26</u>
<b>CR 4220 DIXON (ext off 4221) 0.3 mi.</b>								
19094	Patched - road surface	\$42.25	2.00	\$24.35	\$59.00	4/24/2017	4/24/2017	\$125.60
		<u>\$42.25</u>	<u>2.00</u>	<u>\$24.35</u>	<u>\$59.00</u>			<u>\$125.60</u>
<b>CR 4221 PINE SPRINGS (ext off 4222) 1.5 mi.</b>								
18831	Trash/garbage picked-up	\$38.90	4.00	\$48.70		1/20/2017	1/20/2017	\$87.60
19095	Patched - road surface	\$84.50	4.00	\$48.70	\$59.00	4/24/2017	4/24/2017	\$192.20
19224	Patched - road surface	\$42.25	2.00	\$38.83	\$44.99	5/30/2017	5/30/2017	\$126.07
19498	Patched - road surface	\$0.00	0.00	\$0.00	\$23.48	7/20/2017	7/20/2017	\$23.48
		<u>\$165.65</u>	<u>10.00</u>	<u>\$136.23</u>	<u>\$127.47</u>			<u>\$429.35</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4222 KENNEDY CORNER (45 MPH) 0.7 mi.</u>								
18832	Trash/garbage picked-up	\$38.90	4.00	\$48.70		1/20/2017	1/20/2017	\$87.60
18886	Patch- FALL IN	\$21.12	1.00	\$12.17	\$5.90	2/1/2017	2/1/2017	\$39.19
18964	Patched - road surface	\$42.25	2.00	\$24.35	\$68.59	2/21/2017	2/21/2017	\$135.19
19096	Patched - road surface	\$42.25	2.00	\$24.35	\$29.50	4/24/2017	4/24/2017	\$96.10
19429	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19499	Patched - road surface	\$0.00	0.00	\$0.00	\$23.48	7/20/2017	7/20/2017	\$23.48
19901	Patched - road surface	\$0.00	0.00	\$0.00		10/10/2017	10/10/2017	\$0.00
		\$144.52	9.00	\$109.57	\$127.47			\$381.56
<u>CR 4223 MAYOR RD (ext 4217) 0.3 mi.</u>								
19903	Patched - road surface	\$0.00	0.00	\$0.00		10/10/2017	10/10/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4224 STELLA WALKER (45 MPH) 9.3 mi.</u>								
18783	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/3/2017	1/3/2017	\$992.32
18789	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/4/2017	1/4/2017	\$992.32
18790	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/5/2017	1/5/2017	\$992.32
18833	Trash/garbage picked-up	\$38.90	4.00	\$48.70		1/20/2017	1/20/2017	\$87.60
18963	Patched - road surface	\$42.25	2.00	\$24.35	\$68.59	2/21/2017	2/21/2017	\$135.19
19010	Moved equipment to work site	\$420.00	8.00	\$152.12		3/14/2017	3/14/2017	\$572.12
19016	Cleaned ditches	\$2,097.00	24.00	\$441.28		3/15/2017	3/15/2017	\$2,538.28
19033	Cleaned ditches	\$1,540.00	24.00	\$441.28		3/15/2017	3/15/2017	\$1,981.28
19031	Cleaned ditches	\$1,540.00	24.00	\$441.28	\$600.00	3/16/2017	3/16/2017	\$2,581.28
19030	Road culvert - installed / Add 10Ft to 48"	\$842.00	24.00	\$441.28	\$483.20	3/17/2017	3/17/2017	\$1,766.48
19029	Other drainage work	\$504.00	16.00	\$304.24		3/20/2017	3/20/2017	\$808.24
19027	Road culvert - replaced	\$2,314.00	40.00	\$751.92	\$5,473.92	3/21/2017	3/21/2017	\$8,539.84
19053	Stabilized ditch erosion	\$217.00	4.00	\$77.18	\$32.50	3/27/2017	3/27/2017	\$326.68
19058	Oil Sand Overlay	\$1,770.00	32.00	\$610.40	\$11,932.48	3/30/2017	3/30/2017	\$14,312.88
19066	Oil Sand Overlay	\$1,150.00	24.00	\$473.36	\$9,519.30	3/31/2017	3/31/2017	\$11,142.66
19159	Asphalt overlay	\$885.00	16.00	\$291.40	\$1,485.57	5/15/2017	5/15/2017	\$2,661.97
19222	Patched - road surface	\$42.25	2.00	\$38.83	\$44.99	5/30/2017	5/30/2017	\$126.07
19524	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19500	Patched - road surface	\$0.00	0.00	\$0.00	\$23.48	7/20/2017	7/20/2017	\$23.48
19526	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/21/2017	7/21/2017	\$0.00
19758	Patched - road surface	\$84.50	4.00	\$39.50	\$59.00	8/30/2017	8/30/2017	\$183.00
19878	Patched - road surface	\$84.50	4.00	\$39.50	\$60.77	10/5/2017	10/5/2017	\$184.77
		\$16,115.40	276.00	\$5,049.58	\$29,783.80			\$50,948.78

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4225 RED FLAT (45 MPH) 2.5 mi.</b>								
18897	Cut Brush/ Brush Cutter	\$742.00	7.00	\$126.28		2/3/2017	2/3/2017	\$868.28
19023	Patched - road surface	\$84.50	4.00	\$48.70	\$150.00	3/17/2017	3/17/2017	\$283.20
19223	Patched - road surface	\$0.00	2.00	\$38.83	\$44.99	5/30/2017	5/30/2017	\$83.82
19453	Patched - road surface	\$126.75	3.00	\$37.50	\$94.10	7/12/2017	7/12/2017	\$258.35
19535	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
19536	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
19759	Patched - road surface	\$84.50	4.00	\$39.50	\$57.23	8/30/2017	8/30/2017	\$181.23
19830	Patched - road surface	\$126.75	6.00	\$59.25		9/27/2017	9/27/2017	\$186.00
		<u>\$1,164.50</u>	<u>26.00</u>	<u>\$350.06</u>	<u>\$346.32</u>			<u>\$1,860.88</u>
<b>CR 4226 ROUND TOP CHURCH 1.4 mi.</b>								
18965	Patched - road surface	\$84.50	4.00	\$48.70	\$68.59	2/21/2017	2/21/2017	\$201.79
19017	Road base material - added	\$904.25	16.00	\$310.64	\$246.24	3/15/2017	3/15/2017	\$1,461.13
19040	Oil Sand Overlay	\$2,342.00	40.00	\$751.92	\$5,797.34	3/22/2017	3/22/2017	\$8,891.26
19052	Road culvert - replaced	\$470.25	8.00	\$154.36	\$599.40	3/27/2017	3/27/2017	\$1,224.01
19497	Patched - road surface	\$0.00	0.00	\$0.00	\$23.48	7/20/2017	7/20/2017	\$23.48
19527	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/21/2017	7/21/2017	\$0.00
		<u>\$3,801.00</u>	<u>68.00</u>	<u>\$1,265.62</u>	<u>\$6,735.05</u>			<u>\$11,801.67</u>
<b>CR 4228 BRUNO 0.2 mi.</b>								
18966	Patched - road surface	\$42.25	2.00	\$24.35	\$68.59	2/21/2017	2/21/2017	\$135.19
19525	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19495	Patched - road surface	\$0.00	0.00	\$0.00	\$23.48	7/20/2017	7/20/2017	\$23.48
		<u>\$42.25</u>	<u>2.00</u>	<u>\$24.35</u>	<u>\$92.07</u>			<u>\$158.67</u>
<b>CR 4229 RYLIE (Off 4226) 0.3 mi.</b>								
19054	Road base material - added	\$2,147.00	32.00	\$582.80	\$1,890.11	3/28/2017	3/28/2017	\$4,619.91
19528	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/21/2017	7/21/2017	\$0.00
		<u>\$2,147.00</u>	<u>32.00</u>	<u>\$582.80</u>	<u>\$1,890.11</u>			<u>\$4,619.91</u>
<b>CR 4231 BETHEL CEMETARY 1 mi.</b>								
19354	Patched - road surface	\$84.50	4.00	\$67.28	\$65.49	6/30/2017	6/30/2017	\$217.27
19380	Patched - road surface	\$126.75	3.00	\$37.50	\$106.20	7/5/2017	7/5/2017	\$270.45
19650	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
20031	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		12/4/2017	12/4/2017	\$989.52
20030	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		12/5/2017	12/5/2017	\$989.52
20032	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		12/6/2017	12/6/2017	\$989.52
		<u>\$2,755.25</u>	<u>31.00</u>	<u>\$529.34</u>	<u>\$171.69</u>			<u>\$3,456.28</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4233 NEWMAN (ext 4235) 1.5 mi.</b>								
18956	Patched - road surface	\$84.50	4.00	\$48.70	\$66.23	2/17/2017	2/17/2017	\$199.43
18961	Cleared debris or fallen tree	\$838.85	24.00	\$454.96		2/21/2017	2/21/2017	\$1,293.81
19541	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/26/2017	7/26/2017	\$0.00
19584	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/31/2017	7/31/2017	\$992.32
19583	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		8/2/2017	8/2/2017	\$992.32
19582	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		8/4/2017	8/4/2017	\$992.32
19581	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		8/7/2017	8/7/2017	\$992.32
19591	Driveway culvert - installed/set	\$583.00	12.00	\$199.04	\$114.76	8/9/2017	8/9/2017	\$896.80
19595	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		8/9/2017	8/9/2017	\$992.32
19823	Patched - road surface	\$84.50	4.00	\$39.50	\$88.50	9/21/2017	9/21/2017	\$212.50
		<u>\$5,830.85</u>	<u>84.00</u>	<u>\$1,463.80</u>	<u>\$269.49</u>			<u>\$7,564.14</u>
<b>CR 4234</b>								
19869	Put up 'Stop' sign	\$19.45	1.00	\$18.04		10/4/2017	10/4/2017	\$37.49
		<u>\$19.45</u>	<u>1.00</u>	<u>\$18.04</u>				<u>\$37.49</u>
<b>CR 4235 JOHN'S (35 MPH) 2.6 mi.</b>								
18955	Patched - road surface	\$84.50	4.00	\$48.70	\$66.23	2/17/2017	2/17/2017	\$199.43
19036	Road culvert - Stabilize	\$904.25	16.00	\$310.64	\$97.50	3/17/2017	3/17/2017	\$1,312.39
19537	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
19540	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/26/2017	7/26/2017	\$0.00
19824	Patched - road surface	\$84.50	4.00	\$39.50	\$29.50	9/21/2017	9/21/2017	\$153.50
19827	Patched - road surface	\$253.50	12.00	\$118.50	\$178.18	9/26/2017	9/26/2017	\$550.18
19831	Patched - road surface	\$126.75	6.00	\$59.25		9/27/2017	9/27/2017	\$186.00
19907	Cleaned ditches	\$2,035.60	40.00	\$665.28		10/12/2017	10/12/2017	\$2,700.88
19908	Cleaned ditches	\$1,463.60	32.00	\$498.08		10/13/2017	10/13/2017	\$1,961.68
19992	Cleaned outfall ditch	\$676.00	15.00	\$233.80		11/13/2017	11/13/2017	\$909.80
		<u>\$5,628.70</u>	<u>129.00</u>	<u>\$1,973.75</u>	<u>\$371.41</u>			<u>\$7,973.86</u>
<b>CR 4236 DANSBY (ext 4235) 1.3 mi.</b>								
18815	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/12/2017	1/12/2017	\$992.32
18814	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/13/2017	1/13/2017	\$992.32
18865	Patched - road surface	\$126.75	6.00	\$73.05	\$177.00	1/26/2017	1/26/2017	\$376.80
19121	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19234	Cleared debris or fallen tree	\$239.50	6.00	\$111.44		6/6/2017	6/6/2017	\$350.94
19538	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
19638	Patched - road surface	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
19876	Patched - road surface	\$84.50	4.00	\$39.50	\$60.77	10/5/2017	10/5/2017	\$184.77
		<u>\$2,146.75</u>	<u>32.00</u>	<u>\$512.63</u>	<u>\$237.77</u>			<u>\$2,897.15</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4237 UNDERWOOD (ext ACR 300-303) 0.4 mi.</u>								
18954	Patched - road surface	\$84.50	4.00	\$48.70	\$66.23	2/17/2017	2/17/2017	\$199.43
18962	Road surface repair	\$756.25	12.00	\$227.48	\$234.00	2/22/2017	2/22/2017	\$1,217.73
19007	Asphalt overlay 50ft repaired section	\$470.25	8.00	\$155.32	\$682.63	3/10/2017	3/10/2017	\$1,308.20
19539	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/25/2017	7/25/2017	\$0.00
		<u>\$1,311.00</u>	<u>24.00</u>	<u>\$431.50</u>	<u>\$982.86</u>			<u>\$2,725.36</u>
<u>CR 4238 (off FM 315) 0.4 mi.</u>								
19426	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19657	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4239 BOLES 0.5 mi.</u>								
19821	Patched - road surface	\$169.00	8.00	\$79.00	\$129.21	9/18/2017	9/18/2017	\$377.21
19875	Patched - road surface	\$84.50	4.00	\$39.50	\$88.50	10/4/2017	10/4/2017	\$212.50
		<u>\$253.50</u>	<u>12.00</u>	<u>\$118.50</u>	<u>\$217.71</u>			<u>\$589.71</u>
<u>CR 4300 BELL (off FM 314) 1.2 mi.</u>								
19217	Patched - road surface	\$169.00	4.00	\$84.56	\$93.22	5/25/2017	5/25/2017	\$346.78
		<u>\$169.00</u>	<u>4.00</u>	<u>\$84.56</u>	<u>\$93.22</u>			<u>\$346.78</u>
<u>CR 4303 GENE LINSEY (off 314)</u>								
19486	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
20027	Patched - road surface	\$84.50	2.00	\$25.00	\$59.00	11/30/2017	11/30/2017	\$168.50
		<u>\$84.50</u>	<u>2.00</u>	<u>\$25.00</u>	<u>\$59.00</u>			<u>\$168.50</u>
<u>CR 4304 LONE STAR (off FM 314) 2.2 mi.</u>								
18813	Remove Dead Tree	\$696.25	40.00	\$751.92		1/13/2017	1/13/2017	\$1,448.17
19218	Patched - road surface	\$169.00	4.00	\$84.56	\$88.50	5/25/2017	5/25/2017	\$342.06
19546	Patched - road surface	\$84.50	2.00	\$25.00	\$50.74	7/25/2017	7/25/2017	\$160.24
		<u>\$949.75</u>	<u>46.00</u>	<u>\$861.48</u>	<u>\$139.24</u>			<u>\$1,950.47</u>
<u>CR 4305N C. HARMON (ext 4304) 1.6 mi.</u>								
18909	Patched - road surface	\$0.00	0.00	\$0.00	\$40.30	2/7/2017	2/7/2017	\$40.30
19489	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19544	Patched - road surface	\$84.50	2.00	\$25.00	\$50.74	7/25/2017	7/25/2017	\$160.24
		<u>\$84.50</u>	<u>2.00</u>	<u>\$25.00</u>	<u>\$91.04</u>			<u>\$200.54</u>
<u>CR 4305S HIGHTOWER (ext 4304) 0.6 mi.</u>								
19545	Patched - road surface	\$84.50	2.00	\$25.00	\$50.74	7/25/2017	7/25/2017	\$160.24
		<u>\$84.50</u>	<u>2.00</u>	<u>\$25.00</u>	<u>\$50.74</u>			<u>\$160.24</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4307 GUSSIE LEE (35 MPH) {Minor Collector} 3.1 mi.</u>								
18916	Inquiry about road status	\$19.45	2.00	\$42.42		2/6/2017	2/6/2017	\$61.87
18906	Patched - road surface	\$0.00	0.00	\$0.00	\$40.30	2/7/2017	2/7/2017	\$40.30
19119	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19225	Road culvert - replaced	\$1,050.25	24.00	\$441.28	\$1,619.70	5/30/2017	5/30/2017	\$3,111.23
19226	Driveway entrance - repaired	\$512.25	12.00	\$220.64		5/31/2017	5/31/2017	\$732.89
19430	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19617	Patched - road surface	\$0.00	0.00	\$0.00		8/10/2017	8/10/2017	\$0.00
19802	Blade- Patch road surface	\$1,562.00	24.00	\$398.08	\$4,350.45	9/7/2017	9/7/2017	\$6,310.53
19844	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/28/2017	9/28/2017	\$0.00
19840	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/2/2017	10/2/2017	\$989.52
19838	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/3/2017	10/3/2017	\$989.52
20022	Patched - road surface	\$0.00	0.00	\$0.00		11/29/2017	11/29/2017	\$0.00
		<u>\$4,839.95</u>	<u>78.00</u>	<u>\$1,385.46</u>	<u>\$6,010.45</u>			<u>\$12,235.86</u>
<u>CR 4308 STEVE (off 4305 N) 0.3 mi.</u>								
18835	Road surface repair	\$353.25	8.00	\$152.12	\$125.00	1/23/2017	1/23/2017	\$630.37
19488	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
		<u>\$353.25</u>	<u>8.00</u>	<u>\$152.12</u>	<u>\$125.00</u>			<u>\$630.37</u>
<u>CR 4309 LIVE COVE (off 4307) 0.2 mi.</u>								
20023	Patched - road surface	\$0.00	0.00	\$0.00		11/29/2017	11/29/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4310 FGS Pinewood Trail</u>								
18907	Patched - road surface	\$0.00	0.00	\$0.00	\$40.30	2/7/2017	2/7/2017	\$40.30
19215	Patched - road surface	\$84.50	2.00	\$42.28	\$59.00	5/24/2017	5/24/2017	\$185.78
19285	Patched - road surface	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
19432	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
		<u>\$84.50</u>	<u>2.00</u>	<u>\$42.28</u>	<u>\$99.30</u>			<u>\$226.08</u>
<u>CR 4311 FGS Pineview Trail 0.6 mi.</u>								
19433	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4312 FGS Pinewilde Rd. 1 mi.</u>								
19434	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
20069	Patched - road surface	\$169.00	12.00	\$162.00	\$122.13	12/21/2017	12/21/2017	\$453.13
		<u>\$169.00</u>	<u>12.00</u>	<u>\$162.00</u>	<u>\$122.13</u>			<u>\$453.13</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4313 (ext 4307) PINECREST</b>								
19221	Patched - road surface	\$42.25	2.00	\$38.83	\$44.99	5/30/2017	5/30/2017	\$126.07
19435	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
		\$42.25	2.00	\$38.83	\$44.99			\$126.07
<b>CR 4314 (ext 4307) 0.2 mi.</b>								
19431	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4316 EULESS WARREN (ext 4307) 0.6 mi.</b>								
18908	Patched - road surface	\$0.00	0.00	\$0.00	\$40.30	2/7/2017	2/7/2017	\$40.30
19616	Patched - road surface	\$0.00	0.00	\$0.00		8/10/2017	8/10/2017	\$0.00
19843	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/28/2017	9/28/2017	\$0.00
		\$0.00	0.00	\$0.00	\$40.30			\$40.30
<b>CR 4317A MOORE STA. LOOP 0.2 mi.</b>								
19653	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
19842	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/29/2017	9/29/2017	\$0.00
20003	Cleaned ditches	\$1,880.00	40.00	\$641.28		11/17/2017	11/17/2017	\$2,521.28
20024	Patched - road surface	\$0.00	0.00	\$0.00		11/29/2017	11/29/2017	\$0.00
20026	Patched - road surface	\$84.50	2.00	\$25.00	\$59.00	11/30/2017	11/30/2017	\$168.50
		\$1,964.50	42.00	\$666.28	\$59.00			\$2,689.78
<b>CR 4317B HOE HANDLE 2 mi.</b>								
19654	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
19841	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/29/2017	9/29/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4318 (off 4319)</b>								
19485	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4319 FED'S {Minor Collector} 2.5 mi.</b>								
18905	Patched - road surface	\$0.00	0.00	\$0.00	\$40.30	2/7/2017	2/7/2017	\$40.30
19117	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19213	Patched - road surface	\$84.50	2.00	\$42.28	\$59.00	5/24/2017	5/24/2017	\$185.78
19487	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19633	Cleared debris or fallen tree	\$349.50	9.00	\$165.48		8/16/2017	8/16/2017	\$514.98
19646	Patched - road surface	\$0.00	0.00	\$0.00		8/18/2017	8/18/2017	\$0.00
19890	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/4/2017	10/4/2017	\$989.52
19892	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/5/2017	10/5/2017	\$989.52

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4319 FED'S {Minor Collector} 2.5 mi.</b>								
19891	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/6/2017	10/6/2017	\$989.52
19893	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/9/2017	10/9/2017	\$989.52
19898	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/11/2017	10/11/2017	\$989.52
19910	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/12/2017	10/12/2017	\$989.52
19912	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/13/2017	10/13/2017	\$989.52
		\$6,370.00	67.00	\$1,198.40	\$99.30			\$7,667.70
<b>CR 4320 CUMBY 0.3 mi.</b>								
19484	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00
19655	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4321 PRESSWOOD 0.4 mi.</b>								
19656	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4322 TIP TOP 0.3 mi.</b>								
19353	Patched - road surface	\$84.50	4.00	\$67.28	\$65.49	6/30/2017	6/30/2017	\$217.27
19592	Driveway culvert - installed/set	\$233.00	6.00	\$99.52		8/9/2017	8/9/2017	\$332.52
19651	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
20025	Patched - road surface	\$84.50	2.00	\$25.00	\$83.19	11/30/2017	11/30/2017	\$192.69
		\$402.00	12.00	\$191.80	\$148.68			\$742.48
<b>CR 4323 STREETS (off FM 315) 0.2 mi.</b>								
19652	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
19645	Patched - road surface	\$0.00	0.00	\$0.00		8/18/2017	8/18/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4325 N.Y.- MOORE STATION {Minor Collector} 6.8 mi.</b>								
18860	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/23/2017	1/23/2017	\$992.32
18862	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		1/25/2017	1/25/2017	\$992.32
18893	Patched - road surface	\$126.75	6.00	\$73.05	\$147.50	2/3/2017	2/3/2017	\$347.30
18902	Patched - road surface	\$0.00	0.00	\$0.00	\$63.28	2/6/2017	2/6/2017	\$63.28
18904	Patched - road surface	\$0.00	0.00	\$0.00	\$40.30	2/7/2017	2/7/2017	\$40.30
18937	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		2/13/2017	2/13/2017	\$992.32
18986	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		2/27/2017	2/27/2017	\$992.32
18989	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		2/28/2017	2/28/2017	\$992.32
19012	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		3/13/2017	3/13/2017	\$992.32
19013	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		3/14/2017	3/14/2017	\$992.32



ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4325 N.Y. - MOORE STATION {Minor Collector} 6.8 mi.</u>								
19018	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		3/15/2017	3/15/2017	\$992.32
19028	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		3/21/2017	3/21/2017	\$992.32
19116	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19446	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19483	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00
19649	Patched - road surface	\$0.00	0.00	\$0.00		8/21/2017	8/21/2017	\$0.00
19705	Patched - road surface	\$126.75	6.00	\$59.25	\$88.79	8/23/2017	8/23/2017	\$274.79
19867	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/8/2017	9/8/2017	\$0.00
19877	Patched - road surface	\$84.50	4.00	\$39.50	\$60.77	10/5/2017	10/5/2017	\$184.77
20071	Patch- FALL IN	\$610.00	12.00	\$162.00	\$100.00	12/26/2017	12/26/2017	\$872.00
		\$8,580.00	100.00	\$1,632.68	\$500.64			\$10,713.32
<u>CR 4328 TROY CROSSLEY (35 MPH) 3.2 mi.</u>								
18891	Patched - road surface	\$338.00	16.00	\$194.80	\$250.16	2/2/2017	2/2/2017	\$782.96
18903	Patched - road surface	\$0.00	0.00	\$0.00	\$63.28	2/6/2017	2/6/2017	\$63.28
19118	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19202	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/3/2017	5/3/2017	\$0.00
19553	Patched - road surface	\$126.75	6.00	\$59.25	\$70.51	7/28/2017	7/28/2017	\$256.51
19799	Patched - road surface	\$84.50	4.00	\$39.50	\$77.88	9/6/2017	9/6/2017	\$201.88
19805	Mow Right-of-Way	\$0.00	4.00	\$50.00		9/7/2017	9/7/2017	\$50.00
		\$549.25	30.00	\$343.55	\$461.83			\$1,354.63
<u>CR 4329 (off 4325) 0.3 mi.</u>								
19445	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/12/2017	7/12/2017	\$0.00
19607	Bladed - road surface	\$706.50	12.00	\$205.56		8/11/2017	8/11/2017	\$912.06
		\$706.50	12.00	\$205.56				\$912.06
<u>CR 4330 DINGLER 4.6 mi.</u>								
18981	Patched - road surface	\$84.50	4.00	\$48.70	\$111.75	2/24/2017	2/24/2017	\$244.95
18984	Patched - road surface	\$126.75	6.00	\$73.05	\$293.25	2/27/2017	2/27/2017	\$493.05
18991	Patched - road surface	\$126.75	6.00	\$73.05	\$134.22	2/28/2017	2/28/2017	\$334.02
19140	Patched - road surface	\$84.50	4.00	\$48.70	\$78.75	5/4/2017	5/4/2017	\$211.95
19239	Dead livestock/wildlife burial	\$84.50	4.00	\$78.42		6/5/2017	6/5/2017	\$162.92
19448	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19809	Patched - road surface	\$84.50	4.00	\$39.50	\$64.90	9/11/2017	9/11/2017	\$188.90
19864	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/12/2017	9/12/2017	\$0.00
20053	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		12/18/2017	12/18/2017	\$989.52
20060	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		12/19/2017	12/19/2017	\$989.52

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4330 DINGLER 4.6 mi.</b>								
20063	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		12/20/2017	12/20/2017	\$989.52
		\$3,135.50	52.00	\$785.98	\$682.87			\$4,604.35
<b>CR 4331 TERRELL-HOWETH 3 mi.</b>								
18982	Patched - road surface	\$42.25	2.00	\$24.35	\$75.00	2/24/2017	2/24/2017	\$141.60
19139	Patched - road surface	\$84.50	4.00	\$48.70	\$78.75	5/4/2017	5/4/2017	\$211.95
19447	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19810	Patched - road surface	\$84.50	4.00	\$39.50	\$59.00	9/11/2017	9/11/2017	\$183.00
19863	Mow Right-of-Way					9/13/2017	9/13/2017	\$0.00
		\$211.25	10.00	\$112.55	\$212.75			\$536.55
<b>CR 4332 TINDEL-A (off FM 607) 0.5 mi.</b>								
19977	Road base material - added	\$2,168.00	32.00	\$498.08		11/6/2017	11/6/2017	\$2,666.08
		\$2,168.00	32.00	\$498.08				\$2,666.08
<b>CR 4334 N.Y. CHURCH 2.3 mi.</b>								
18854	Patched - road surface	\$84.50	4.00	\$48.70	\$141.00	1/25/2017	1/25/2017	\$274.20
19019	Patched - road surface	\$84.50	4.00	\$48.70	\$75.00	3/16/2017	3/16/2017	\$208.20
19060	Put up County Road Number sign 'NS'	\$9.72	1.00	\$17.87	\$20.61	3/30/2017	3/30/2017	\$48.20
19134	Cleared debris or fallen tree	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19198	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19339	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19801	Patched - road surface	\$84.50	4.00	\$39.50	\$59.00	9/6/2017	9/6/2017	\$183.00
20021	Blade- Patch road surface	\$0.00	0.00	\$0.00		11/28/2017	11/28/2017	\$0.00
		\$263.22	13.00	\$154.77	\$295.61			\$713.60
<b>CR 4336 MYRTLE SPRINGS (45 MPH) 8.8 mi.</b>								
18825	Patch- FALL IN	\$42.25	2.00	\$24.35		1/17/2017	1/17/2017	\$66.60
18867	Patched - road surface	\$42.25	2.00	\$24.35	\$59.00	1/26/2017	1/26/2017	\$125.60
18894	Patched - road surface	\$84.50	4.00	\$48.70	\$89.09	2/3/2017	2/3/2017	\$222.29
19005	Patch- FALL IN	\$42.25	2.00	\$24.35	\$30.09	3/7/2017	3/7/2017	\$96.69
19024	Patched - road surface	\$42.25	2.00	\$24.35	\$97.50	3/17/2017	3/17/2017	\$164.10
19049	Patched - road surface	\$126.75	6.00	\$73.05	\$142.19	3/27/2017	3/27/2017	\$341.99
19063	Put up 'Speed Limit' sign	\$9.72	1.00	\$17.87	\$20.52	3/30/2017	3/30/2017	\$48.11
19071	Patched - road surface	\$84.50	4.00	\$48.70	\$150.00	4/7/2017	4/7/2017	\$283.20
19115	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19128	Cleared debris or fallen tree	\$132.00	2.00	\$54.12		5/3/2017	5/3/2017	\$186.12
19201	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/3/2017	5/3/2017	\$0.00
19133	Cleared debris or fallen tree	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4336 MYRTLE SPRINGS (45 MPH) 8.8 mi.</u>								
19340	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19552	Patched - road surface	\$253.50	12.00	\$118.50	\$186.44	7/27/2017	7/27/2017	\$558.44
19865	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/11/2017	9/11/2017	\$0.00
19986	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/9/2017	11/9/2017	\$989.52
19994	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/13/2017	11/13/2017	\$989.52
20008	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/17/2017	11/17/2017	\$989.52
20006	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/20/2017	11/20/2017	\$989.52
20009	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/21/2017	11/21/2017	\$989.52
20011	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/22/2017	11/22/2017	\$989.52
20016	Cut Brush/ Brush Cutter	\$530.00	5.00	\$88.45		11/22/2017	11/22/2017	\$618.45
20015	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/27/2017	11/27/2017	\$989.52
20020	Blade- Patch road surface	\$0.00	0.00	\$0.00		11/28/2017	11/28/2017	\$0.00
		<u>\$7,325.97</u>	<u>98.00</u>	<u>\$1,537.43</u>	<u>\$774.83</u>			<u>\$9,638.23</u>
<u>CR 4340 ROY SMITH (ext 4336) 1 mi.</u>								
19020	Patched - road surface	\$126.75	6.00	\$73.05	\$262.50	3/16/2017	3/16/2017	\$462.30
19203	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19800	Patched - road surface	\$84.50	4.00	\$39.50	\$59.00	9/6/2017	9/6/2017	\$183.00
20046	Road base material - added	\$2,324.00	32.00	\$528.24		12/15/2017	12/15/2017	\$2,852.24
20051	Road base material - added	\$2,471.00	48.00	\$765.28	\$1,300.00	12/18/2017	12/18/2017	\$4,536.28
		<u>\$5,006.25</u>	<u>90.00</u>	<u>\$1,406.07</u>	<u>\$1,621.50</u>			<u>\$8,033.82</u>
<u>CR 4341 Taylor Farms Rd (ext 4336) 1.1 mi.</u>								
19377	Bladed - add rock	\$1,736.00	32.00	\$565.28		7/7/2017	7/7/2017	\$2,301.28
19420	Bladed - add rock	\$1,302.00	20.00	\$332.82		7/10/2017	7/10/2017	\$1,634.82
19461	Bladed - add rock	\$2,308.00	32.00	\$565.28		7/13/2017	7/13/2017	\$2,873.28
19510	Bladed - road surface	\$672.00	8.00	\$137.04		7/19/2017	7/19/2017	\$809.04
		<u>\$6,018.00</u>	<u>92.00</u>	<u>\$1,600.42</u>				<u>\$7,618.42</u>
<u>CR 4343 JOE YOUNG 6.5 mi.</u>								
18866	Patched - road surface	\$42.25	2.00	\$24.35	\$35.40	1/26/2017	1/26/2017	\$102.00
19092	Oil Sand Overlay	\$2,134.00	32.00	\$585.60	\$8,586.86	4/24/2017	4/24/2017	\$11,306.46
19093	Oil Sand Overlay	\$1,600.50	24.00	\$439.20	\$4,268.06	4/25/2017	4/25/2017	\$6,307.76
19205	Mow Right-of-Way	\$0.00	0.00	\$0.00		4/26/2017	4/26/2017	\$0.00
19120	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19143	Stabilized ditch erosion	\$2,140.00	32.00	\$582.80	\$195.00	5/8/2017	5/8/2017	\$2,917.80
19597	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
19610	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
19629	Patched - road surface	\$0.00	0.00	\$0.00		8/15/2017	8/15/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4343 JOE YOUNG 6.5 mi.</b>								
19632	Patched - road surface	\$0.00	0.00	\$0.00		8/16/2017	8/16/2017	\$0.00
20018	Remove Dead Tree	\$740.00	20.00	\$332.64		11/29/2017	11/29/2017	\$1,072.64
		\$6,656.75	110.00	\$1,964.59	\$13,085.32			\$21,706.66
<b>CR 4344 BOB WALKER 1.7 mi.</b>								
19204	Mow Right-of-Way	\$0.00	0.00	\$0.00		4/26/2017	4/26/2017	\$0.00
19136	Cleared debris or fallen tree	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19398	Patched - road surface	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19452	Patched - road surface	\$126.75	3.00	\$37.50	\$94.10	7/12/2017	7/12/2017	\$258.35
19598	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
		\$126.75	3.00	\$37.50	\$94.10			\$258.35
<b>CR 4345 CHURCH OF CHRIST 0.6 mi.</b>								
19395	Patched - road surface	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
19397	Patched - road surface	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19569	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4346 SMITH 4.6 mi.</b>								
18787	Cleared debris or fallen tree	\$252.00	8.00	\$152.12		1/4/2017	1/4/2017	\$404.12
19122	Road base material - added	\$1,562.00	24.00	\$445.76	\$1,350.00	5/2/2017	5/2/2017	\$3,357.76
19165	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		5/23/2017	5/23/2017	\$992.32
19231	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		5/24/2017	5/24/2017	\$992.32
19611	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
19631	Patched - road surface	\$0.00	0.00	\$0.00		8/16/2017	8/16/2017	\$0.00
19866	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/11/2017	9/11/2017	\$0.00
		\$3,510.00	48.00	\$886.52	\$1,350.00			\$5,746.52
<b>CR 4347 FLOYD'S (Poynor) 1.6 mi.</b>								
19601	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4348 SHOLAR'S 0.6 mi.</b>								
19097	Patched - road surface	\$84.50	4.00	\$48.70	\$118.00	4/24/2017	4/24/2017	\$251.20
19200	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19385	Patched - road surface	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19505	Driveway culvert - installed/set	\$538.00	12.00	\$220.64	\$127.68	7/21/2017	7/21/2017	\$886.32
19613	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
19849	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/26/2017	9/26/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4348 SHOLAR'S 0.6 mi.</b>								
20017	Remove Dead Tree	\$740.00	20.00	\$332.64		11/29/2017	11/29/2017	\$1,072.64
20028	Bladed - pulled shoulders/ditches	\$1,811.25	25.00	\$415.80		12/6/2017	12/6/2017	\$2,227.05
20042	Asphalt overlay	\$4,389.75	90.00	\$1,344.33	\$21,134.01	12/12/2017	12/12/2017	\$26,868.09
20043	Asphalt overlay	\$4,979.25	99.00	\$1,506.69	\$21,008.43	12/13/2017	12/13/2017	\$27,494.37
		<u>\$12,542.75</u>	<u>250.00</u>	<u>\$3,868.80</u>	<u>\$42,388.12</u>			<u>\$58,799.67</u>
<b>CR 4349 WYLIE 1 mi.</b>								
19384	Patched - road surface	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19593	Cut Brush/ Brush Cutter	\$212.00	2.00	\$35.38		8/9/2017	8/9/2017	\$247.38
19614	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
19846	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/26/2017	9/26/2017	\$0.00
		<u>\$212.00</u>	<u>2.00</u>	<u>\$35.38</u>				<u>\$247.38</u>
<b>CR 4350 LARUE CEMETARY 0.4 mi.</b>								
19131	Cleared debris or fallen tree	\$269.00	8.00	\$147.52		5/3/2017	5/3/2017	\$416.52
19135	Cleared debris or fallen tree	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19199	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19612	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
19848	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/26/2017	9/26/2017	\$0.00
20029	Road base material - added	\$1,086.75	15.00	\$249.48		12/6/2017	12/6/2017	\$1,336.23
20049	Road base material - added	\$2,022.00	40.00	\$665.28		12/7/2017	12/7/2017	\$2,687.28
20050	Road base material - added	\$2,022.00	40.00	\$665.28		12/8/2017	12/8/2017	\$2,687.28
20044	Laid tack oil Primer	\$789.60	40.00	\$737.44	\$2,341.69	12/11/2017	12/11/2017	\$3,868.73
		<u>\$6,189.35</u>	<u>143.00</u>	<u>\$2,465.00</u>	<u>\$2,341.69</u>			<u>\$10,996.04</u>
<b>CR 4351 LARUE 0.3 mi.</b>								
19648	Patched - road surface	\$0.00	0.00	\$0.00		8/21/2017	8/21/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<b>CR 4353 LARUE 0.2 mi.</b>								
19647	Patched - road surface	\$0.00	0.00	\$0.00		8/21/2017	8/21/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<b>CR 4400 ROCKHILL (35 MPH) 5.4 mi.</b>								
18944	/ Reinstall trash pick-up sings	\$77.80	8.00	\$156.72		2/14/2017	2/14/2017	\$234.52
19004	Patched - road surface	\$126.75	6.00	\$73.05	\$177.00	3/7/2017	3/7/2017	\$376.80
19042	Patch- FALL IN	\$42.25	2.00	\$24.35	\$21.83	3/23/2017	3/23/2017	\$88.43
19055	Cleared debris or fallen tree	\$462.48	7.50	\$137.89		3/29/2017	3/29/2017	\$600.37
19062	Put up 'Stop' sign	\$9.72	1.00	\$17.87	\$92.49	3/30/2017	3/30/2017	\$120.08

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4400 ROCKHILL (35 MPH) 5.4 mi.</u>								
19196	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/10/2017	5/10/2017	\$0.00
19220	Blade- Patch road surface	\$169.00	4.00	\$84.56	\$183.49	5/26/2017	5/26/2017	\$437.05
19386	Patched - road surface	\$253.50	6.00	\$75.00	\$263.25	7/7/2017	7/7/2017	\$591.75
19551	Road surface repair	\$764.25	24.00	\$441.28		7/28/2017	7/28/2017	\$1,205.53
19571	Mow Right-of-Way	\$0.00	6.00	\$75.00		7/31/2017	7/31/2017	\$75.00
19628	Patched - road surface	\$0.00	0.00	\$0.00		8/15/2017	8/15/2017	\$0.00
19845	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/28/2017	9/28/2017	\$0.00
19913	Blade- Patch road surface	\$338.00	24.00	\$216.00	\$179.36	10/12/2017	10/12/2017	\$733.36
19995	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		11/14/2017	11/14/2017	\$992.32
19996	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		11/15/2017	11/15/2017	\$992.32
20033	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/4/2017	12/4/2017	\$992.32
20034	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/5/2017	12/5/2017	\$992.32
20035	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/6/2017	12/6/2017	\$992.32
20047	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/14/2017	12/14/2017	\$992.32
20048	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/15/2017	12/15/2017	\$992.32
20052	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/18/2017	12/18/2017	\$992.32
20058	Patch- FALL IN	\$353.25	8.00	\$130.52	\$100.00	12/19/2017	12/19/2017	\$583.77
20059	Cut Brush/ Brush Cutter	\$0.00	8.00	\$144.32		12/19/2017	12/19/2017	\$144.32
20062	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		12/20/2017	12/20/2017	\$992.32
		<u>\$10,229.00</u>	<u>176.50</u>	<u>\$2,875.44</u>	<u>\$1,017.42</u>			<u>\$14,121.86</u>
<u>CR 4401 DOUGLAS LOOP 1 mi.</u>								
18820	Clean Culvert/Beaver Dam	\$259.40	4.00	\$77.66		1/17/2017	1/17/2017	\$337.06
19396	Patched - road surface	\$0.00	0.00	\$0.00		7/11/2017	7/11/2017	\$0.00
19599	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
19938	Clean Culvert/Beaver Dam	\$272.50	6.00	\$107.06		10/23/2017	10/23/2017	\$379.56
		<u>\$531.90</u>	<u>10.00</u>	<u>\$184.72</u>				<u>\$716.62</u>
<u>CR 4402 ROSENBERG (off FM 2588) (35 MPH) 4.1 mi.</u>								
18779	Patched - road surface	\$338.00	16.00	\$310.64	\$213.58	1/4/2017	1/4/2017	\$862.22
18846	Patch- FALL IN	\$0.00	0.00	\$0.00		1/24/2017	1/24/2017	\$0.00
18996	Patched - road surface	\$126.75	6.00	\$73.05	\$118.00	3/2/2017	3/2/2017	\$317.80
19065	Patched - road surface	\$126.75	6.00	\$73.05	\$148.09	3/31/2017	3/31/2017	\$347.89
19156	Patched - road surface	\$84.50	4.00	\$48.70	\$75.00	5/8/2017	5/8/2017	\$208.20
19322	Patched - road surface	\$169.00	8.00	\$134.56	\$178.77	6/21/2017	6/21/2017	\$482.33
19343	Mow Right-of-Way	\$0.00	5.00	\$62.50		6/27/2017	6/27/2017	\$62.50
19470	Patched - road surface	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4402 ROSENBERG (off FM 2588) (35 MPH)</b>								
4.1 mi.								
19685	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19707	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19792	Cut Brush/ Brush Cutter	\$424.00	4.00	\$72.16		9/5/2017	9/5/2017	\$496.16
19803	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		9/7/2017	9/7/2017	\$992.32
19906	Patched - road surface	\$84.50	4.00	\$39.50	\$76.11	10/11/2017	10/11/2017	\$200.11
		<u>\$2,201.50</u>	<u>61.00</u>	<u>\$958.48</u>	<u>\$809.55</u>			<u>\$3,969.53</u>
<b>CR 4403 SISSY'S 2.1 mi.</b>								
18819	Clean Culvert/Beaver Dam	\$259.40	4.00	\$77.66		1/17/2017	1/17/2017	\$337.06
18882	Patched - road surface	\$84.50	4.00	\$48.70	\$148.68	1/30/2017	1/30/2017	\$281.88
18890	Patched - road surface	\$84.50	4.00	\$48.70	\$114.46	2/1/2017	2/1/2017	\$247.66
19114	Patched - road surface	\$0.00	0.00	\$0.00		5/2/2017	5/2/2017	\$0.00
19393	Patched - road surface	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
19567	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
19600	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
19937	Clean Culvert/Beaver Dam	\$272.50	6.00	\$107.06		10/23/2017	10/23/2017	\$379.56
19979	Moved equipment to work site	\$586.00	24.00	\$441.28		11/1/2017	11/1/2017	\$1,027.28
19971	Asphalt overlay	\$4,104.00	80.00	\$1,194.96	\$20,782.80	11/2/2017	11/2/2017	\$26,081.76
		<u>\$5,390.90</u>	<u>122.00</u>	<u>\$1,918.36</u>	<u>\$21,045.94</u>			<u>\$28,355.20</u>
<b>CR 4404 ARCHIE DENNIS-A (off US 175) 1.3 mi.</b>								
19075	Blade- Patch road surface	\$1,165.00	15.00	\$261.50	\$1,998.92	4/6/2017	4/6/2017	\$3,425.42
19392	Patched - road surface	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
19570	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
		<u>\$1,165.00</u>	<u>15.00</u>	<u>\$261.50</u>	<u>\$1,998.92</u>			<u>\$3,425.42</u>
<b>CR 4494 TUFFY ROBERTS</b>								
19394	Patched - road surface	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
19568	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<b>CR 4500 0.6 mi.</b>								
19077	Road culvert - replaced	\$904.25	16.00	\$336.32	\$963.20	4/6/2017	4/6/2017	\$2,203.77
19087	Other right-of-way work	\$1,746.50	40.00	\$729.04		4/21/2017	4/21/2017	\$2,475.54
		<u>\$2,650.75</u>	<u>56.00</u>	<u>\$1,065.36</u>	<u>\$963.20</u>			<u>\$4,679.31</u>
<b>CR 4501 COUNTRY LN 0.4 mi.</b>								
18951	Patched - road surface	\$0.00	0.00	\$0.00	\$89.68	2/16/2017	2/16/2017	\$89.68
19175	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/18/2017	5/18/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4501 COUNTRY LN 0.4 mi.</b>								
19356	Cleared debris or fallen tree	\$155.00	6.00	\$171.76		7/1/2017	7/1/2017	\$326.76
19697	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
		\$155.00	6.00	\$171.76	\$89.68			\$416.44
<b>CR 4502 CREEKSIDE (off US 175) 0.3 mi.</b>								
19695	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
19716	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4503 ENOCK (off US 175) 0.7 mi.</b>								
19715	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4504 Rakestraw 0.1 mi.</b>								
18822	Inquiry about road status	\$19.45	1.00	\$20.90		1/17/2017	1/17/2017	\$40.35
18874	Asphalt overlay Over New Culvert	\$0.00	12.00	\$220.64	\$416.76	1/26/2017	1/26/2017	\$637.40
19696	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
19714	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$19.45	13.00	\$241.54	\$416.76			\$677.75
<b>CR 4506 HUGGINS (ext 4507) 0.9 mi.</b>								
19168	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/22/2017	5/22/2017	\$0.00
19691	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4507 MOONSHINE (off US 175) 0.8 mi.</b>								
19171	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/22/2017	5/22/2017	\$0.00
19643	Patched - road surface	\$0.00	0.00	\$0.00		8/18/2017	8/18/2017	\$0.00
19692	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4508 MOONSHINE (ext 4507) 0.5 mi.</b>								
18802	Patched - road surface	\$84.50	4.00	\$48.70	\$176.25	1/11/2017	1/11/2017	\$309.45
19089	Patched - road surface	\$84.50	4.00	\$48.70	\$135.75	4/21/2017	4/21/2017	\$268.95
19169	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/22/2017	5/22/2017	\$0.00
19642	Patched - road surface	\$0.00	0.00	\$0.00		8/18/2017	8/18/2017	\$0.00
19693	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
		\$169.00	8.00	\$97.40	\$312.00			\$578.40



ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4509 HARRY MILLS 0.5 mi.</b>								
18803	Patched - road surface	\$84.50	4.00	\$48.70	\$176.25	1/11/2017	1/11/2017	\$309.45
19090	Patched - road surface	\$42.25	2.00	\$24.35	\$75.00	4/21/2017	4/21/2017	\$141.60
19170	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/22/2017	5/22/2017	\$0.00
19641	Patched - road surface	\$0.00	0.00	\$0.00		8/18/2017	8/18/2017	\$0.00
19694	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/22/2017	8/22/2017	\$0.00
		\$126.75	6.00	\$73.05	\$251.25			\$451.05
<b>CR 4510 TU 1.9 mi.</b>								
18782	Cleared debris or fallen tree	\$78.00	6.00	\$114.09		1/3/2017	1/3/2017	\$192.09
19099	Cleared debris or fallen tree	\$452.12	8.00	\$155.32		4/24/2017	4/24/2017	\$607.44
19148	Driveway entrance - repaired	\$42.25	3.00	\$31.60	\$17.25	5/5/2017	5/5/2017	\$91.10
19208	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/25/2017	5/25/2017	\$0.00
19626	Patched - road surface	\$0.00	0.00	\$0.00		8/14/2017	8/14/2017	\$0.00
19679	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/21/2017	8/21/2017	\$25.00
		\$572.37	19.00	\$326.01	\$17.25			\$915.63
<b>CR 4511 BAXTER/PINEGROVE (45 MPH) {Minor Collector*} 3.3 mi.</b>								
18950	Patched - road surface	\$0.00	0.00	\$0.00	\$177.00	2/16/2017	2/16/2017	\$177.00
19209	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/25/2017	5/25/2017	\$0.00
19280	Patched - road surface	\$0.00	0.00	\$0.00	\$239.25	6/13/2017	6/13/2017	\$239.25
19627	Patched - road surface	\$0.00	0.00	\$0.00		8/14/2017	8/14/2017	\$0.00
19676	Mow Right-of-Way	\$0.00	4.00	\$50.00		8/18/2017	8/18/2017	\$50.00
19680	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/21/2017	8/21/2017	\$25.00
19794	Cleared debris or fallen tree	\$714.00	12.00	\$214.12		9/5/2017	9/5/2017	\$928.12
19817	Patched - road surface	\$84.50	4.00	\$39.50	\$10.74	9/12/2017	9/12/2017	\$134.74
19924	Patched - road surface	\$126.75	9.00	\$81.00	\$80.24	10/16/2017	10/16/2017	\$287.99
		\$925.25	31.00	\$409.62	\$507.23			\$1,842.10
<b>CR 4513 D. McGEE 0.5 mi.</b>								
19039	Patched - road surface	\$42.25	2.00	\$24.35	\$46.61	3/22/2017	3/22/2017	\$113.21
19206	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/23/2017	5/23/2017	\$0.00
19677	Mow Right-of-Way	\$0.00	0.50	\$6.25		8/18/2017	8/18/2017	\$6.25
19818	Patched - road surface	\$84.50	4.00	\$39.50	\$66.67	9/12/2017	9/12/2017	\$190.67
		\$126.75	6.50	\$70.10	\$113.28			\$310.13
<b>CR 4514 DAVIS CEM. 0.1 mi.</b>								
19678	Mow Right-of-Way	\$0.00	0.50	\$6.25		8/18/2017	8/18/2017	\$6.25
19819	Patched - road surface	\$84.50	4.00	\$39.50	\$66.67	9/12/2017	9/12/2017	\$190.67

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4514 DAVIS CEM. 0.1 mi.</u>								
		\$84.50	4.50	\$45.75	\$66.67			\$196.92
<u>CR 4515 RICHARDSON (45 MPH) 2.9 mi.</u>								
18911	Patched - road surface	\$126.75	6.00	\$73.05	\$118.00	2/8/2017	2/8/2017	\$317.80
18925	Patched - road surface	\$0.00	0.00	\$0.00	\$177.00	2/9/2017	2/9/2017	\$177.00
19037	Patched - road surface	\$84.50	4.00	\$48.70	\$118.00	3/22/2017	3/22/2017	\$251.20
19041	Patched - road surface	\$126.75	6.00	\$73.05	\$236.00	3/23/2017	3/23/2017	\$435.80
19337	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19366	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/3/2017	7/3/2017	\$0.00
19717	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
19776	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
19770	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00
19923	Patched - road surface	\$126.75	9.00	\$81.00	\$80.24	10/16/2017	10/16/2017	\$287.99
19932	Patched - road surface	\$253.50	12.00	\$118.50	\$198.24	10/18/2017	10/18/2017	\$570.24
20066	Road Culvert clean inlet ( Drift Wood )	\$259.40	4.00	\$68.52		12/20/2017	12/20/2017	\$327.92
20068	Cleaned outfall ditch	\$518.80	12.00	\$220.64		12/21/2017	12/21/2017	\$739.44
		\$1,496.45	53.00	\$683.46	\$927.48			\$3,107.39
<u>CR 4516 HAIRGROVE 1.6 mi.</u>								
19038	Patched - road surface	\$84.50	4.00	\$48.70	\$118.00	3/22/2017	3/22/2017	\$251.20
19338	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19367	Mow Right-of-Way					7/3/2017	7/3/2017	\$0.00
19775	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
19953	Patched - road surface	\$253.50	12.00	\$118.50	\$197.06	10/19/2017	10/19/2017	\$569.06
20013	Clean Culvert/Beaver Dam	\$1,428.00	24.00	\$404.24		11/27/2017	11/27/2017	\$1,832.24
20019	Blade- Patch road surface	\$0.00	0.00	\$0.00		11/28/2017	11/28/2017	\$0.00
20065	Clean Culvert/Beaver Dam	\$259.40	4.00	\$68.52		12/20/2017	12/20/2017	\$327.92
20070	Patch- FALL IN	\$610.00	8.00	\$168.00	\$100.00	12/22/2017	12/22/2017	\$878.00
		\$2,635.40	52.00	\$807.96	\$415.06			\$3,858.42
<u>CR 4518 BURNETT / SUPER COP (35MPH) 1.1 mi.</u>								
18816	Put up County Road Number sign 'NS'	\$19.45	1.00	\$18.04	\$22.57	1/17/2017	1/17/2017	\$60.06
18912	Patched - road surface	\$84.50	4.00	\$48.70	\$106.20	2/8/2017	2/8/2017	\$239.40
18926	Patched - road surface	\$0.00	0.00	\$0.00	\$177.00	2/9/2017	2/9/2017	\$177.00
19142	Patched - road surface	\$84.50	4.00	\$48.70	\$78.75	5/4/2017	5/4/2017	\$211.95
19346	Mow Right-of-Way	\$0.00	1.00	\$12.50		6/28/2017	6/28/2017	\$12.50
19474	Patched - road surface	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19554	Patched - road surface	\$84.50	4.00	\$39.50	\$70.51	7/28/2017	7/28/2017	\$194.51
19771	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4518 BURNETT / SUPER COP (35MPH) 1.1 mi.</u>								
		\$272.95	14.00	\$167.44	\$455.03			\$895.42
<u>CR 4520E RAINBOW-E ( Rainbo Gate to 4402 2.4 mi.</u>								
18801	Patched - road surface	\$338.00	16.00	\$194.80	\$267.00	1/10/2017	1/10/2017	\$799.80
18997	Patched - road surface	\$126.75	6.00	\$73.05	\$150.45	3/2/2017	3/2/2017	\$350.25
19344	Mow Right-of-Way	\$0.00	2.00	\$25.00		6/28/2017	6/28/2017	\$25.00
19473	Patched - road surface	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19739	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
19773	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
19978	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		11/6/2017	11/6/2017	\$992.32
19973	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		11/7/2017	11/7/2017	\$992.32
20012	Stabilized ditch erosion	\$1,066.25	25.00	\$415.80	\$1,200.00	11/22/2017	11/22/2017	\$2,682.05
		\$3,227.00	65.00	\$997.29	\$1,617.45			\$5,841.74
<u>CR 4520W RAINBOW-W (1615 to Rainbo Gate) 3 mi.</u>								
18809	Patched - road surface	\$84.50	4.00	\$48.70	\$93.75	1/12/2017	1/12/2017	\$226.95
18959	Cleared debris or fallen tree	\$1,062.25	22.00	\$403.25		2/21/2017	2/21/2017	\$1,465.50
19015	Patched - road surface	\$253.50	12.00	\$146.10	\$258.42	3/14/2017	3/14/2017	\$658.02
19141	Patched - road surface	\$84.50	4.00	\$48.70	\$78.75	5/4/2017	5/4/2017	\$211.95
19345	Mow Right-of-Way	\$0.00	2.00	\$25.00		6/28/2017	6/28/2017	\$25.00
19472	Patched - road surface	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00
19738	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
19774	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
19884	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		9/11/2017	9/11/2017	\$992.32
19885	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		9/12/2017	9/12/2017	\$992.32
19886	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		9/13/2017	9/13/2017	\$992.32
19887	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		9/14/2017	9/14/2017	\$992.32
		\$4,876.75	76.00	\$1,249.03	\$430.92			\$6,556.70
<u>CR 4521 LOOKABOUGH 0.5 mi.</u>								
19471	Patched - road surface	\$0.00	0.00	\$0.00		7/17/2017	7/17/2017	\$0.00
19737	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4522 GROSS 0.4 mi.</u>								
19727	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4523 HALBERT 0.3 mi.</b>								
19709	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19725	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4524 BUBBA BURNETT 0.2 mi.</b>								
19708	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19724	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
19822	Asphalt overlay	\$3,122.00	72.00	\$1,094.96	\$11,757.60	9/22/2017	9/22/2017	\$15,974.56
19883	Driveway entrance - repaired	\$353.25	8.00	\$152.12	\$150.00	10/9/2017	10/9/2017	\$655.37
		\$3,475.25	80.00	\$1,247.08	\$11,907.60			\$16,629.93
<b>CR 4528 COUNTY LINE (35 MPH) 5.2 mi.</b>								
18977	Patched - road surface	\$84.50	6.00	\$63.20	\$256.50	2/23/2017	2/23/2017	\$404.20
19064	Patched - road surface	\$126.75	6.00	\$73.05	\$118.00	3/31/2017	3/31/2017	\$317.80
19074	Patched - road surface	\$169.00	8.00	\$97.40	\$142.78	4/3/2017	4/3/2017	\$409.18
19100	Cleaned ditches	\$904.25	16.00	\$310.64		4/25/2017	4/25/2017	\$1,214.89
19106	Oil Sand Overlay	\$1,562.00	24.00	\$441.28	\$4,117.02	4/27/2017	4/27/2017	\$6,120.30
19108	Oil Sand Overlay	\$1,562.00	32.00	\$582.80	\$5,487.59	4/28/2017	4/28/2017	\$7,632.39
19126	Moved equipment to work site	\$45.00	8.00	\$152.12		5/1/2017	5/1/2017	\$197.12
19157	Patched - road surface	\$84.50	4.00	\$48.70	\$75.00	5/8/2017	5/8/2017	\$208.20
19144	Asphalt overlay	\$4,790.00	88.00	\$1,472.64	\$31,584.75	5/9/2017	5/9/2017	\$37,847.39
19145	Asphalt overlay	\$5,362.00	96.00	\$1,600.64	\$36,787.35	5/10/2017	5/10/2017	\$43,749.99
19147	Asphalt overlay	\$4,218.00	80.00	\$1,321.20	\$27,095.04	5/11/2017	5/11/2017	\$32,634.24
19316	Patched - road surface	\$0.00	0.00	\$0.00		6/19/2017	6/19/2017	\$0.00
19341	Mow Right-of-Way	\$0.00	3.00	\$37.50		6/26/2017	6/26/2017	\$37.50
19383	Patched - road surface	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19686	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19905	Patched - road surface	\$84.50	4.00	\$39.50	\$76.11	10/11/2017	10/11/2017	\$200.11
20067	Remove Dead Tree	\$518.80	8.00	\$137.04		12/20/2017	12/20/2017	\$655.84
		\$19,511.30	383.00	\$6,377.71	\$105,740.14			\$131,629.15
<b>CR 4529 MRS. MCGEE 0.5 mi.</b>								
19687	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4530 SHEPTRINE (35 MPH) 1.3 mi.</b>								
19572	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/1/2017	8/1/2017	\$0.00
19706	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4533</b>								
19622	Patched - road surface	\$0.00	0.00	\$0.00		8/11/2017	8/11/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4535 PALMER 0.2 mi.</b>								
19342	Mow Right-of-Way	\$0.00	0.50	\$6.25		6/26/2017	6/26/2017	\$6.25
19690	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
		\$0.00	0.50	\$6.25				\$6.25
<b>CR 4537 E. COLLEGE 0.6 mi.</b>								
19481	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
19963	Patched - road surface	\$84.50	4.00	\$39.50	\$65.25	10/26/2017	10/26/2017	\$189.25
		\$84.50	4.00	\$39.50	\$65.25			\$189.25
<b>CR 4538 COLONIAL CIRCLE 0.7 mi.</b>								
19482	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/14/2017	7/14/2017	\$0.00
19964	Patched - road surface	\$84.50	4.00	\$39.50	\$75.00	10/26/2017	10/26/2017	\$199.00
		\$84.50	4.00	\$39.50	\$75.00			\$199.00
<b>CR 4600 CARROLL SPRINGS (35 MPH) 2.5 mi.</b>								
18994	Patched - road surface	\$84.50	4.00	\$48.70	\$118.00	3/1/2017	3/1/2017	\$251.20
19294	Sealcoat	\$3,768.00	72.00	\$1,292.40	\$11,736.50	6/15/2017	6/15/2017	\$16,796.90
19688	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19712	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19904	Patched - road surface	\$84.50	4.00	\$39.50	\$76.11	10/11/2017	10/11/2017	\$200.11
		\$3,937.00	80.00	\$1,380.60	\$11,930.61			\$17,248.21
<b>CR 4601 (to county line) 0.3 mi.</b>								
18995	Patched - road surface	\$126.75	6.00	\$73.05	\$145.14	3/1/2017	3/1/2017	\$344.94
19689	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
		\$126.75	6.00	\$73.05	\$145.14			\$344.94
<b>CR 4604 Terry Davis 0.4 mi.</b>								
19216	Patched - road surface	\$84.50	2.00	\$42.28	\$18.29	5/24/2017	5/24/2017	\$145.07
19233	Trimmed brush or trees	\$239.50	6.00	\$111.44		6/6/2017	6/6/2017	\$350.94
19710	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19726	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$324.00	8.00	\$153.72	\$18.29			\$496.01
<b>CR 4607 DIAMOND C 0.7 mi.</b>								
19288	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4607 DIAMOND C 0.7 mi.</u>								
19736	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4608 D WARREN 0.2 mi.</u>								
19711	Blade- Patch road surface	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
19728	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4609 ANDING 1 mi.</u>								
19287	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4610 GARY RD 2.2 mi.</u>								
18824	Trash/garbage picked-up	\$42.25	2.00	\$24.35		1/17/2017	1/17/2017	\$66.60
18834	Trash/garbage picked-up	\$169.00	8.00	\$97.40		1/19/2017	1/19/2017	\$266.40
18924	Blade- Patch road surface	\$435.75	7.00	\$133.55	\$979.40	2/10/2017	2/10/2017	\$1,548.70
19051	Patched - road surface	\$84.50	4.00	\$48.70	\$225.75	3/28/2017	3/28/2017	\$358.95
19072	Patched - road surface	\$211.25	10.00	\$121.75	\$366.00	4/6/2017	4/6/2017	\$699.00
19232	Driveway culvert - installed/set	\$359.25	9.00	\$167.16	\$325.00	6/6/2017	6/6/2017	\$851.41
19475	Patched - road surface	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19729	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
19734	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
		\$1,302.00	40.00	\$592.91	\$1,896.15			\$3,791.06
<u>CR 4610A BROWN-A 0.6 mi.</u>								
19265	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/12/2017	6/12/2017	\$0.00
19476	Patched - road surface	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19730	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4610B LASITER 0.3 mi.</u>								
19269	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/12/2017	6/12/2017	\$0.00
19477	Patched - road surface	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19731	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4610C BONHAM 0.6 mi.</u>								
19267	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/12/2017	6/12/2017	\$0.00
19478	Patched - road surface	\$0.00	0.00	\$0.00		7/18/2017	7/18/2017	\$0.00
19732	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4610C BONHAM 0.6 mi.</b>								
		\$0.00	0.00	\$0.00				\$0.00
<b>CR 4611 BUTLER</b>								
18917	Bladed - road surface	\$0.00	0.00	\$0.00		2/7/2017	2/7/2017	\$0.00
18918	Laid tack oil	\$396.25	15.00	\$297.75	\$1,635.00	2/9/2017	2/9/2017	\$2,329.00
18923	Oil Sand Overlay	\$3,050.25	50.00	\$951.98	\$13,993.62	2/10/2017	2/10/2017	\$17,995.85
19264	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/12/2017	6/12/2017	\$0.00
19733	Mow Right-of-Way					8/25/2017	8/25/2017	\$0.00
		\$3,446.50	65.00	\$1,249.73	\$15,628.62			\$20,324.85
<b>CR 4612 MAYS CAFÉ 0.4 mi.</b>								
18808	Patched - road surface	\$42.25	2.00	\$24.35	\$75.00	1/12/2017	1/12/2017	\$141.60
19262	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/12/2017	6/12/2017	\$0.00
19735	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
19967	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/27/2017	10/27/2017	\$992.32
		\$890.25	10.00	\$168.67	\$75.00			\$1,133.92
<b>CR 4613 OLD 19 (35 MPH) 3 mi.</b>								
18817	Put up STOP sign 'NS'	\$19.45	1.00	\$18.04	\$32.49	1/17/2017	1/17/2017	\$69.98
18821	Road Cuvert (mark for dig tess)	\$38.90	2.00	\$41.80		1/17/2017	1/17/2017	\$80.70
18868	Patched - road surface	\$42.25	2.00	\$24.35	\$44.43	1/27/2017	1/27/2017	\$111.03
18875	Cleaned ditches	\$1,959.00	40.00	\$751.92		1/27/2017	1/27/2017	\$2,710.92
18876	Cleaned ditches	\$2,452.00	40.00	\$751.92		1/30/2017	1/30/2017	\$3,203.92
18877	Road culvert - replaced	\$1,242.25	24.00	\$441.28	\$2,312.10	1/31/2017	1/31/2017	\$3,995.63
18883	Patched - road surface	\$338.00	16.00	\$194.80	\$292.05	1/31/2017	1/31/2017	\$824.85
18884	Road culvert - installed	\$868.00	24.00	\$441.28	\$512.42	2/1/2017	2/1/2017	\$1,821.70
18889	Patched - road surface	\$84.50	4.00	\$48.70	\$118.00	2/1/2017	2/1/2017	\$251.20
18899	Asphalt overlay / Over new culvert	\$726.00	12.00	\$207.80		2/2/2017	2/2/2017	\$933.80
18901	Patched - road surface	\$0.00	0.00	\$0.00		2/6/2017	2/6/2017	\$0.00
18913	Cleaned ditches	\$1,510.00	40.00	\$751.92		2/6/2017	2/6/2017	\$2,261.92
18942	Trash/garbage picked-up	\$77.80	8.00	\$97.40		2/14/2017	2/14/2017	\$175.20
18952	Stabilized ditch erosion	\$0.00	0.00	\$0.00	\$105.57	2/16/2017	2/16/2017	\$105.57
18957	Road base material - added / Wash Out from ROLO	\$1,440.00	32.00	\$582.80		2/16/2017	2/16/2017	\$2,022.80
18967	Grind Road (ZIPPER) / Section 1	\$2,893.60	56.00	\$849.40	\$1,644.30	2/22/2017	2/22/2017	\$5,387.30
18978	Grind Road (ZIPPER) / Section 2	\$3,233.60	48.00	\$896.24	\$1,642.20	2/23/2017	2/23/2017	\$5,772.04
18985	Bladed - road surface /Shape,Water&Compact	\$1,844.00	32.00	\$582.80		2/27/2017	2/27/2017	\$2,426.80
18988	Grind Road (ZIPPER) /Section 3	\$3,078.00	40.00	\$751.92	\$1,634.50	2/28/2017	2/28/2017	\$5,464.42
18992	Grind Road (ZIPPER) / Section 4	\$3,078.00	0.00	\$0.00	\$1,669.50	2/28/2017	2/28/2017	\$4,747.50

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4613 OLD 19 (35 MPH) 3 mi.</b>								
19008	Bladed - road surface Prep for Primer	\$1,147.00	24.00	\$445.76		3/13/2017	3/13/2017	\$1,592.76
19009	Laid tack oil /MC-30	\$524.20	20.00	\$364.64	\$2,400.00	3/14/2017	3/14/2017	\$3,288.84
19032	Laid tack oil /MC-30 Primer	\$524.20	20.00	\$396.72	\$2,400.00	3/16/2017	3/16/2017	\$3,320.92
19067	Asphalt overlay	\$4,488.00	80.00	\$1,391.20	\$28,308.40	4/4/2017	4/4/2017	\$34,187.60
19068	Asphalt overlay	\$4,488.00	80.00	\$1,391.20	\$31,020.92	4/5/2017	4/5/2017	\$36,900.12
19080	Asphalt overlay	\$4,790.00	88.00	\$1,463.84	\$37,555.72	4/12/2017	4/12/2017	\$43,809.56
19079	Asphalt overlay	\$4,218.00	80.00	\$1,321.20	\$20,931.08	4/13/2017	4/13/2017	\$26,470.28
19085	Driveway entrance - repaired	\$169.00	12.00	\$126.40	\$276.75	4/17/2017	4/17/2017	\$572.15
19086	Other driveway work	\$169.00	12.00	\$126.40	\$193.50	4/18/2017	4/18/2017	\$488.90
19229	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/2/2017	6/2/2017	\$0.00
19704	Patched - road surface	\$126.75	6.00	\$59.25	\$88.79	8/23/2017	8/23/2017	\$274.79
19766	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/1/2017	9/1/2017	\$0.00
19916	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/16/2017	10/16/2017	\$992.32
19922	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/17/2017	10/17/2017	\$992.32
19927	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/18/2017	10/18/2017	\$992.32
19944	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/19/2017	10/19/2017	\$992.32
19935	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/20/2017	10/20/2017	\$992.32
19945	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/20/2017	10/20/2017	\$992.32
19946	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/23/2017	10/23/2017	\$992.32
19957	Patched - road surface	\$0.00	0.00	\$0.00	\$59.00	10/23/2017	10/23/2017	\$59.00
		\$51,505.50	899.00	\$15,531.22	\$133,241.72			\$200,278.44
<b>CR 4614 HOLDER (35 MPH) 1.6 mi.</b>								
18869	Patched - road surface	\$42.25	2.00	\$24.35	\$44.43	1/27/2017	1/27/2017	\$111.03
18998	Patched - road surface	\$211.25	10.00	\$121.75	\$267.86	3/3/2017	3/3/2017	\$600.86
19081	Bridge - repaired	\$155.60	16.00	\$194.80	\$720.00	3/8/2017	3/8/2017	\$1,070.40
19082	Bridge - repaired	\$155.60	16.00	\$194.80	\$265.58	3/9/2017	3/9/2017	\$615.98
19070	Patched - road surface	\$84.50	4.00	\$48.70	\$150.00	4/7/2017	4/7/2017	\$283.20
19210	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/25/2017	5/25/2017	\$0.00
19555	Patched - road surface	\$84.50	4.00	\$39.50	\$63.13	7/31/2017	7/31/2017	\$187.13
19585	Driveway culvert - installed/set	\$583.00	12.00	\$199.04		8/8/2017	8/8/2017	\$782.04
19772	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/30/2017	8/30/2017	\$0.00
19767	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/1/2017	9/1/2017	\$0.00
19958	Patched - road surface	\$0.00	0.00	\$0.00	\$59.00	10/23/2017	10/23/2017	\$59.00
		\$1,316.70	64.00	\$822.94	\$1,570.00			\$3,709.64
<b>CR 4615 LITTLE ACRES 0.2 mi.</b>								
19059	Put up County Road Number sign 'NS'	\$9.72	1.00	\$17.87	\$20.61	3/30/2017	3/30/2017	\$48.20



ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4615 LITTLE ACRES 0.2 mi.</u>								
19768	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/1/2017	9/1/2017	\$0.00
		\$9.72	1.00	\$17.87	\$20.61			\$48.20
<u>CR 4616 GIN 0.4 mi.</u>								
18887	Patched - road surface	\$42.25	2.00	\$24.35	\$118.00	2/1/2017	2/1/2017	\$184.60
19769	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/1/2017	9/1/2017	\$0.00
19787	Patched - road surface	\$0.00	0.00	\$0.00		9/5/2017	9/5/2017	\$0.00
19951	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/25/2017	10/25/2017	\$992.32
		\$890.25	10.00	\$168.67	\$118.00			\$1,176.92
<u>CR 4617 CARROL DR / VIRGINIA PINES-A 0.3 mi.</u>								
18888	Patched - road surface	\$42.25	2.00	\$24.35	\$59.00	2/1/2017	2/1/2017	\$125.60
19312	Herbicide/weed spraying	\$116.80	8.00	\$134.56		6/14/2017	6/14/2017	\$251.36
19788	Patched - road surface	\$0.00	0.00	\$0.00		9/5/2017	9/5/2017	\$0.00
		\$159.05	10.00	\$158.91	\$59.00			\$376.96
<u>CR 4618 VIRGINIA PINES-B 0.3 mi.</u>								
18870	Patched - road surface	\$42.25	2.00	\$24.35	\$44.43	1/27/2017	1/27/2017	\$111.03
19789	Patched - road surface	\$0.00	0.00	\$0.00		9/5/2017	9/5/2017	\$0.00
		\$42.25	2.00	\$24.35	\$44.43			\$111.03
<u>CR 4619 VIRGINIA PINES-C 0.3 mi.</u>								
18871	Patched - road surface	\$42.25	2.00	\$24.35	\$44.43	1/27/2017	1/27/2017	\$111.03
19790	Patched - road surface	\$0.00	0.00	\$0.00		9/5/2017	9/5/2017	\$0.00
		\$42.25	2.00	\$24.35	\$44.43			\$111.03
<u>CR 4622 OWEN CEMETARY 1 mi.</u>								
18898	Patch- FALL IN	\$726.00	12.00	\$207.80	\$537.12	2/2/2017	2/2/2017	\$1,470.92
19069	Patched - road surface	\$42.25	2.00	\$24.35	\$74.25	4/7/2017	4/7/2017	\$140.85
19230	Mow Right-of-Way	\$0.00	0.00	\$0.00		6/2/2017	6/2/2017	\$0.00
19325	Patched - road surface	\$42.25	2.00	\$33.64	\$59.00	6/23/2017	6/23/2017	\$134.89
19404	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/26/2017	6/26/2017	\$992.32
19406	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/28/2017	6/28/2017	\$992.32
19407	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		6/29/2017	6/29/2017	\$992.32
19698	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
		\$3,354.50	40.00	\$698.75	\$670.37			\$4,723.62
<u>CR 4625 South Park Circle</u>								
20002	Road surface repair	\$1,419.00	42.00	\$617.46		11/16/2017	11/16/2017	\$2,036.46

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4625 South Park Circle</b>								
		\$1,419.00	42.00	\$617.46				\$2,036.46
<b>CR 4626 WAVERLY WAY 30 MPH 0.4 mi.</b>								
18873	Patched - road surface	\$42.25	2.00	\$24.35	\$44.43	1/27/2017	1/27/2017	\$111.03
19311	Herbicide/weed spraying	\$116.80	8.00	\$134.56		6/14/2017	6/14/2017	\$251.36
		\$159.05	10.00	\$158.91	\$44.43			\$362.39
<b>CR 4627 GIBSON {Minor Collector*} 0.7 mi.</b>								
18980	Patched - road surface	\$84.50	4.00	\$48.70	\$193.50	2/24/2017	2/24/2017	\$326.70
18983	Patched - road surface	\$169.00	8.00	\$97.40	\$268.45	2/27/2017	2/27/2017	\$534.85
19227	Mow Right-of-Way	\$0.00	1.00	\$12.50		6/1/2017	6/1/2017	\$12.50
19320	Patched - road surface	\$0.00	0.00	\$0.00		6/19/2017	6/19/2017	\$0.00
19700	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/24/2017	8/24/2017	\$0.00
		\$253.50	13.00	\$158.60	\$461.95			\$874.05
<b>CR 4628 ROBBINS RD (35 MPH) {Minor Collector*} 1 mi.</b>								
18872	Patched - road surface	\$42.25	2.00	\$24.35	\$44.43	1/27/2017	1/27/2017	\$111.03
18900	Patched - road surface	\$0.00	0.00	\$0.00	\$63.28	2/6/2017	2/6/2017	\$63.28
18941	Trash/garbage picked-up	\$77.80	8.00	\$97.40		2/14/2017	2/14/2017	\$175.20
18979	Patched - road surface	\$84.50	4.00	\$48.70	\$150.00	2/24/2017	2/24/2017	\$283.20
19228	Mow Right-of-Way					6/1/2017	6/1/2017	\$0.00
19321	Patched - road surface	\$0.00	0.00	\$0.00		6/19/2017	6/19/2017	\$0.00
19740	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
19791	Patched - road surface	\$0.00	0.00	\$0.00		9/5/2017	9/5/2017	\$0.00
		\$204.55	14.00	\$170.45	\$257.71			\$632.71
<b>CR 4700 WARD (35 MPH) {Minor Collector} 2 mi.</b>								
18780	Road Cuvert (mark for dig tess)	\$26.00	2.00	\$38.03		1/3/2017	1/3/2017	\$64.03
18773	Road culvert - replaced	\$3,065.25	40.00	\$751.92	\$3,985.00	1/5/2017	1/5/2017	\$7,802.17
19561	Road base material - added	\$2,134.00	32.00	\$582.80	\$1,091.74	4/18/2017	4/18/2017	\$3,808.54
19088	Oil Sand Overlay / over new culvert	\$1,717.60	32.00	\$585.60	\$2,529.52	4/20/2017	4/20/2017	\$4,832.72
19173	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/18/2017	5/18/2017	\$0.00
19352	Road surface repair	\$781.00	12.00	\$199.04	\$1,455.21	6/30/2017	6/30/2017	\$2,435.25
19559	Asphalt overlay	\$5,982.00	88.00	\$1,588.40	\$30,604.95	8/1/2017	8/1/2017	\$38,175.35
19560	Asphalt overlay	\$5,982.00	91.00	\$1,665.13	\$47,276.04	8/3/2017	8/3/2017	\$54,923.17
19596	Patched - road surface	\$253.50	12.00	\$118.50		8/9/2017	8/9/2017	\$372.00
19615	Patched - road surface	\$253.50	12.00	\$118.50	\$260.19	8/9/2017	8/9/2017	\$632.19
19663	Mow Right-of-Way	\$0.00	3.00	\$37.50		8/9/2017	8/9/2017	\$37.50

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4700 WARD (35 MPH) {Minor Collector} 2 mi.</b>								
19856	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/20/2017	9/20/2017	\$0.00
19881	Trash/garbage picked-up	\$42.25	2.00	\$19.75		10/6/2017	10/6/2017	\$62.00
20072	Patch- FALL IN	\$42.25	3.00	\$40.50	\$12.50	12/26/2017	12/26/2017	\$95.25
		<u>\$20,279.35</u>	<u>329.00</u>	<u>\$5,745.67</u>	<u>\$87,215.15</u>			<u>\$113,240.17</u>
<b>CR 4700A WOODCREST (ext 4700) 0.2 mi.</b>								
19718	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<b>CR 4700B RUTH (ext 4700) 0.1 mi.</b>								
19719	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<b>CR 4702 NEW SUBDIVISION (between 4704 &amp; 4705) 1 mi.</b>								
19127	Inquiry about road status /Driveway	\$22.50	4.00	\$76.06		5/1/2017	5/1/2017	\$98.56
19586	Driveway culvert - installed/set	\$583.00	12.00	\$199.04		8/8/2017	8/8/2017	\$782.04
		<u>\$605.50</u>	<u>16.00</u>	<u>\$275.10</u>				<u>\$880.60</u>
<b>CR 4703 HOPEWELL CHURCH 0.1 mi.</b>								
18934	Patched - road surface	\$21.12	1.50	\$15.79	\$31.27	2/13/2017	2/13/2017	\$68.18
		<u>\$21.12</u>	<u>1.50</u>	<u>\$15.79</u>	<u>\$31.27</u>			<u>\$68.18</u>
<b>CR 4704 RAY ROAD 1 mi.</b>								
18810	Patched - road surface	\$84.50	4.00	\$48.70	\$225.00	1/13/2017	1/13/2017	\$358.20
18935	Patched - road surface	\$63.38	4.50	\$47.41	\$118.00	2/13/2017	2/13/2017	\$228.79
19150	Patched - road surface	\$84.50	6.00	\$63.20	\$150.00	5/5/2017	5/5/2017	\$297.70
19174	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/18/2017	5/18/2017	\$0.00
19662	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/8/2017	8/8/2017	\$25.00
19855	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/20/2017	9/20/2017	\$0.00
		<u>\$232.38</u>	<u>16.50</u>	<u>\$184.31</u>	<u>\$493.00</u>			<u>\$909.69</u>
<b>CR 4705 THOMAS FRANK 2 mi.</b>								
18812	Patched - road surface	\$42.25	2.00	\$24.35	\$17.25	1/13/2017	1/13/2017	\$83.85
19178	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/17/2017	5/17/2017	\$0.00
19661	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/8/2017	8/8/2017	\$25.00
19854	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/20/2017	9/20/2017	\$0.00
		<u>\$42.25</u>	<u>4.00</u>	<u>\$49.35</u>	<u>\$17.25</u>			<u>\$108.85</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4706 POWDER RIVER 2.2 mi.</b>								
18811	Patched - road surface	\$42.25	2.00	\$24.35	\$75.00	1/13/2017	1/13/2017	\$141.60
18932	Patched - road surface	\$126.75	6.00	\$73.05	\$165.79	2/10/2017	2/10/2017	\$365.59
19151	Patched - road surface	\$42.25	3.00	\$31.60	\$75.00	5/5/2017	5/5/2017	\$148.85
19177	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/17/2017	5/17/2017	\$0.00
19660	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/8/2017	8/8/2017	\$25.00
19834	Patched - road surface	\$84.50	4.00	\$39.50	\$75.00	10/2/2017	10/2/2017	\$199.00
		\$295.75	17.00	\$193.50	\$390.79			\$880.04
<b>CR 4708 SMITH LUMBER 2.1 mi.</b>								
19176	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/17/2017	5/17/2017	\$0.00
19578	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
19820	Trash/garbage picked-up	\$42.25	2.00	\$19.75		9/12/2017	9/12/2017	\$62.00
		\$42.25	2.00	\$19.75				\$62.00
<b>CR 4710 COOK-A 1.3 mi.</b>								
18804	Patched - road surface	\$84.50	4.00	\$48.70	\$186.00	1/11/2017	1/11/2017	\$319.20
19362	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/5/2017	7/5/2017	\$0.00
		\$84.50	4.00	\$48.70	\$186.00			\$319.20
<b>CR 4712 COOK-B 2.7 mi.</b>								
18859	Clean Culvert/Beaver Dam	\$92.12	4.00	\$77.66		1/25/2017	1/25/2017	\$169.78
18960	Clean Culvert/Beaver Dam	\$136.25	3.00	\$55.16		2/21/2017	2/21/2017	\$191.41
19001	Dead livestock/wildlife burial	\$272.50	4.00	\$76.06		3/2/2017	3/2/2017	\$348.56
19155	Patch- FALL IN	\$42.25	2.00	\$24.35	\$55.50	5/8/2017	5/8/2017	\$122.10
19161	Driveway culvert - installed/set	\$1,115.25	32.00	\$612.64	\$135.28	5/18/2017	5/18/2017	\$1,863.17
19244	Patched - road surface	\$42.25	2.00	\$33.64	\$45.14	6/12/2017	6/12/2017	\$121.03
19365	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19412	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/10/2017	7/10/2017	\$992.32
19413	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/11/2017	7/11/2017	\$992.32
19414	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/12/2017	7/12/2017	\$992.32
19462	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/13/2017	7/13/2017	\$992.32
19492	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/14/2017	7/14/2017	\$992.32
19491	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/17/2017	7/17/2017	\$992.32
19493	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/18/2017	7/18/2017	\$992.32
19494	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/19/2017	7/19/2017	\$992.32
19508	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/20/2017	7/20/2017	\$992.32
19507	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/21/2017	7/21/2017	\$992.32
19514	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/24/2017	7/24/2017	\$992.32
19515	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/25/2017	7/25/2017	\$992.32

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4712 COOK-B 2.7 mi.</b>								
19516	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/26/2017	7/26/2017	\$992.32
19760	Road culvert - replaced	\$916.50	19.00	\$346.46	\$422.93	8/30/2017	8/30/2017	\$1,685.89
19852	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/25/2017	9/25/2017	\$0.00
19894	Patched - road surface	\$126.75	3.00	\$37.50	\$88.50	10/9/2017	10/9/2017	\$252.75
		<u>\$13,767.87</u>	<u>173.00</u>	<u>\$3,139.63</u>	<u>\$747.35</u>			<u>\$17,654.85</u>
<b>CR 4713 KITCHENS 0.3 mi.</b>								
19061	Put up County Road Number sign 'NS'	\$9.72	1.00	\$17.87	\$20.61	3/30/2017	3/30/2017	\$48.20
		<u>\$9.72</u>	<u>1.00</u>	<u>\$17.87</u>	<u>\$20.61</u>			<u>\$48.20</u>
<b>CR 4714 Tiner (off 4712) 0.2 mi.</b>								
19363	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/5/2017	7/5/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<b>CR 4715 ALLIGATOR 1.6 mi.</b>								
19098	Cleared debris or fallen tree	\$343.62	6.00	\$116.49	\$146.25	4/24/2017	4/24/2017	\$606.36
19364	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19713	Patched - road surface	\$0.00	0.00	\$0.00		8/25/2017	8/25/2017	\$0.00
19723	Patched - road surface	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
19826	Cleared debris or fallen tree		6.00	\$107.06		9/25/2017	9/25/2017	\$107.06
19882	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/9/2017	10/9/2017	\$992.32
19895	Patched - road surface	\$126.75	3.00	\$37.50	\$97.94	10/9/2017	10/9/2017	\$262.19
19899	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/11/2017	10/11/2017	\$992.32
19909	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/12/2017	10/12/2017	\$992.32
19911	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		10/13/2017	10/13/2017	\$992.32
19987	Road culvert - cleaned/repared	\$2,026.00	24.00	\$398.08	\$650.00	11/8/2017	11/8/2017	\$3,074.08
		<u>\$5,888.37</u>	<u>71.00</u>	<u>\$1,236.41</u>	<u>\$894.19</u>			<u>\$8,018.97</u>
<b>CR 4716 Tiger</b>								
19381	Patched - road surface	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19974	Cut Brush/ Brush Cutter	\$424.00	4.00	\$70.76		11/7/2017	11/7/2017	\$494.76
19985	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		11/8/2017	11/8/2017	\$989.52
		<u>\$1,272.00</u>	<u>12.00</u>	<u>\$212.28</u>				<u>\$1,484.28</u>
<b>CR 4718 HALLMARK 0.4 mi.</b>								
19104	Mow Right-of-Way	\$0.00	0.50	\$6.25		4/25/2017	4/25/2017	\$6.25
19334	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19609	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
		<u>\$0.00</u>	<u>0.50</u>	<u>\$6.25</u>				<u>\$6.25</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4719 COUNTY BARN 0.3 mi.</u>								
18845	Patched - road surface	\$0.00	0.00	\$0.00		1/24/2017	1/24/2017	\$0.00
18892	Patched - road surface	\$126.75	6.00	\$73.05	\$59.00	2/3/2017	2/3/2017	\$258.80
19103	Mow Right-of-Way	\$0.00	1.00	\$12.50		4/25/2017	4/25/2017	\$12.50
19518	Mow Right-of-Way	\$0.00	1.00	\$12.50		7/26/2017	7/26/2017	\$12.50
19630	Patched - road surface	\$0.00	0.00	\$0.00		8/15/2017	8/15/2017	\$0.00
19806	Mow Right-of-Way	\$0.00	3.00	\$37.50		9/6/2017	9/6/2017	\$37.50
19983	Patched - road surface	\$42.25	2.00	\$19.75	\$59.00	11/7/2017	11/7/2017	\$121.00
		<u>\$169.00</u>	<u>13.00</u>	<u>\$155.30</u>	<u>\$118.00</u>			<u>\$442.30</u>
<u>CR 4720 LAMBRIGHT 0.3 mi.</u>								
19105	Mow Right-of-Way					4/25/2017	4/25/2017	\$0.00
19382	Patched - road surface	\$0.00	0.00	\$0.00		7/6/2017	7/6/2017	\$0.00
19608	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/9/2017	8/9/2017	\$0.00
19981	Patched - road surface	\$42.25	2.00	\$19.75	\$59.00	11/7/2017	11/7/2017	\$121.00
		<u>\$42.25</u>	<u>2.00</u>	<u>\$19.75</u>	<u>\$59.00</u>			<u>\$121.00</u>
<u>CR 4800 BAXTER RD (45 MPH) {Minor Collector*} 1.7 mi.</u>								
18927	Patched - road surface	\$0.00	0.00	\$0.00	\$90.38	2/9/2017	2/9/2017	\$90.38
18933	Patched - road surface	\$84.50	6.00	\$63.20	\$118.00	2/13/2017	2/13/2017	\$265.70
19091	Patched - road surface	\$42.25	2.00	\$24.35	\$75.00	4/21/2017	4/21/2017	\$141.60
19129	Cleared debris or fallen tree	\$161.50	3.00	\$55.72		5/3/2017	5/3/2017	\$217.22
19137	Cleared debris or fallen tree	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19179	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/16/2017	5/16/2017	\$0.00
19281	Patched - road surface	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
19573	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/3/2017	8/3/2017	\$0.00
19860	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/18/2017	9/18/2017	\$0.00
19879	Patched - road surface	\$84.50	4.00	\$39.50	\$34.50	10/6/2017	10/6/2017	\$158.50
		<u>\$372.75</u>	<u>15.00</u>	<u>\$182.77</u>	<u>\$317.88</u>			<u>\$873.40</u>
<u>CR 4801 DAM 1.1 mi.</u>								
18928	Patched - road surface	\$0.00	0.00	\$0.00	\$90.38	2/9/2017	2/9/2017	\$90.38
19283	Patched - road surface	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
19304	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19574	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/3/2017	8/3/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>	<u>\$106.88</u>			<u>\$106.88</u>
<u>CR 4802 PERKINS {Minor Collector*} 1 mi.</u>								
19181	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/16/2017	5/16/2017	\$0.00

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4802 PERKINS {Minor Collector*} 1 mi.</u>								
19282	Patched - road surface	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
19576	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/3/2017	8/3/2017	\$0.00
19880	Patched - road surface	\$42.25	2.00	\$19.75	\$34.50	10/6/2017	10/6/2017	\$96.50
		<u>\$42.25</u>	<u>2.00</u>	<u>\$19.75</u>	<u>\$34.50</u>			<u>\$96.50</u>
<u>CR 4803 OAKWOOD 1.5 mi.</u>								
18896	Put up 'Dead End' sign	\$19.45	2.00	\$35.73	\$91.00	2/3/2017	2/3/2017	\$146.18
18929	Patched - road surface	\$0.00	0.00	\$0.00	\$90.38	2/9/2017	2/9/2017	\$90.38
19180	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/16/2017	5/16/2017	\$0.00
19305	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19575	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/3/2017	8/3/2017	\$0.00
19861	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/18/2017	9/18/2017	\$0.00
		<u>\$19.45</u>	<u>2.00</u>	<u>\$35.73</u>	<u>\$197.88</u>			<u>\$253.06</u>
<u>CR 4804 UPPER ROOM {Minor Collector*} 1.1 mi.</u>								
18930	Patched - road surface	\$0.00	0.00	\$0.00	\$90.38	2/9/2017	2/9/2017	\$90.38
19187	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/15/2017	5/15/2017	\$0.00
19182	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/16/2017	5/16/2017	\$0.00
19317	Patched - road surface	\$0.00	0.00	\$0.00		6/19/2017	6/19/2017	\$0.00
19358	Patch- FALL IN	\$0.00	0.00	\$0.00		7/3/2017	7/3/2017	\$0.00
19577	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/7/2017	8/7/2017	\$0.00
19750	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
19862	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/18/2017	9/18/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>	<u>\$90.38</u>			<u>\$90.38</u>
<u>CR 4805 PLANTATION POINT (30 MPH) 1 mi.</u>								
19186	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/15/2017	5/15/2017	\$0.00
19319	Patched - road surface	\$0.00	0.00	\$0.00		6/19/2017	6/19/2017	\$0.00
19751	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4806 (off 4804) 0.4 mi.</u>								
19167	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/22/2017	5/22/2017	\$0.00
19318	Patched - road surface	\$0.00	0.00	\$0.00		6/19/2017	6/19/2017	\$0.00
19752	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4807 VFW</u>								
18881	Patched - road surface	\$42.25	2.00	\$24.35	\$61.95	1/30/2017	1/30/2017	\$128.55

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4807 VFW</u>								
19183	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/15/2017	5/15/2017	\$0.00
19664	Mow Right-of-Way	\$0.00	1.00	\$12.50		8/9/2017	8/9/2017	\$12.50
		\$42.25	3.00	\$36.85	\$61.95			\$141.05
<u>CR 4808 Impala South (30 MPH)</u>								
19185	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/15/2017	5/15/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4810 VIEWPOINT (off Bear Creek) 0.3 mi.</u>								
19026	Patch- FALL IN	\$126.75	6.00	\$73.05	\$270.22	3/21/2017	3/21/2017	\$470.02
19047	Patched - road surface	\$169.00	8.00	\$97.40	\$269.04	3/24/2017	3/24/2017	\$535.44
19197	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/10/2017	5/10/2017	\$0.00
19300	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19378	Patch- FALL IN	\$42.25	1.00	\$12.50	\$14.75	7/5/2017	7/5/2017	\$69.50
19671	Mow Right-of-Way	\$0.00	0.50	\$6.25		8/14/2017	8/14/2017	\$6.25
19720	Patched - road surface	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
		\$338.00	15.50	\$189.20	\$570.51			\$1,097.71
<u>CR 4811 PEEWEE 1.5 mi.</u>								
19323	Patched - road surface	\$84.50	4.00	\$67.28	\$65.49	6/23/2017	6/23/2017	\$217.27
19333	Patched - road surface	\$253.50	12.00	\$201.84	\$192.75	6/26/2017	6/26/2017	\$648.09
19335	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19934	Cut Brush/ Brush Cutter	\$424.00	4.00	\$70.76		10/20/2017	10/20/2017	\$494.76
19949	Cut Brush/ Brush Cutter	\$424.00	4.00	\$70.76		10/24/2017	10/24/2017	\$494.76
19950	Cut Brush/ Brush Cutter	\$848.00	8.00	\$141.52		10/25/2017	10/25/2017	\$989.52
19970	Patched - road surface	\$84.50	4.00	\$39.50	\$59.00	10/30/2017	10/30/2017	\$183.00
19982	Patched - road surface	\$42.25	2.00	\$19.75	\$59.00	11/7/2017	11/7/2017	\$121.00
		\$2,160.75	38.00	\$611.41	\$376.24			\$3,148.40
<u>CR 4812 Peninsula Point {Minor Collector*} (35 MPH) 40,000 lb 1 mi.</u>								
19191	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/12/2017	5/12/2017	\$0.00
19284	Patched - road surface	\$0.00	0.00	\$0.00		6/13/2017	6/13/2017	\$0.00
19295	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19410	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/6/2017	7/6/2017	\$992.32
19411	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/7/2017	7/7/2017	\$992.32
19501	Patched - road surface	\$42.25	1.00	\$12.50	\$17.46	7/21/2017	7/21/2017	\$72.21
19753	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
19857	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/18/2017	9/18/2017	\$0.00



ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4812 Peninsula Point {Minor Collector*} (35 MPH) 40,000 lb 1 mi.</u>								
19832	Patch- FALL IN	\$84.50	4.00	\$39.50	\$75.00	10/2/2017	10/2/2017	\$199.00
		\$1,822.75	21.00	\$340.64	\$108.96			\$2,272.35
<u>CR 4812A Peninsula Circle 0.7 mi.</u>								
19296	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
		\$0.00	0.00	\$0.00	\$16.50			\$16.50
<u>CR 4812B West Circle 0.04 mi.</u>								
18968	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4812C East Circle 0.04 mi.</u>								
18969	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4812D Dorsey Ln.</u>								
18970	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
19297	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
		\$0.00	0.00	\$0.00	\$16.50			\$16.50
<u>CR 4812E Dorsey Circle 0.08 mi.</u>								
18971	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4812F Dorsey Drive 0.51 mi.</u>								
18805	Blade- Patch road surface	\$1,214.75	24.00	\$441.28	\$3,234.03	1/12/2017	1/12/2017	\$4,890.06
18972	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
		\$1,214.75	24.00	\$441.28	\$3,234.03			\$4,890.06
<u>CR 4812G Crestview Rd (Timberlake Estates) 0.69 mi.</u>								
18973	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
19754	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		\$0.00	0.00	\$0.00				\$0.00
<u>CR 4812H Sherwood Rd. (Timberlake Estates) 0.31 mi.</u>								
18799	Cleaned ditches /Between Kim Ln And Tanglewood	\$1,270.50	21.00	\$418.11		1/11/2017	1/11/2017	\$1,688.61
18855	Road surface repair	\$761.00	12.00	\$220.64	\$1,612.53	1/25/2017	1/25/2017	\$2,594.17

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4812H Sherwood Rd. (Timberlake Estates) 0.31 mi.</u>								
18974	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
19755	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		<u>\$2,031.50</u>	<u>33.00</u>	<u>\$638.75</u>	<u>\$1,612.53</u>			<u>\$4,282.78</u>
<u>CR 4812J Kim Ln (Timberlake Estates) 0.08 mi.</u>								
18975	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
19756	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>CR 4812K TANGLEWOOD (Timberlake Estates)</u>								
18976	Patched - road surface	\$0.00	0.00	\$0.00		2/23/2017	2/23/2017	\$0.00
19130	Cleared debris or fallen tree	\$161.50	6.00	\$165.46		5/3/2017	5/3/2017	\$326.96
19138	Cleared debris or fallen tree	\$0.00	0.00	\$0.00		5/4/2017	5/4/2017	\$0.00
19757	Patched - road surface	\$0.00	0.00	\$0.00		8/29/2017	8/29/2017	\$0.00
		<u>\$161.50</u>	<u>6.00</u>	<u>\$165.46</u>				<u>\$326.96</u>
<u>CR 4817 PHANTOM (30 MPH) 1 mi.</u>								
19003	Road surface repair /water line	\$42.25	2.00	\$24.35	\$59.00	3/7/2017	3/7/2017	\$125.60
19021	Patched - road surface	\$42.25	2.00	\$24.35	\$75.00	3/17/2017	3/17/2017	\$141.60
19195	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/11/2017	5/11/2017	\$0.00
19298	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19548	Patched - road surface	\$84.50	2.00	\$25.00	\$39.53	7/26/2017	7/26/2017	\$149.03
19668	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/14/2017	8/14/2017	\$25.00
		<u>\$169.00</u>	<u>8.00</u>	<u>\$98.70</u>	<u>\$190.03</u>			<u>\$457.73</u>
<u>CR 4819 GRUBBS 0.2 mi.</u>								
19022	Patched - road surface	\$21.12	1.00	\$12.17	\$37.50	3/17/2017	3/17/2017	\$70.79
		<u>\$21.12</u>	<u>1.00</u>	<u>\$12.17</u>	<u>\$37.50</u>			<u>\$70.79</u>
<u>CR 4825 BEARCREEK {Minor Collector*} 1.5 mi.</u>								
18864	Asphalt overlay Over New Culvert	\$737.00	12.00	\$220.64	\$968.76	1/26/2017	1/26/2017	\$1,926.40
19050	Patched - road surface	\$169.00	8.00	\$97.40	\$452.25	3/28/2017	3/28/2017	\$718.65
19193	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/11/2017	5/11/2017	\$0.00
19299	Patched - road surface	\$0.00	0.00	\$0.00	\$51.00	6/14/2017	6/14/2017	\$51.00
19379	Patched - road surface	\$42.25	1.00	\$12.50	\$59.00	7/5/2017	7/5/2017	\$113.75
19623	Patched - road surface	\$0.00	0.00	\$0.00		8/11/2017	8/11/2017	\$0.00
19669	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/14/2017	8/14/2017	\$25.00
		<u>\$948.25</u>	<u>23.00</u>	<u>\$355.54</u>	<u>\$1,531.01</u>			<u>\$2,834.80</u>

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4825A BEARCREEK CIRCLE 0.2 mi.</u>								
19194	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/11/2017	5/11/2017	\$0.00
19670	Mow Right-of-Way	\$0.00	1.00	\$12.50		8/14/2017	8/14/2017	\$12.50
		\$0.00	1.00	\$12.50				\$12.50
<u>CR 4826 HOPSON 1.7 mi.</u>								
18795	Cut Brush/ Brush Cutter	\$1,608.00	16.00	\$278.32		1/9/2017	1/9/2017	\$1,886.32
18990	Patched - road surface	\$126.75	6.00	\$73.05	\$134.22	2/28/2017	2/28/2017	\$334.02
19192	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/11/2017	5/11/2017	\$0.00
19301	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19674	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/15/2017	8/15/2017	\$25.00
19722	Patched - road surface	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
		\$1,734.75	24.00	\$376.37	\$150.72			\$2,261.84
<u>CR 4826A Two Mile Cir. (off Hopson)</u>								
19302	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19672	Mow Right-of-Way	\$0.00	1.00	\$12.50		8/15/2017	8/15/2017	\$12.50
		\$0.00	1.00	\$12.50	\$16.50			\$29.00
<u>CR 4827 BLUEBIRD 0.5 mi.</u>								
19149	Patched - road surface	\$42.25	3.00	\$31.60	\$75.00	5/5/2017	5/5/2017	\$148.85
19303	Patched - road surface	\$0.00	0.00	\$0.00	\$16.50	6/14/2017	6/14/2017	\$16.50
19673	Mow Right-of-Way	\$0.00	0.00	\$0.00		8/15/2017	8/15/2017	\$0.00
19721	Patched - road surface	\$0.00	0.00	\$0.00		8/28/2017	8/28/2017	\$0.00
		\$42.25	3.00	\$31.60	\$91.50			\$165.35
<u>CR 4828 ROUNSAVALL 2.2 mi.</u>								
19449	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
19793	Cleared debris or fallen tree	\$714.00	12.00	\$214.12		9/5/2017	9/5/2017	\$928.12
		\$714.00	12.00	\$214.12				\$928.12
<u>CR 4829 TINDEL-B 0.9 mi.</u>								
18843	Patched - road surface	\$84.50	4.00	\$48.70	\$206.50	1/23/2017	1/23/2017	\$339.70
19450	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
		\$84.50	4.00	\$48.70	\$206.50			\$339.70
<u>CR 4830 COY TERREL 0.6 mi.</u>								
18844	Patched - road surface	\$10.56	0.50	\$6.09	\$14.75	1/23/2017	1/23/2017	\$31.40
19451	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/10/2017	7/10/2017	\$0.00
		\$10.56	0.50	\$6.09	\$14.75			\$31.40

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4831 Melvin Pool 0.4 mi.</b>								
19371	Mow Right-of-Way					7/7/2017	7/7/2017	\$0.00
								\$0.00
<b>CR 4832 LEDBETTER 0.7 mi.</b>								
19370	Mow Right-of-Way					7/7/2017	7/7/2017	\$0.00
19850	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/25/2017	9/25/2017	\$0.00
19969	Patched - road surface	\$84.50	4.00	\$39.50	\$66.08	10/30/2017	10/30/2017	\$190.08
		\$84.50	4.00	\$39.50	\$66.08			\$190.08
<b>CR 4833 JOHN MARK 1.5 mi.</b>								
19243	Patched - road surface	\$42.25	2.00	\$33.64	\$47.55	6/12/2017	6/12/2017	\$123.44
19368	Mow Right-of-Way					7/5/2017	7/5/2017	\$0.00
19853	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/21/2017	9/21/2017	\$0.00
19896	Cattle guard - installed	\$1,428.00	32.00	\$528.24	\$2,200.31	10/10/2017	10/10/2017	\$4,156.55
19961	Patched - road surface	\$42.25	2.00	\$19.75	\$43.81	10/24/2017	10/24/2017	\$105.81
19968	Patched - road surface	\$84.50	4.00	\$39.50	\$59.00	10/30/2017	10/30/2017	\$183.00
		\$1,597.00	40.00	\$621.13	\$2,350.67			\$4,568.80
<b>CR 4834 PeeWee Dirt RD</b>								
19241	Patched - road surface	\$42.25	2.00	\$33.64	\$47.55	6/12/2017	6/12/2017	\$123.44
		\$42.25	2.00	\$33.64	\$47.55			\$123.44
<b>CR 4835 COLEMAN 2 mi.</b>								
18931	Patched - road surface	\$84.50	4.00	\$48.70	\$165.79	2/10/2017	2/10/2017	\$298.99
19242	Patched - road surface	\$42.25	2.00	\$33.64	\$47.55	6/12/2017	6/12/2017	\$123.44
19959	Patched - road surface	\$84.50	4.00	\$39.50	\$43.81	10/24/2017	10/24/2017	\$167.81
		\$211.25	10.00	\$121.84	\$257.15			\$590.24
<b>CR 4836 DUCKER 0.1 mi.</b>								
19960	Patched - road surface	\$84.50	4.00	\$39.50	\$43.81	10/24/2017	10/24/2017	\$167.81
		\$84.50	4.00	\$39.50	\$43.81			\$167.81
<b>CR 4837 FORESTER DR. 1.1 mi.</b>								
19237	Assisted other precinct	\$296.00	8.00	\$169.12		6/2/2017	6/2/2017	\$465.12
19236	Assisted other precinct	\$296.00	8.00	\$169.12		6/5/2017	6/5/2017	\$465.12
19235	Assisted other precinct	\$296.00	8.00	\$169.12		6/6/2017	6/6/2017	\$465.12
19369	Mow Right-of-Way					7/7/2017	7/7/2017	\$0.00
19851	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/25/2017	9/25/2017	\$0.00
19962	Patched - road surface	\$84.50	4.00	\$39.50	\$43.81	10/24/2017	10/24/2017	\$167.81
		\$972.50	28.00	\$546.86	\$43.81			\$1,563.17

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<b>CR 4838 GARNER 0.5 mi.</b>								
19324	Patched - road surface	\$42.25	2.00	\$33.64	\$59.00	6/23/2017	6/23/2017	\$134.89
19847	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/26/2017	9/26/2017	\$0.00
19984	Patched - road surface	\$42.25	1.00	\$12.50	\$14.16	11/7/2017	11/7/2017	\$68.91
		<u>\$84.50</u>	<u>3.00</u>	<u>\$46.14</u>	<u>\$73.16</u>			<u>\$203.80</u>
<b>CR 4908 JOE BROWNING 0.7 mi.</b>								
18880	Patched - road surface	\$42.25	2.00	\$24.35	\$61.95	1/30/2017	1/30/2017	\$128.55
19188	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/12/2017	5/12/2017	\$0.00
19336	Patched - road surface	\$0.00	0.00	\$0.00		6/29/2017	6/29/2017	\$0.00
19421	Cleared debris or fallen tree	\$107.00	14.00	\$361.62		7/10/2017	7/10/2017	\$468.62
19666	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/10/2017	8/10/2017	\$25.00
19859	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/18/2017	9/18/2017	\$0.00
19825	Remove Dead Tree		12.00	\$214.12		9/25/2017	9/25/2017	\$214.12
19828	Asphalt overlay	\$4,487.00	72.00	\$1,094.96	\$29,795.58	9/28/2017	9/28/2017	\$35,377.54
19829	Asphalt overlay	\$646.55	32.00	\$476.72	\$415.38	9/29/2017	9/29/2017	\$1,538.65
19833	Patched - around mailboxes	\$84.50	4.00	\$39.50	\$130.50	10/2/2017	10/2/2017	\$254.50
		<u>\$5,367.30</u>	<u>138.00</u>	<u>\$2,236.27</u>	<u>\$30,403.41</u>			<u>\$38,006.98</u>
<b>CR 4910 ROBY 0.9 mi.</b>								
19189	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/12/2017	5/12/2017	\$0.00
19667	Mow Right-of-Way	\$0.00	2.00	\$25.00		8/10/2017	8/10/2017	\$25.00
		<u>\$0.00</u>	<u>2.00</u>	<u>\$25.00</u>				<u>\$25.00</u>
<b>CR 4911 DEER RUN 0.6 mi.</b>								
18879	Patched - road surface	\$42.25	2.00	\$24.35	\$61.95	1/30/2017	1/30/2017	\$128.55
19184	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/15/2017	5/15/2017	\$0.00
19549	Patched - road surface	\$84.50	2.00	\$25.00	\$39.53	7/26/2017	7/26/2017	\$149.03
19675	Mow Right-of-Way	\$0.00	1.00	\$12.50		8/15/2017	8/15/2017	\$12.50
		<u>\$126.75</u>	<u>5.00</u>	<u>\$61.85</u>	<u>\$101.48</u>			<u>\$290.08</u>
<b>CR 4912 CRYSTAL 0.2 mi.</b>								
19109	Patched - road surface	\$0.00	0.00	\$0.00		4/28/2017	4/28/2017	\$0.00
19190	Mow Right-of-Way	\$0.00	0.00	\$0.00		5/12/2017	5/12/2017	\$0.00
19502	Patched - road surface	\$42.25	1.00	\$12.50	\$17.46	7/21/2017	7/21/2017	\$72.21
		<u>\$42.25</u>	<u>1.00</u>	<u>\$12.50</u>	<u>\$17.46</u>			<u>\$72.21</u>
<b>CR 4913 DUSTY RD. 1.2 mi.</b>								
18781	Road Cuvert (mark for dig tess)	\$26.00	2.00	\$38.03		1/3/2017	1/3/2017	\$64.03
18793	Moved equipment to work site	\$420.00	12.00	\$220.64		1/6/2017	1/6/2017	\$640.64

ID:	Activity:	Equip. Cost:	Labor Hrs:	Labor Cost:	Material Cost:	Start Date:	Stop Date:	Total Cost:
<u>CR 4913 DUSTY RD. 1.2 mi.</u>								
18794	/ Remove Trees	\$872.00	24.00	\$473.36		1/9/2017	1/9/2017	\$1,345.36
18797	Road culvert - replaced	\$1,076.00	32.00	\$614.88	\$865.63	1/10/2017	1/10/2017	\$2,556.51
18798	Road base material - added	\$134.50	3.00	\$59.73	\$120.65	1/11/2017	1/11/2017	\$314.88
18856	Road surface repair	\$761.00	12.00	\$220.64	\$1,611.15	1/25/2017	1/25/2017	\$2,592.79
19110	Patched - road surface	\$0.00	0.00	\$0.00		4/28/2017	4/28/2017	\$0.00
19409	Cut Brush/ Brush Cutter	\$848.00	8.00	\$144.32		7/5/2017	7/5/2017	\$992.32
19503	Patched - road surface	\$42.25	1.00	\$12.50	\$17.46	7/21/2017	7/21/2017	\$72.21
19547	Patched - road surface	\$84.50	2.00	\$25.00	\$39.53	7/26/2017	7/26/2017	\$149.03
19665	Mow Right-of-Way	\$0.00	1.00	\$12.50		8/10/2017	8/10/2017	\$12.50
19858	Mow Right-of-Way	\$0.00	0.00	\$0.00		9/18/2017	9/18/2017	\$0.00
		<u>\$4,264.25</u>	<u>97.00</u>	<u>\$1,821.60</u>	<u>\$2,654.42</u>			<u>\$8,740.27</u>
<u>Elm Street</u>								
18836	Trimmed brush or trees		16.00	\$310.64		1/23/2017	1/23/2017	\$310.64
18948	Stabilized ditch erosion	\$561.15	16.00	\$305.20		2/15/2017	2/15/2017	\$866.35
19543	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/26/2017	7/26/2017	\$0.00
19564	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
19640	Patched - road surface	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
19942	Blade- Patch road surface	\$726.00	16.00	\$282.64	\$833.52	10/19/2017	10/19/2017	\$1,842.16
		<u>\$1,287.15</u>	<u>48.00</u>	<u>\$898.48</u>	<u>\$833.52</u>			<u>\$3,019.15</u>
<u>Elwood</u>								
19639	Patched - road surface	\$0.00	0.00	\$0.00		8/17/2017	8/17/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>Hunt Oil Road</u>								
19542	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/26/2017	7/26/2017	\$0.00
19563	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
		<u>\$0.00</u>	<u>0.00</u>	<u>\$0.00</u>				<u>\$0.00</u>
<u>Shady Lane</u>								
19566	Mow Right-of-Way	\$0.00	0.00	\$0.00		7/31/2017	7/31/2017	\$0.00
19603	Mow Right-of-Way					8/7/2017	8/7/2017	\$0.00
19914	Patched - road surface	\$253.50	18.00	\$162.00	\$142.19	10/13/2017	10/13/2017	\$557.69
		<u>\$253.50</u>	<u>18.00</u>	<u>\$162.00</u>	<u>\$142.19</u>			<u>\$557.69</u>
	<b>Report Totals:</b>	<b>\$442,935.55</b>	<b>8,218.00</b>	<b>\$137,746.70</b>	<b>\$725,961.22</b>			<b>\$1,306,643.47</b>



**Road & Bridge  
Annual Road Report**

**FY - 2017**

**PRECINCT 4**

**SIGNAGE REPORT**



Daily Work History (by Type of Work)

Period: 1/1/2017 - 12/31/2017

Work Category: Signs

Location: All locations in all areas

All Assignments

Henderson County

**Signs: Put up County road number sign (1)**

Location	Date	Work Done
CR 4234	10/4/2017	Put up County road number sign

**Signs: Put up County Road Number sign 'NS' (7)**

Location	Date	Work Done
CR 4518 BURNETT / SUPER COP (35MPH)	1/17/2017	Put up County Road Number sign 'NS'
CR 4334 N.Y. CHURCH	3/30/2017	Put up County Road Number sign 'NS'
CR 4615 LITTLE ACRES	3/30/2017	Put up County Road Number sign 'NS'
CR 4713 KITCHENS	3/30/2017	Put up County Road Number sign 'NS'
2 Multi Locations	8/25/2017	Put up County Road Number sign 'NS'
2 Multi Locations	8/28/2017	Put up County Road Number sign 'NS'
2 Multi Locations	11/20/2017	Put up County Road Number sign 'NS'

**Signs: Put up 'Speed Limit' sign (1)**

Location	Date	Work Done
CR 4336 MYRTLE SPRINGS (45 MPH)	3/30/2017	Put up 'Speed Limit' sign

**Signs: Put up 'Stop' sign (2)**

Location	Date	Work Done
CR 4400 ROCKHILL (35 MPH)	3/30/2017	Put up 'Stop' sign
CR 4234	10/4/2017	Put up 'Stop' sign

**Signs: Put up STOP sign 'NS' (1)**

Location	Date	Work Done
CR 4613 OLD 19 (35 MPH)	1/17/2017	Put up STOP sign 'NS'



Daily Work History (by Type of Work)

Period: 1/1/2017 - 12/31/2017

Work Category: Signs

Location: All locations in all areas

All Assignments

Henderson County

**Signs: Put up 'Dead End' sign (2)**

Location	Date	Work Done
CR 4803 OAKWOOD	2/3/2017	Put up 'Dead End' sign
CR 4234	10/4/2017	Put up 'Dead End' sign

**Signs: Other sign work (3)**

Location	Date	Work Done
CR 4400 ROCKHILL (35 MPH)	2/14/2017	/ Reinstall trash pick-up signs
Pct 4 barn	8/24/2017	/ Build Signs
Pct 4 barn	10/4/2017	Build Road Number Signs