

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types

Location: All locations in all areas

All Assignments

Henderson County

Roads: Bladed - pulled shoulders/ditches (1)

Location	Date	Work Done
CR 4348 SHOLAR'S	12/6/2017	Bladed - pulled shoulders/ditches

Roads: Blade- Patch road surface (5)

Location	Date	Work Done
CR 4400 ROCKHILL (35 MPH)	10/12/2017	Blade- Patch road surface
Elm Street	10/19/2017	Blade- Patch road surface
CR 4334 N.Y. CHURCH	11/28/2017	Blade- Patch road surface
CR 4336 MYRTLE SPRINGS (45 MPH)	11/28/2017	Blade- Patch road surface
CR 4516 HAIRGROVE	11/28/2017	Blade- Patch road surface

Roads: Patched - road surface (54)

Location	Date	Work Done
CR 4706 POWDER RIVER	10/2/2017	Patched - road surface
CR 4117 B. VILLE {Minor Collector*}	10/4/2017	Patched - road surface
CR 4239 BOLES	10/4/2017	Patched - road surface
CR 4224 STELLA WALKER (45 MPH)	10/5/2017	Patched - road surface
CR 4236 DANSBY (ext 4235)	10/5/2017	Patched - road surface
CR 4325 N.Y.- MOORE STATION {Minor Collector}	10/5/2017	Patched - road surface
CR 4800 BAXTER RD (45 MPH) {Minor Collector*}	10/6/2017	Patched - road surface
CR 4802 PERKINS {Minor Collector*}	10/6/2017	Patched - road surface
CR 4712 COOK-B	10/9/2017	Patched - road surface
CR 4715 ALLIGATOR	10/9/2017	Patched - road surface
CR 4217 MANOY (Pleasant Ridge)	10/10/2017	Patched - road surface
CR 4222 KENNEDY CORNER (45 MPH)	10/10/2017	Patched - road surface
CR 4223 MAYOR RD (ext 4217)	10/10/2017	Patched - road surface
CR 4402 ROSENBERG (off FM 2588) (35 MPH)	10/11/2017	Patched - road surface

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types

Location: All locations in all areas

All Assignments

Henderson County

Roads: Patched - road surface (54)

Location	Date	Work Done
CR 4528 COUNTY LINE (35 MPH)	10/11/2017	Patched - road surface
CR 4600 CARROLL SPRINGS (35 MPH)	10/11/2017	Patched - road surface
Shady Lane	10/13/2017	Patched - road surface
CR 4511 BAXTER/PINEGROVE (45 MPH) {Minor Collector*}	10/16/2017	Patched - road surface
CR 4515 RICHARDSON (45 MPH)	10/16/2017	Patched - road surface
CR 4515 RICHARDSON (45 MPH)	10/18/2017	Patched - road surface
CR 4516 HAIRGROVE	10/19/2017	Patched - road surface
CR 41107 MILL RUN RD (35 MPH)	10/23/2017	Patched - road surface
CR 4613 OLD 19 (35 MPH)	10/23/2017	Patched - road surface
CR 4614 HOLDER (35 MPH)	10/23/2017	Patched - road surface
CR 4833 JOHN MARK	10/24/2017	Patched - road surface
CR 4835 COLEMAN	10/24/2017	Patched - road surface
CR 4836 DUCKER	10/24/2017	Patched - road surface
CR 4837 FORESTER DR.	10/24/2017	Patched - road surface
CR 4537 E. COLLEGE	10/26/2017	Patched - road surface
CR 4538 COLONIAL CIRCLE	10/26/2017	Patched - road surface
CR 4811 PEEWEE	10/30/2017	Patched - road surface
CR 4832 LEDBETTER	10/30/2017	Patched - road surface
CR 4833 JOHN MARK	10/30/2017	Patched - road surface
CR 4719 COUNTY BARN	11/7/2017	Patched - road surface
CR 4720 LAMBRIGHT	11/7/2017	Patched - road surface
CR 4811 PEEWEE	11/7/2017	Patched - road surface
CR 4838 GARNER	11/7/2017	Patched - road surface
CR 4201E Ridge Rd. (Woodridge)	11/9/2017	Patched - road surface
CR 4201F Quil Cutoff (Woodridge)	11/9/2017	Patched - road surface

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Roads: Patched - road surface (54)

Location	Date	Work Done
CR 4201G Hillcrest (Woodridge)	11/9/2017	Patched - road surface
CR 4201H Pineview (Woodridge)	11/9/2017	Patched - road surface
CR 4307 GUSSIE LEE (35 MPH) {Minor Collector}	11/29/2017	Patched - road surface
CR 4309 LIVE COVE (off 4307)	11/29/2017	Patched - road surface
CR 4317A MOORE STA. LOOP	11/29/2017	Patched - road surface
CR 4303 GENE LINSEY (off 315)	11/30/2017	Patched - road surface
CR 4317A MOORE STA. LOOP	11/30/2017	Patched - road surface
CR 4322 TIP TOP	11/30/2017	Patched - road surface
CR 4202 CAPE (off FM 3506)	12/1/2017	Patched - road surface
CR 4213 TWIN OAKS (off FM 315)	12/1/2017	Patched - road surface
CR 41002 RANCH ROAD (Oak Manor)	12/4/2017	Patched - road surface
CR 41511 (Larry Anding)	12/4/2017	Patched - road surface
CR 41513	12/4/2017	Patched - road surface
CR 41515 McGEE NURSEY	12/4/2017	Patched - road surface
CR 4312 FOREST GROVE-B	12/21/2017	Patched - road surface

Roads: Patch- FALL IN (5)

Location	Date	Work Done
CR 4812 Peninsula Point {Minor Collector*} (35 MPH) 40,000 lb	10/2/2017	Patch- FALL IN
CR 4400 ROCKHILL (35 MPH)	12/19/2017	Patch- FALL IN
CR 4516 HAIRGROVE	12/22/2017	Patch- FALL IN
CR 4325 N.Y.- MOORE STATION {Minor Collector}	12/26/2017	Patch- FALL IN
CR 4700 WARD (35 MPH) {Minor Collector}	12/26/2017	Patch- FALL IN

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Roads: Patched - around mailboxes (1)

Location	Date	Work Done
CR 4908 JOE BROWNING	10/2/2017	Patched - around mailboxes

Roads: Asphalt overlay (7)

Location	Date	Work Done
CR 4403 SISSY'S	11/2/2017	Asphalt overlay
Fair Ground	11/7/2017	Asphalt overlay Parking Lot
Fair Park	11/14/2017	Asphalt overlay
Fair Park	11/15/2017	Asphalt overlay
Fair Park	11/20/2017	Asphalt overlay
CR 4348 SHOLAR'S	12/12/2017	Asphalt overlay
CR 4348 SHOLAR'S	12/13/2017	Asphalt overlay

Roads: Laid tack oil (1)

Location	Date	Work Done
CR 4350 LARUE CEMETARY	12/11/2017	Laid tack oil Primer

Roads: Road base material - added (9)

Location	Date	Work Done
155 Brierwood Dr (Brierwood Bay)	10/6/2017	Road base material - added
155 Forest Hill Dr (Brierwood Bay)	10/18/2017	Road base material - added (lift road over culvert)
155 Forest Hill Dr (Brierwood Bay)	10/19/2017	Road base material - added
CR 4332 TINDEL-A (off FM 607)	11/6/2017	Road base material - added
CR 4350 LARUE CEMETARY	12/6/2017	Road base material - added
CR 4350 LARUE CEMETARY	12/7/2017	Road base material - added
CR 4350 LARUE CEMETARY	12/8/2017	Road base material - added
CR 4340 ROY SMITH (ext 4336)	12/15/2017	Road base material - added

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Roads: Road base material - added (9)

Location	Date	Work Done
CR 4340 ROY SMITH (ext 4336)	12/18/2017	Road base material - added

Roads: Road surface repair (1)

Location	Date	Work Done
CR 4625 South Park Circle	11/16/2017	Road surface repair

Roads: Material - stockpiled (2)

Location	Date	Work Done
Pct 4 barn	12/27/2017	Material - stockpiled
Pct 4 barn	12/28/2017	Material - stockpiled

Roads: Cattle guard - installed (1)

Location	Date	Work Done
CR 4833 JOHN MARK	10/10/2017	Cattle guard - installed

Drainage: Cleaned ditches (5)

Location	Date	Work Done
CR 4235 JOHN'S (35 MPH)	10/12/2017	Cleaned ditches
CR 4235 JOHN'S (35 MPH)	10/13/2017	Cleaned ditches
CR 4117 B. VILLE {Minor Collector*}	10/24/2017	Cleaned ditches
CR 4117 B. VILLE {Minor Collector*}	10/25/2017	Cleaned ditches
CR 4317A MOORE STA. LOOP	11/17/2017	Cleaned ditches

Drainage: Cleaned outfall ditch (2)

Location	Date	Work Done
CR 4235 JOHN'S (35 MPH)	11/13/2017	Cleaned outfall ditch

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Drainage: Cleaned outfall ditch (2)

Location	Date	Work Done
CR 4515 RICHARDSON (45 MPH)	12/21/2017	Cleaned outfall ditch

Drainage: Clean Culvert/Beaver Dam (6)

Location	Date	Work Done
CR 41515 McGEE NURSEY	10/18/2017	Clean Culvert/Beaver Dam (needs more work)
CR 41515 McGEE NURSEY	10/23/2017	Clean Culvert/Beaver Dam
CR 4401 DOUGLAS LOOP	10/23/2017	Clean Culvert/Beaver Dam
CR 4403 SISSY'S	10/23/2017	Clean Culvert/Beaver Dam
CR 4516 HAIRGROVE	11/27/2017	Clean Culvert/Beaver Dam
CR 4516 HAIRGROVE	12/20/2017	Clean Culvert/Beaver Dam

Drainage: Stabilized ditch erosion (1)

Location	Date	Work Done
CR 4520E RAINBOW-E (Rainbo Gate to 4402	11/22/2017	Stabilized ditch erosion

Drainage: Road culvert - cleaned/repared (1)

Location	Date	Work Done
CR 4715 ALLIGATOR	11/8/2017	Road culvert - cleaned/repared

Drainage: Road Culvert (measure size for replacment) (1)

Location	Date	Work Done
CR 4515 RICHARDSON (45 MPH)	12/21/2017	Road Culvert (measure size for replacment)

Drainage: Road culvert - replaced (2)

Location	Date	Work Done
155 Brierwood Dr (Brierwood Bay)	10/5/2017	Road culvert - replaced

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types

All Assignments

Location: All locations in all areas

Henderson County

Drainage: Road culvert - replaced (2)

Location	Date	Work Done
155 Forest Hill Dr (Brierwood Bay)	10/17/2017	Road culvert - replaced

Drainage: Road Culvert clean inlet (Drift Wood) (1)

Location	Date	Work Done
CR 4515 RICHARDSON (45 MPH)	12/20/2017	Road Culvert clean inlet (Drift Wood)

Drainage: Other drainage work (1)

Location	Date	Work Done
155 Forest Hill Dr (Brierwood Bay)	10/6/2017	waterline damaged reschedule

Driveway work: Driveway entrance - repaired (1)

Location	Date	Work Done
CR 4524 BUBBA BURNETT	10/9/2017	Driveway entrance - repaired

Driveway work: Other driveway work (1)

Location	Date	Work Done
CR 4625 South Park Circle	11/16/2017	Other driveway work

Right-of-way: Cut Brush/ Brush Cutter (53)

Location	Date	Work Done
CR 4307 GUSSIE LEE (35 MPH) {Minor Collector}	10/2/2017	Cut Brush/ Brush Cutter
CR 4307 GUSSIE LEE (35 MPH) {Minor Collector}	10/3/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/4/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/5/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/6/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/9/2017	Cut Brush/ Brush Cutter

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Right-of-way: Cut Brush/ Brush Cutter (53)

Location	Date	Work Done
CR 4715 ALLIGATOR	10/9/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/11/2017	Cut Brush/ Brush Cutter
CR 4715 ALLIGATOR	10/11/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/12/2017	Cut Brush/ Brush Cutter
CR 4715 ALLIGATOR	10/12/2017	Cut Brush/ Brush Cutter
CR 4319 FED'S {Minor Collector}	10/13/2017	Cut Brush/ Brush Cutter
CR 4715 ALLIGATOR	10/13/2017	Cut Brush/ Brush Cutter
CR 4613 OLD 19 (35 MPH)	10/16/2017	Cut Brush/ Brush Cutter
CR 4613 OLD 19 (35 MPH)	10/17/2017	Cut Brush/ Brush Cutter
CR 4613 OLD 19 (35 MPH)	10/18/2017	Cut Brush/ Brush Cutter
CR 4613 OLD 19 (35 MPH)	10/19/2017	Cut Brush/ Brush Cutter
CR 4613 OLD 19 (35 MPH)	10/20/2017	Cut Brush/ Brush Cutter
	10/20/2017	Cut Brush/ Brush Cutter
CR 4811 PEEWEE	10/20/2017	Cut Brush/ Brush Cutter
CR 4613 OLD 19 (35 MPH)	10/23/2017	Cut Brush/ Brush Cutter
CR 4811 PEEWEE	10/24/2017	Cut Brush/ Brush Cutter
CR 4616 GIN	10/25/2017	Cut Brush/ Brush Cutter
CR 4811 PEEWEE	10/25/2017	Cut Brush/ Brush Cutter
CR 4612 MAYS CAFÉ	10/27/2017	Cut Brush/ Brush Cutter
CR 4520E RAINBOW-E (Rainbo Gate to 4402	11/6/2017	Cut Brush/ Brush Cutter
CR 4520E RAINBOW-E (Rainbo Gate to 4402	11/7/2017	Cut Brush/ Brush Cutter
CR 4716 Tiger	11/7/2017	Cut Brush/ Brush Cutter
CR 4716 Tiger	11/8/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/9/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/13/2017	Cut Brush/ Brush Cutter

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Right-of-way: Cut Brush/ Brush Cutter (53)

Location	Date	Work Done
CR 4400 ROCKHILL (35 MPH)	11/14/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	11/15/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/17/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/20/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/21/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/22/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/22/2017	Cut Brush/ Brush Cutter
CR 4336 MYRTLE SPRINGS (45 MPH)	11/27/2017	Cut Brush/ Brush Cutter
CR 4231 BETHEL CEMETARY	12/4/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/4/2017	Cut Brush/ Brush Cutter
CR 4231 BETHEL CEMETARY	12/5/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/5/2017	Cut Brush/ Brush Cutter
CR 4231 BETHEL CEMETARY	12/6/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/6/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/14/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/15/2017	Cut Brush/ Brush Cutter
CR 4330 DINGLER	12/18/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/18/2017	Cut Brush/ Brush Cutter
CR 4330 DINGLER	12/19/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/19/2017	Cut Brush/ Brush Cutter
CR 4330 DINGLER	12/20/2017	Cut Brush/ Brush Cutter
CR 4400 ROCKHILL (35 MPH)	12/20/2017	Cut Brush/ Brush Cutter

Right-of-way: Remove Dead Tree (5)

Location	Date	Work Done
CR 4217 MANOY (Pleasant Ridge)	10/16/2017	Remove Dead Tree

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Right-of-way: Remove Dead Tree (5)

Location	Date	Work Done
CR 4516 HAIRGROVE	11/27/2017	Remove Dead Tree
CR 4343 JOE YOUNG	11/29/2017	Remove Dead Tree
CR 4348 SHOLAR'S	11/29/2017	Remove Dead Tree
CR 4528 COUNTY LINE (35 MPH)	12/20/2017	Remove Dead Tree

Right-of-way: Cleared debris or fallen tree (2)

Location	Date	Work Done
CR 41107 MILL RUN RD (35 MPH)	10/11/2017	Cleared debris or fallen tree
CR 4516 HAIRGROVE	11/27/2017	Cleared debris or fallen tree

Right-of-way: Chip Brush w/ Wood Chipper (1)

Location	Date	Work Done
CR 41126 LABELLO	12/29/2017	Chip Brush w/ Wood Chipper

Right-of-way: Other right-of-way work (1)

Location	Date	Work Done
Clevis Meadows	10/27/2017	Other right-of-way work

Signs: Put up County road number sign (1)

Location	Date	Work Done
CR 4234	10/4/2017	Put up County road number sign

Signs: Put up County Road Number sign 'NS' (1)

Location	Date	Work Done
2 Multi Locations	11/20/2017	Put up County Road Number sign 'NS'

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Signs: Put up 'Stop' sign (1)

Location	Date	Work Done
CR 4234	10/4/2017	Put up 'Stop' sign

Signs: Put up 'Dead End' sign (1)

Location	Date	Work Done
CR 4234	10/4/2017	Put up 'Dead End' sign

Signs: Other sign work (1)

Location	Date	Work Done
Pct 4 barn	10/4/2017	Build Road Number Signs

Other work: Trash/garbage picked-up (2)

Location	Date	Work Done
CR 4700 WARD (35 MPH) {Minor Collector}	10/6/2017	Trash/garbage picked-up
CR 4800 BAXTER RD (45 MPH) {Minor Collector*}	10/6/2017	Trash/garbage picked-up

Other work: Equipment maintenance/service (24)

Location	Date	Work Done
Pct 4 barn	10/3/2017	Equipment maintenance/service
Pct 4 barn	10/11/2017	Equipment maintenance/service
Pct 4 barn	10/17/2017	Equipment maintenance/service
Pct 4 barn	10/18/2017	Equipment maintenance/service
	10/18/2017	Equipment maintenance/service
Pct 4 barn	10/19/2017	Equipment maintenance/service
Pct 4 barn	10/20/2017	Equipment maintenance/service
Pct 4 barn	10/23/2017	Equipment maintenance/service
Pct 4 barn	10/24/2017	Equipment maintenance/service

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Other work: Equipment maintenance/service (24)

Location	Date	Work Done
Pct 4 barn	10/25/2017	Equipment maintenance/service
Pct 4 barn	11/6/2017	Equipment maintenance/service
Pct 4 barn	11/7/2017	Equipment maintenance/service
Pct 4 barn	11/8/2017	Equipment maintenance/service
Pct 4 barn	11/13/2017	Equipment maintenance/service
	11/13/2017	Equipment maintenance/service Check Antifreeze
Pct 4 barn	11/17/2017	Equipment maintenance/service
Pct 4 barn	11/21/2017	Equipment maintenance/service
Pct 4 barn	11/27/2017	Equipment maintenance/service
Pct 4 barn	12/14/2017	Equipment maintenance/service
Pct 4 barn	12/18/2017	Equipment maintenance/service
Pct 4 barn	12/19/2017	Equipment maintenance/service
Pct 4 barn	12/20/2017	Equipment maintenance/service
Pct 4 barn	12/26/2017	Equipment maintenance/service
Pct 4 barn	12/27/2017	Equipment maintenance/service

Other work: Moved equipment to work site (4)

Location	Date	Work Done
155 Forest Hill Dr (Brierwood Bay)	10/3/2017	Moved equipment to work site
CR 4403 SISSY'S	11/1/2017	Moved equipment to work site
Pct 4 barn	11/3/2017	Moved equipment to work site
Fair Park	11/13/2017	Moved equipment to work site

Other work: Picked-up materials from vendor (2)

Location	Date	Work Done
Pct 4 barn	10/16/2017	Picked-up materials from vendor

Daily Work History (by Type of Work)

Period: 10/1/2017 - 12/31/2017

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Henderson County

Other work: Picked-up materials from vendor (2)

Location	Date	Work Done
Pct 4 barn	12/29/2017	Picked-up materials from vendor Load of ESC unloaded @ TxDOT Stock Pile

Other work: Delivered dirt or sand (1)

Location	Date	Work Done
bethel cemetary	10/6/2017	Delivered dirt or sand

Other work: Worked at barn/office (4)

Location	Date	Work Done
Pct 4 barn	10/16/2017	Worked at barn/office
Pct 4 barn	10/16/2017	Worked at barn/office
Pct 4 barn	10/20/2017	Worked at barn/office
Pct 4 barn	11/21/2017	Worked at barn/office

Other work: Storm preparation (East End) (1)

Location	Date	Work Done
2 Multi Locations	12/19/2017	Storm preparation (East End)

Other work: Other work (5)

Location	Date	Work Done
DPS Office	10/3/2017	DOT Testing
TDPS	10/20/2017	CDL Testing
Pct 4 barn	10/27/2017	Load Tire Trailer
DPS Canton	12/20/2017	/CDL Test
Canton DPS	12/28/2017	CDL Test